Transportation AMERICAN Library

RAILROAD JOURNAL

R. M. VAN ARSDALE, Proprietor. J. S. BONSALL, Business Manager.

Editors R. V. WRIGHT
E. A. AVERILL

Published Monthly at 140 Nassau Street, New York.

INDEX TO VOLUME LXXXIII—1909

indicates illustrated article. § indicates editorial comment.

	Setting Valves with Wal	
Valve Gear	****************	128*
Apprentice	Instructors' Confe	rence,

New York Central Lines.

Blacksmith Apprentices, Difficulty in Obtaining 443
Boiler-Maker Apprentices, Difficulty in Obtaining 443
Boiler-Maker Apprentices, Drawing Course for 440
Bronner, E. D., On Apprenticeship. 386
Brazier, F. W., On Apprenticeship. 385
Car Shop, Apprentice Drawing Course for 389
Car Shop Apprentice, Freight. 389
Car Shop Apprentices, Should There Be a Separate Shop Instructor for. 443
Classroom, Discipline in 439
Classroom Instructor, The Assistant. 443
Classroom Work, Penaltics for Not Doing 438 Assn. 145
American Railway Association, Officers of ... 252†
American Soc. of Mech. Engrs., Annual Meeting ... 501†
American Soc. of Mech. Engrs., November Meeting ... 453†
American Soc. of Mech. Engrs., October Meeting ... 422
American Soc. of Mech. Engrs., Spring Meeting ... 500 Mech. Engrs., Spring Meeting ... 191
American Soc. of Mech. Engrs., Spring Meeting ... 191
American Specialty Co. "Use-Em-Up" Drill Socket ... 76*
American Steam Cause and Meeting ... 76*

Instructor, Shop, for Car Shop Apprentices 443
Labor Unions 387
Laboratory Work 439
Letter Writing, Teaching of 439
Lettering Course for Painter Apprentices 443
Loyalty to the Company 387
McCarthy, M. J., Address of Welcome 385
Mathematics, Higher, How Much Instruction Should be Given in 443
Observation Trips for Instructors 443
Painter Apprentices, Course in Lettering for 443

20	indicates	communication.		
.1.	Indiantes.	a short non illustrated article	-	note

Penalties for Failure to Do Home Class Work Piece Work Promotions to Responsible Positions	
	or
Class Work	. 438
Piece Work	. 387
Promotions to Responsible Positions.	. 388
Rate, Should Shop Instructor Notify the Foreman of the Boy's Next Advan-	16
in the boy's Next Advan-	. 442
Results for the Vear	. 387
School Room, Beech Grove Shops	. 388
in Results for the Year School Room, Beech Grove Shops Shea, R. T., On Apprenticeship	. 386
Shifting Apprentices	. 442
Shop Course for Spring-Maker Appre	n-
Chan Instructor for Car Chan Appro	. 442
tices	. 448
Shea, R. T., On Apprenticeship. Shifting Apprentices Shop Course for Spring-Maker Appretices Shop Instructor for Car Shop Appretices Shop Instructor, Duties of. Shop Instructor, Results from. Shop Practice, Classroom Instruction Shop Work Done by Apprentices, Impetant	. 442
Shop Instructor, Results from	. 387
Shop Practice, Classroom Instruction	in 443
Shop Work Done by Apprentices, Impo	I-
Shop Work Done by Apprentices, Impotant Spelling, Teaching of Spring-Maker Apprentice, Shop Cour for Square Root, Should it be Taught Statistics for the Year. Stimulating Home Work. Stools, Use of in Drawing Room Strength of Materials, Testing Machin for Studying	. 388
Spelling, Teaching of Shop Cour	. 200
for	. 442
Square Root, Should it be Taught	. 443
Statistics for the Year	. 387
Stimulating Home Work	389
Stools, Use of in Drawing Room	. 443
Strength of Materials, Testing Machin	16
Tasting Machine for Studying the	
Strength of Materials Turner, L. H., On Apprenticeship Walschaert Valve Gear, Class Room I	. 441
Turner, L. H., On Apprenticeship	. 386
Walschaert Valve Gear, Class Room I	n-
struction	. 440
	100
Apprentice, The Kallroad Snop	138
Apprentices, Discipline	. 133
Apprentice, The Railroad Shop	. 138
Apprentices, Sketching for	405
Apprenticeship Extension of	387
Apprenticeship, Extension of	139
Arch Rare for 50-Ton Care	. 200
Arcs Equal to Straight Lines	. 336
The state of the s	. 336
Articulated Compound Locomotives (see Ma	. 336
Articulated Compound Locomotives (see Management Articulated Connection, 2-8-8-2 Loco., So.	. 336 . 11 illet).
Articulated Compound Locomotives (see Management Articulated Connection, 2-8-8-2 Loco., So. Pac. Co.	. 336 . 11 allet).
Articulated Compound Locomotives (see M. Articulated Connection, 2-8-8-2 Loco., So. Pac. Co	. 336 . 11 allet). . 367
Articulated Compound Locomotives (see Management Articulated Connection, 2-8-8-2 Loco., So. Pac. Co	. 336 . 11 allet). . 367
Articulated Compound Locomotives (see M. Articulated Connection, 2-8-8-2 Loco., So. Pac. Co	. 336 . 11 allet). . 367 . 301 †, 403
Apprentices, Sketching for Apprenticeship. Apprenticeship, Extension of Apprenticeship, Home Study Arch Bars for 50-Ton Cars. Arcs Equal to Straight Lines. Articulated Compound Locomotives (see Marticulated Connection, 2-8-8-2 Loco., So. Pac. Co. Asbestos Protected Metal. Ash, Basing Fuel Contracts on Amount of, 189, 347	. 336 . 11 allet). . 367 . 301 †, 403
Articulated Compound Locomotives (see M. Articulated Connection, 2-8-8-2 Loco., So. Pac. Co	367 . 367 . 301 †, 403
Articulated Compound Locomotives (see M. Articulated Connection, 2-8-8-2 Loco., So. Pac. Co	367 367 301 †, 403
Articulated Compound Locomotives (see M: Articulated Connection, 2-8-8-2 Loco., So. Pac. Co. Asbestos Protected Metal. Ash, Basing Fuel Contracts on Amount of, 189, 347 Ash Pan. Editorial Comment Hopper Type, Hinged Doors. Hopper Type, Sliding Doors.	, 336 , 11 allet). , 367 , 301 †, 403
Articulated Compound Locomotives (see M: Articulated Connection, 2-8-8-2 Loco., So. Pac. Co. Asbestos Protected Metal. Ash, Basing Fuel Contracts on Amount of, 189, 347 Ash Pan. Editorial Comment Hopper Type, Hinged Doors. Hopper Type, Sliding Doors. Hopper Type, Special Arrangements.	*** 336 **** 11 ***** 367 **** 301 **** 403 **** 240 **** 242 **** 242
Articulated Compound Locomotives (see M: Articulated Connection, 2-8-8-2 Loco., So. Pac. Co. Asbestos Protected Metal. Ash, Basing Fuel Contracts on Amount of, 189, 347 Ash Pan. Editorial Comment Hopper Type, Hinged Doors. Hopper Type, Sliding Doors. Hopper Type, Special Arrangements. Hopper Type, Swinging Doors.	*** 386 **** 11 ***** 367 **** 301 **** 403 **** 244 **** 242 **** 245 **** 244
Articulated Compound Locomotives (see M. Articulated Connection, 2-8-8-2 Loco., So. Pac. Co	*** 386 **** 11 ***** 367 **** 301 **** 403 **** 244 **** 242 **** 244 **** 242 **** 244
Articulated Compound Locomotives (see M: Articulated Connection, 2-8-8-2 Loco., So. Pac. Co. Asbestos Protected Metal. Ash, Basing Fuel Contracts on Amount of, 189, 347 Ash Pan. Editorial Comment Hopper Type, Hinged Doors. Hopper Type, Siding Doors. Hopper Type, Special Arrangements. Hopper Type, Special Arrangements. Hopper Type, Swinging Doors. Lancashire & Yorkshire Ry. Lignite Burning Locomotives39	7, 403 11, 403 1, 40
Articulated Compound Locomotives (see M: Articulated Connection, 2-8-8-2 Loco., So. Pac. Co. Asbestos Protected Metal. Ash, Basing Fuel Contracts on Amount of, 189, 347 Ash Pan. Editorial Comment Hopper Type, Hinged Doors. Hopper Type, Sliding Doors. Hopper Type, Swinging Doors. Lancashire & Yorkshire Ry. Lignite Burning Locomotives. Self Clearing C. P. Ry	**************************************
Articulated Compound Locomotives (see M: Articulated Connection, 2-8-8-2 Loco., So. Pac. Co	**************************************
Articulated Compound Locomotives (see M: Articulated Connection, 2-8-8-2 Loco., So. Pac. Co. Asbestos Protected Metal Ash, Basing Fuel Contracts on Amount of, 189, 347 Ash Pan. Editorial Comment	**************************************
Articulated Compound Locomotives (see M: Articulated Connection, 2-8-8-2 Loco., So. Pac. Co. Asbestos Protected Metal. Ash, Basing Fuel Contracts on Amount of, 189, 347 Ash Pan. Editorial Comment	*** 336*** 301*** 403*** 244*** 245**
Articulated Compound Locomotives (see M: Articulated Connection, 2-8-8-2 Loco., So. Pac. Co. Asbestos Protected Metal Ash, Basing Fuel Contracts on Amount of, 189, 347 Ash Pan. Editorial Comment Hopper Type, Hinged Doors. Hopper Type, Sliding Doors. Hopper Type, Special Arrangements. Hopper Type, Swinging Doors. Lancashire & Yorkshire Ry. Lignite Burning Locomotives. 39 Self Clearing, C. P. Ry. Shallow, Blower Discharge. Shallow, Side Opening. Shallow, Special Arrangements for Dumping.	*** 386*** 301*** 403*** 240*** 242*** 245*** 242**
Articulated Compound Locomotives (see M: Articulated Connection, 2-8-8-2 Loco., So. Pac. Co. Asbestos Protected Metal Ash, Basing Fuel Contracts on Amount of, 189, 347 Ash Pan. Editorial Comment Hopper Type, Hinged Doors. Hopper Type, Silding Doors. Hopper Type, Special Arrangements. Hopper Type, Swinging Doors. Lancashire & Yorkshire Ry. Lignite Burning Locomotives. 39 Self Clearing Self-Clearing, C. P. Ry. Shallow, Blower Discharge. Shallow, Side Opening. Shallow, Special Arrangements for Dumping Shallow, With Sliding Doors.	*** 336** *** 11allet) 367** *** 301** *** 403** *** 240** *** 242** *** 242** *** 244** *** 244** *** 244** *** 244** *** 244** *** 244** *** 244** *** 244** *** 244** *** 244** *** 246** ** 246** ***
Editorial Comment Hopper Type, Hinged Doors Hopper Type, Sliding Doors Hopper Type, Special Arrangements. Hopper Type, Swinging Doors. Lancashire & Yorkshire Ry. Lignite Burning Locomotives. 39 Self Clearing. P. Ry. Shallow, Blower Discharge. Shallow, Side Opening. Shallow, Side Opening. Shallow, Special Arrangements for Dumping. Shallow, With Sliding Doors.	240 244 242 245 245 246 409 0, 394 246 246
Editorial Comment Hopper Type, Hinged Doors Hopper Type, Sliding Doors Hopper Type, Special Arrangements. Hopper Type, Swinging Doors. Lancashire & Yorkshire Ry. Lignite Burning Locomotives. Self Clearing Self-Clearing, C. P. Ry. Shallow, Blower Discharge. Shallow, Blower Discharge. Shallow, Side Opening. Shallow, Special Arrangements for Dumping. Shallow, With Sliding Doors. Atchison, Topeka & Santa Fe Ry., (see San Fe).	240 . 244 . 242 . 245 . 245 . 409 0, 392 . 242 . 246 . 246
Editorial Comment Hopper Type, Hinged Doors. Hopper Type, Sliding Doors. Hopper Type, Special Arrangements. Hopper Type, Special Arrangements. Hopper Type, Swinging Doors. Lancashire & Yorkshire Ry. Lignite Burning Locomotives. Self Clearing Self-Clearing, C. P. Ry. Shallow, Blower Discharge. Shallow, Blower Discharge. Shallow, Side Opening. Shallow, Special Arrangements for Dumping Shallow, With Sliding Doors. Atchison, Topeka & Santa Fe Ry., (see San Fe).	240 . 244 . 242 . 245 . 844 . 409 0, 392 . 242 . 427 . 246 . 246
Editorial Comment Hopper Type, Hinged Doors. Hopper Type, Sliding Doors. Hopper Type, Special Arrangements. Hopper Type, Special Arrangements. Hopper Type, Swinging Doors. Lancashire & Yorkshire Ry. Lignite Burning Locomotives. Self Clearing Self-Clearing, C. P. Ry. Shallow, Blower Discharge. Shallow, Blower Discharge. Shallow, Side Opening. Shallow, Special Arrangements for Dumping Shallow, With Sliding Doors. Atchison, Topeka & Santa Fe Ry., (see San Fe).	240 . 244 . 242 . 245 . 844 . 409 0, 392 . 242 . 427 . 246 . 246
Editorial Comment Hopper Type, Hinged Doors. Hopper Type, Sliding Doors. Hopper Type, Special Arrangements. Hopper Type, Special Arrangements. Hopper Type, Swinging Doors. Lancashire & Yorkshire Ry. Lignite Burning Locomotives. Self Clearing Self-Clearing, C. P. Ry. Shallow, Blower Discharge. Shallow, Blower Discharge. Shallow, Side Opening. Shallow, Special Arrangements for Dumping Shallow, With Sliding Doors. Atchison, Topeka & Santa Fe Ry., (see San Fe).	240 . 244 . 242 . 245 . 844 . 409 0, 392 . 242 . 427 . 246 . 246
Editorial Comment Hopper Type, Hinged Doors. Hopper Type, Sliding Doors. Hopper Type, Special Arrangements. Hopper Type, Special Arrangements. Hopper Type, Swinging Doors. Lancashire & Yorkshire Ry. Lignite Burning Locomotives. Self Clearing Self-Clearing, C. P. Ry. Shallow, Blower Discharge. Shallow, Blower Discharge. Shallow, Side Opening. Shallow, Special Arrangements for Dumping Shallow, With Sliding Doors. Atchison, Topeka & Santa Fe Ry., (see San Fe).	240 . 244 . 242 . 245 . 844 . 409 0, 392 . 242 . 427 . 246 . 246
Editorial Comment Hopper Type, Hinged Doors. Hopper Type, Sliding Doors. Hopper Type, Special Arrangements. Hopper Type, Special Arrangements. Hopper Type, Swinging Doors. Lancashire & Yorkshire Ry. Lignite Burning Locomotives. Self Clearing Self-Clearing, C. P. Ry. Shallow, Blower Discharge. Shallow, Blower Discharge. Shallow, Side Opening. Shallow, Special Arrangements for Dumping Shallow, With Sliding Doors. Atchison, Topeka & Santa Fe Ry., (see San Fe).	240 . 244 . 242 . 245 . 844 . 409 0, 392 . 242 . 427 . 246 . 246
Editorial Comment Hopper Type, Hinged Doors. Hopper Type, Sliding Doors. Hopper Type, Special Arrangements. Hopper Type, Special Arrangements. Hopper Type, Swinging Doors. Lancashire & Yorkshire Ry. Lignite Burning Locomotives. Self Clearing Self-Clearing, C. P. Ry. Shallow, Blower Discharge. Shallow, Blower Discharge. Shallow, Side Opening. Shallow, Special Arrangements for Dumping Shallow, With Sliding Doors. Atchison, Topeka & Santa Fe Ry., (see San Fe).	240 . 244 . 242 . 245 . 844 . 409 0, 392 . 242 . 427 . 246 . 246
Editorial Comment Hopper Type, Hinged Doors. Hopper Type, Sliding Doors. Hopper Type, Special Arrangements. Hopper Type, Special Arrangements. Hopper Type, Swinging Doors. Lancashire & Yorkshire Ry. Lignite Burning Locomotives. Self Clearing Self-Clearing, C. P. Ry. Shallow, Blower Discharge. Shallow, Blower Discharge. Shallow, Side Opening. Shallow, Special Arrangements for Dumping Shallow, With Sliding Doors. Atchison, Topeka & Santa Fe Ry., (see San Fe).	240 . 244 . 242 . 245 . 844 . 409 0, 392 . 242 . 427 . 246 . 246
Editorial Comment Hopper Type, Hinged Doors Hopper Type, Sliding Doors Hopper Type, Special Arrangements. Hopper Type, Swinging Doors. Lancashire & Yorkshire Ry. Lignite Burning Locomotives. Self Clearing Self-Clearing, C. P. Ry. Shallow, Blower Discharge. Shallow, Blower Discharge. Shallow, Side Opening. Shallow, Special Arrangements for Dumping. Shallow, With Sliding Doors. Atchison, Topeka & Santa Fe Ry., (see San Fe).	240 . 244 . 242 . 245 . 844 . 409 0, 392 . 242 . 427 . 246 . 246

Atlantic Type Loco., Three-Cyl. Simple, Fast Run on the P. & R	Repairs Reduced		Brake Chain	297* 336
Atlantic Type Loco., Vauclain Comp., C., M. & St. P. Ry	Stays Above Crown Sheet to Clear Lon-	150%	Brake Hanger Guides, Wing Dies for Forming	
Automobiles and Road Maintenance 410 Axle Journals, Grinding	Tapping Holes in	433*	Brake Rod Jaws, Forging at the Collinwood Shops	482*
Axles (see Crank Axles).	Tube Joints, The Slipping Point of, 364\$, Washing Hose and Tools, Truck for	370*	Shops Brake Shaft Brake Shaft Brackets, Former for Bending.	210*
Axles, Locomotive, Boring	Water Changing and Washing the	353	Brake Shoes, Tests of	124
В	Equipment, Miller	5 23§	Brake Wheel	297*
Babbitting Crosshead Gibs	water lube vs. Standard	253"	Brakes, Fower on Trains	125
Babbitting Crosshead Shoes	Bolt Cutter With Turret Head	8*	Brasses (see Rod Brasses). Brasses, Car Journal, Machine for Boring	410*
Baker Bros., High Duty Drill	Bolt Fasteners, Bartley299† Bolt for Drawing Up and Fitting Bonus Schedule for Firemen	91	Brazier, F. W., On Apprenticeship Brick Arch	385 322
Baker-Pilliod Valve Gear, 4-6-2 Loco., Chicago & Alton Ry. 26	Bonus System, Results of	237*	Brick Arch and Smoke	392
Balanced Compound 4-4-2 Loco., Santa Fe47: Balanced Compound 4-6-2 Loco., Western	Books.		Brick Arch, Lancashire & Yorkshire Ry Brill Truck for Electric Cars	409 499*
Ry. of France	Air Brake Instruction Book, Westing house E.T	303	Briquets.	
C. & St. L. Ry	to Interstate Commerce Commission.	179	Advantages of	
I. & P. Ry	tribution of Expense Burden	43	Disadvantages of	314 383†
Baltimore & Ohio Ry., Cast Iron Ash Pan	Earth Slopes, Retaining Walls and Dams Chas. Prelini	43	Handling, Effect ofOn European Railroads	347
Slide and Frame with Heating Passages 24 Barney & Smith Car Co., Buffet Library	Wages, Harrington Emerson	423	Smoke from	68
Car	on by Chac P Steinmets	. 119	Test of	69
Barrels, Device for Elevating		423	Bronner, E. D., On Apprenticeship Brown & Sharpe Heavy Plain Milling Ma-	386
Basford, G. M., On Apprenticeship 38: Basford, G. M., The Railway Business Association, An Inside View	Engineering Index, Annual for 1908 Estimates, Tables of Quantities for Pre- liminary, E. F. Haugh & R. D. Rice.		chine	214*
Baulch, J. J., Are Railroad Clubs Worth While?	Expense Burden, The Proper Distribution	43	Buck Superheater, Santa Fe Mallet Comp. Locos.	
Bearings, Car Journal, Machine for Boring. 410 Bedee Knives for Woodworking 360	Fowle, Frank F., Protection of Rail-		Buckley, John, Good Mixture for Case Hard-	10
Beech Grove Shops, Big 4, General Arrangement of	Going, Chas. B., Methods of the Santa	422	Buffalo Heating Co., Roundhouse Heating System	5*
Belts.	Fe—Efficiency in the Manufacture of Transportation	501	Buffalo, Rochester & Pittsburgh Ry., Ash Pan with Patented Radial Doors	245*
Abuse of	in Locomotive Service	119	Buffet Library Car, C. M. & St. P. Ry Building Construction, Use of Wood in Bullard Vertical Turret Lathe, Work Done	2
Dressing for	Preliminary Estimates	79	by Bumper Beam, 2-8-0 Loco., C. P. Ry	260° 430°
Fasteners for 41 Friction, Explosion from 27:	Ketchum	43	Burner Using Hydro-Carbon as Fuel	457
Good Grade, How to Secure	Wimperis	119	Burns, Geo. J., Machining Driving Boxes Burns, Geo. J., Machining Shoes and Wedges Burns, Geo. J., Observations on Babbitting	134*
Lacing Textile	Bridges Lighting Engineers' Hand-Book, by L	43	and Brasses Burns, Geo. J., Railroad Machine Shop Practice	219
Leather, Proper Care of	R. Pomeroy Locomotive. The Railway, by Vaughar	463	Bushings, Hydraulic Press for Valve Cham-	
Short Centers	Pendred Locomotive Service, High Steam Pres	178	Business Failures This Year	483* 323†
Textile, Lacing of	Master Blacksmiths' Assn., Internation	119	Business Notes, 44, 80, 120, 180, 216, 264, 303, 344, 384,	500
Welding and Cutting Machine	Master Car Builders' Assn., Proceedings	79 5 79	Business Outlook Improving	151\$
Bentel & Margedant Heavy Automatic Cut- Off Saw	Master Mechanics' Assn., Proceedings of Morrison, Egbert R., Spring Tables Patents as a Factor in Manufacturing	. 78	P. Ry. By-Pass Valves, Are They Necessary With	429*
izontal Car Boring Machine	Edwin J. Prindle Pendred, Vaughan, The Railway Loco	43		322
Bentel & Margedant Co., Vertical Car Bor- ing Machines 167*, 21	motive P. Lighting Engineers	, 178	c	
Bentel & Margedant Universal Woodworker 34 Bentley, H. T., Are By-Pass Valves Neces- sary With Piston Valves	Poor's Manual for 1909	463	Caboose, Virginian Ry	409*
Berlin, American Exposition in	walls ally Dams	43	Cabooses, Telephones on	453
Black Mechanical Stoker	Prindle, Edwin J., Patents as a Factor in Manufacturing	43	Canadian Pacific Ry. Consolidation Loco.	495*
Ry	Transmission Line Crossings, Frank F.		Canadian Pacific Ry., Equipment of Canadian Pacific Ry. Safety League	138†
Blowers, Effect of on Smoke	Poilsond Construction Theory and Days		Canadian Railway Club, 25, 65, 113, 152, 209, 237, 422, 462,	
Boiler.	Rice, R. D., Tables of Quantities for Preliminary Estimates	r	Car.	
2-8-0 Loco., C. P. Ry	Santa Fe, Methods of, Efficiency in the Manufacture of Transportation, by	è V	Blown from Track	21†
Ry 25	Chas. B. Going	. 501 . 78	Box, Device for Loading Coal in Box, Doors for	72*
2-8-2 Loco., Chicago, Milwaukee & Puget Sound Ry	Electrical Engineering	. 119	Coke, Four Hopper, Steel, P. R. R. Door, Box Car	187* 296
2-8-8-2 Loco., So. Pac. Co	Webb, Walter Loring, Railroad Con	-	Freight (see Freight Car). Freight, Steel (see Steel Freight Car).	
4-6-9 Loco., Gt. Nor. Ry	Westinghouse E-T Air Brake Instruction	. 43	Glass, for Carrying Plate	9504
Barrel, Long	Pocket Book	. 303	Gondola, Steel, 50-Ton, Maine Central Ry.	
Circulation in Water Leg20, 2 Clean, Necessity of Keeping	Wood, W. W., Westinghouse E-T Ai	. 119	Gondola, Steel, 50-Ton, Norfolk & West- ern Ry.	
Cleaning Out. Methods of	Brake Instruction Pocket Book	. 303	Gondola, Steel, 50-Ton, Nor. Pac. Ry	251*
Pac. Ry. 19 Crown Bolts in 32 European Design, Tendency of 37	zontal	. 378*	Gondola, Steel, 50-Ton, Virginian Ry Hopper, for Coke, P. R. R Hopper, for Ore, Summers	338
Firebox (see Firebox). Inspection Bill. Federal	Boring Locomotive Axles Boring Machine, Single Spindle Horizontal		Hopper, for Ore, Summers	369°
ment on	(Wood) Boring Machines, Vertical, Car167* Boring Mill, Vertical	, 213*	Lighting Engineers', Assn. of	151
Ry40	Boring Square Holes	. 38*	Motor (see Motor Car). Number Built in 1908 Passenger (see Passenger Car).	47
Mallet Compound Locomotive, Santa Fe. 47	Boston Electrification of Steam Railways in	n 178	Passenger (see Passenger Car). Passenger, Steel (see Steel Passenger Ca Refrigerator (see Refrigerator Car).	ir).
Performance, Saturated and Superheated Steam	Box Cars, Device for Loading Coal in Boxes (see Driving Boxes).	. 72*	Repair Department, Organization of	86
Pressure and Superheated Steam, Relation of	Brake Beam Safety Hangers, Dies for Reng		Repair Yards, Altoona83*, 92*, Repairs (see Steel Freight Cars, Maintenance and Repair of at Altoona).	

Shops (see Shop, Car). Steel, Freight (see Steel Freight Cars). Steel, Passenger (see Steel Passenger		Collinwood Shops, Flue Plant	131*	Delaware, Lackawanna & Western Railroad, Machine Tools for the Locomotive Machine and Boiler Shops at Scranton121,	
Cars). Summers Steel Hopper49*, 338*, Tank	369*	Collinwood Shops, Machine for Boring Car		Delays to Trains, New York State Denatured Alcohol from Natural Gas	39*
Wheels (see Wheels). Window Cleaning Device		Journal Bearings	13†	Denver, Northwestern & Pacific Ry., Mallet Loco. Denver & Rio Grande 50-Ton Steel Gondola	61*
Window Fixtures	114*	Ry	195*	CarDepreciation of Power Plants	
Carpenter, Geo. M., On Testing Loco. Fuel.	397	Locos	475	Derailments, Causes of	203
Carrigan, J. E., Welding Locomotive Frames Case Hardening, Good Mixture for	453* 10	Combustion, Smokeless	205†	pirical Formula for	3128
Cast Iron Pipe Fittings, Effect of Superheat- ed Steam on	177†	Compound Loco. (see Mallet Comp. Locos.) Compound Loco., Vauclain, 4-4-2, C. M. & St.		Diamond Stack for Burning Lignite Direct Current, Pennsylvania Electrification	391*
Castings, To Find the Weight of	320*	P. Ry	115* 170	Dispatch Tube, Pneumatic for Roundhouse Dixon Crucible Co. Belt Dressing	72
Castle Nuts, Dies and Former for Forging. Catalogs,	130*	Compression Testing Machine, 10,000,000 lb. Compressors (see Air Compressors).	102	Dodge Mechanical Stoker Door, Box Car	280
44, 80, 120, 180, 216, 263, 303, 344, 383, 424, 464,	503	Condensation, Cylinder	379†	Door, Drop, Air Operated for Summers Car. Door, Drop, Steel Coke Car	369*
Center Plates	337	Conservation of Natural Resources Consolidation Loco., Chicago & Alton Ry	269*	Door, Grain, Metal	296
Centering Device, 2-8-8-2 Loco., So. Pac. Co.	368*	Consolidation Locos, Tabular Comparison Consolidation Loco, With Fire Tube Super-	274.	Door Knobs for Baggage Cars, Dies and Former for Forging	
Central of Georgia Ry., Hopper Type Ash Pan Central of Georgia Ry., Tests of Locos. With	243*	Consolidation Loco. With Superheater, C. P.	256*	Door for Roundhouse, Folding Doten, Prof. C., Causes of Derailments	203
Superheater and Feed Water Heater Central Railroad of New Jersey, Cast Iron	241	Continuation Schools Cincinnati 4048	425"	Draft Gear, Friction	1
Ash Pan	243*	Cooper-Hewitt Lamps, Lighting Railroad Shops With	298*	Draft in Steam Boiler Practice Drafting Engines Properly	315
frame Coaches	488*	Co-operation, How Taught to Apprentices Co-operative Education, Lewis Institute Co-operative Engineering Courses, University	58	Drafting Room, Data of Interest to11*, Drafting Room, Erasing Device for	59 259*
25, 65, 113, 152, 209, 237, 372, 422, Chain, Brake Chain Grates	462 297*	of Cincinnati	497†	Drawbar Between Engine and Tender, Virginian Mallet Loco	359*
Chambersburg 1500-Ton Press	91*	Copper Safe-Ends for Flues	181	Drill.	
"Change-in-Progress Cards"	427"	Cost of High Speed	86	Angular for Square Holes	38*
Chesapeake & Ohio Ry., Cast Steel Ash Pan Slide and Frame	243*	Costs, Importance of Knowing Promptly Costs of Operation of Repair Shop	2†	High Duty, Baker Bros	207*
Chesapeake & Ohio R. R., Road Tests of Briquets	69	Costs and Performances, Keeping Officials Posted		High Speed	347†
Chicago & Alton, Consolidation Loco Chicago & Alton Ry., Pacific Type Loco	268*	Costs, Standard	217	Multiple Spindle in Railroad Shop	160*
Chicago, Burlington & Quincy, Consolidation Loco. With Wood's Fire Box and Tube	979*	from Counterbalancing398*,	45"	Radial, Mueller Radial, Sensitive 210*, Sensitive, Radial 210*,	458* 458*
Plates Chicago, Burlington & Quincy Pacific Type Loco.	376*	Coupler. Face Tests	990*	Shank, Stronger	178* 78*
Chicago, Milwaukee & Puget Sound Ry., Mi-		Gauges for Attachment to Yoke	331*	Shank, Stronger Socket, "Economy" Socket, "Use-Em-Up" Twist, "Highpower" Twist, High Speed. 238,	419*
kado Type Loco. Chicago, Milwaukee & St. Paul Ry., 4-4-2 Comp. Loco.	115	Mating of	331	I wist, I al agoli	343
Chicago, Milwaukee & St. Paul Ry., Ash Pan With Swinging Doors	245*	Side Clearance Tests	332* 211*	Drilling Apparatus, Portable Drilling, Boring and Milling Machine, Hori-	
Chicago, Milwaukee & St. Paul Ry., Buffet Library Cars	447*	Yoke Filler, Forging	229* 91	Drilling, Diagram for Finding Information. Drilling, High Speed, Data on	496"
Chicago, Rock Island & Pacific Ry. (see Rock Island).	554	Coupling, Air Brake Hose	11*	Drilling Machine, 3-Spindle, Horizontal Drilling Machines Required in Loco. Boiler	497"
Chisel Bar, Engineer's	970*	Crane, Jib, in Roundhouse	160†	Shop Drilling Square Holes	126
Cincinnati-Bickford High Speed Upright Drill Cincinnati Continuation Schools404\$,	418*	Crank Axles, Development of on the Lan- cashire & Yorkshire Ry	406*	Driving Box, Babbitting Hub Side of	299†
Cincinnati Electrical Tool Company Electric		Crank Axles, Increasing Life of	280	Driving Box, Babbitting Shells of Driving Box Brasses, Shimming	219
Hammer Cincinnati Milling Machine Co. High Power Milling Machines	168*	Crank Pin Block	56*	Driving Box, Casting Shells and Hub Plate	910
Cincinnati Planer Co., 22-Inch Planer Cincinnati Planer Co. Two-Speed Planer	37*	Crank Pin, Machine for Turning Off the Rivet Head on.		Driving Box, Machine Tools Required for Driving Box, Machining of	180
Cincinnati Planer for Cylinders	73*	Crank Pins, Machine Tools Required for Crawford, D. F., On the Mechanical Stokers	122	Driving Box, Moulding Grease for Driving Wheel Tires, Flange Wear on Driving Wheels and Tires, Machine Tools	248
Cincinnati, University of, Co-operative Engineering Courses	497†	Crosby Mechanical Stoker	279	Required for Drop Doors, Air Operated, Summers Ore Car	122
Cinders from Briquets	9*	Crosshead Gibs, Babbitting Crosshead, Machine Tools Required for	122	Drop Doors, Steel Coke Car	188*
Circuit Breakers, New Haven Electrification Circulation in Fire Box Water Legs	28	Crosshead Shoes, Babbitting	322	Drop Pits, East Buffalo Roundhouse Drop Tables, Cost of	1311
Cleaver, F. C., On Superheaters	288	Crude Oil Heater for Steel Car Repairs.92*, Cups, Individual Drinking	299†	Duff Mfg. Co., Hydraulic Jacks Duluth & Iron Range R. R., Steel Hopper	177*
ment of the Beech Grove Shops Cleveland Machine Tool Works, Horizontal	133*	Cup for Measuring Oil		Dupree, W. H., Locomotive Crank Pin Lu-	338*
Cleveland Twist Drill Co., Flat Twisted Drill	378*	Cut-off Saw, Abrasion	377†	Dust Guards, Standard	415°
Coach and Paint Shop, Idaho & Washington Nor. Ry.		Cut-off Saw, Heavy Automatic	421*	Dynamometer for Coupler Side Clearance Tests	824
Coal.		Cutting Metal by Oxy-Acetylene Methods Cutting Metals, Oxy-Acetylene Machine	528	Е	
Basing Contracts on Amount of Ash Buying on a Heat Value Basis. 189, 314		Cylinder.	490*	East Buffalo Roundhouse, N. Y. C. & H. R. R. R. R.	3
Conservation of	379†	2-8-0 Loco., C. P. Ry	226*	R. R. Conomizers, Cost and Saving. "Economy" Drill Sockets. Education, Co-operative.	78
How to Burn Successfully in a Locomo		Balanced Simple Loco., C. R. I. & P. Ry. Brake, Cleaning	469*	Education, Co-operative, Only. of Chichingti,	497
Inspection of	393†	Condensation	223	Education of Firemen, D. R. MacBain	198
Lignite as Fuel for Locos	176†	LatheLife of on the Lancashire & Yorkshire	260*	Education, How to Impress the Apprentice With the Value of	437
Testing Locomotive	346	Ry Low Pressure for Virginian Mallet Loco.	406 358*	Education, Industrial Education, Industrial, Important Develop-	312
Coaling Stations, Cost of Operating	402	Power and Heating Surface, Diagram for Determining the Relation Between,		Education of Railroad Men	404
Coaling Station, East Buffalo Roundhouse Coates Clipper Flexible Shaft Applications.	209-	Machine Tools Required for Planer, Cincinnati	122	Pacific Information, Union	392
Coke Car, Four Hopper, Steel, P. R. R Colburn Machine Tool Co. Vertical Boring	390*	Saddle, High Pressure, 2-8-8-2 Loco., So. Pac. Co.		Educational Methods, The Need of Better Efficiency of an Engine, Theoretical Efficiency, The Gospel of	288
Mill	456*	D	001	Efficiency Notes Efficiency of Power Plants	444
Superheated Steam	, 339	Damon, George A., Analysis of Cost of Loco- motive Repair Shops		Efficiency Records, Individual Efficiency of the Shop, Building Up	218
Cole Superheater on Atlantic Type Loco., C R. I. & P. Ry	467*	Darling, Philip G., Safety Valve Capacity	162°	Efficiency System, How to Perpetuate Efficiency System, What It Is	486
College Men in Railroad Service	. 176	Deems, J. F., On Apprenticeship	. 385	Efficient Foremen	234

Eight-Wheel Switching Loco., Va. Ry 359*	Fireman, Limitations of	Buying on a Heat Value Basis, 189, 314, 347†
Electric Hammer 171†	Fires, Locomotives Equipped for Fighting 4707	See "Coal."
Electric Loco., Detroit River Tunnel 362* Electric Loco., Freight, N. Y. N. 11. & H.	Fires on P. R. R. Property	Contracts Based on Amount of Ash 403† Economy
R. R 498*	Firing, Bank vs. Level	Editorial Comment 364§
Electric Loco., New Haven, Results of 29	Firing Lignite Burning Locomotives 391	Inspection of
Electric Loco., Pennsylvania261†, 490* Electric Loco. With Connecting Rods 307*	Fitt, E. W., Lignite Coal as Fuel for Loco- Motives	Peat as a
Electric Railway, 1200 Volt Direct Current. 159† Electric Turntable Donkey	Flange Wear on Driving Tires 248*	Records, Individual
Electric Turntable Donkey	Flanging Machines Required in Loco. Boiler Shop	Stations, Cost of Operating 403 Testing Locomotive
Electrification, Pennsylvania, Direct Current 75†	Flat Wheels, Effect of on Rails111‡, 149‡	
Electrification, Results of on N. Y. N. H. &	Flexible Shaft Applications 259*	Fuel Association, International Ry 462† Fuller, C. E., Motor Cars
H. R. R	Flexible Staybolts	Fuller, C. E., On Superheaters 287
Elliott, J. B., On Superheaters 287	Flexible Stayholts, A New Departure in 190*	Fulton Bill Dangerous to Railroads 66 Fulton Bill Reported Adversely 105†
Emerson, Harrington, Design of Oil Burning Locomotives	Flexible Stapbolts, A Criticism 494‡ Flues (see Tubes).	Furnace, Crude Oil, Kirkwood. 341* Furnace, Flue Welding. 460*
Emerson, Harrington, Dinner to 486§	Flue Plant, An Efficient, Collinwood 350*	Furnace, Flue Welding
Emerson, Harrington, Mallet Comp. Locos 15 Emerson, R., On Testing Locomotive Fuel 396	Flue Welding Furnace	Furnace for Heating Steel Car Parts 174*
Empirical Formula for Designing Locomotive	Folding Doors for Roundhouses 41*	
and Car Parts 312§	Foote-Burt High Duty Drill	G
Employees, Insurance for	Forcing Press	Gaines, F. F., On Superheaters 288
Engine Equipments (see Locomotive Supplies).	Foreman, Bonus Schedule for 235	Gardner, Henry, On Results from Appren-
Engine Failures	Foremen's Convention, Ry. General 118† Foreman, Difficulty in Determining the Effi-	ticeship
come 414*	ciency of 234	Gas-Electric Motor Cars, So. Ry 495
Engine Failures and Roundhouse Service29†	Foremen, Efficient	Gas Producer Tests
Engine House.	Foreman, How to Stimulate and Reward 234	Gasket, Air Brake Hose 295*
Air Compressors in	Foremen, Necessity of Training	Gasket Cutter
Cinder Pits	Forest Products Laboratory 1617	Gasoline Tanks, How to Repair Leaky 3507
Conditions 23§	Forest Resources, Condition of in the U. S. 114	Gate Shear, 125-Inch
Dispatch Tube, Pneumatic	Forest Service, Railroad Co-operates With 360† Forging at the Altoona Car Shops 210*	Pressure 495*
East Buffalo, N. Y. C. & H. R. R 3*	Forging Brake Rod Jaws at the Collinwood	Gauges for Car Wheels
Facilities	Shops	Gauges for Mounting and Inspecting Wheels 327* Gauge of Tracks, Widening
Folding Doors for	Forging Coupler Yoke Fillers 229*	Gears, Noiseless
Foreman, Troubles of	Forging Dies, Vanadium Steel for 497 Formula for Designing Locomotive and Car	General Electric Co. Electric Loco 362* General Electric Co. Electric Loco. With
Idaho & Washington Nor. Ry 154*	Parts, Empirical 3128 Four-Cylinder Simple Loco., 4-4-2, C. R. I. &	Connecting Rods
Inspection Pits 21†	P. Ry	General Electric Co., Gas-Electric Motor Cars 495 General Foremen's Convention, Railway 118†
Jib Crane in	Fowler, Geo. L., Effect of Flat Wheels on	General Service Steel Gondola Car, Denver
Machine Shop, East Buffalo 7*	Rails 149‡	& Rio Grande Ry 250*
Pneumatic Dispatch Tube for	Frame, 2-8-0 Loco., C. P. Ry	General Service Steel Gondola Car, Maine Central Ry 252*
Stop Block for Engines	Frame, 2-8-2 Loco., Va. Ry	General Service Steel Gondola Car, Nor.
Track "Skate" in 1617 Windows 58†	Frame, 2-8-8-2 Loco., So. Pac. Co 368*	Pac. Ry
Engine, Theoretical Efficiency of 220	Frame Brace, 2-8-2 Loco., Va. Ry 228*	Gold Leaf for Signal Blades 10†
Engineering Education, Co-operative199, 4977	Frame Braces, 4-6-2 Loco., Nor. Pac. Ry 196* Frame Cross Tie at Cylinders, 2-8-0 Loco., C.	Gondola Car, 50-Ton Steel, Denver & Rio Grande
Enginemen as Passenger Agents 487† Enginemen, Telephones for Calling 18†	P. Ry 429*	Gondola Car, 50-Ton Steel, Maine Central
Engineer's Hammer 55°	Frame, Loco., Machine Tools Required for 122 Frame, Welding Locomotive, Rutland Ry 453*	Ry. 252* Gondola Car, 50-Ton Steel, Norfolk & West-
Ensie, E. Fish, Handling Loco. Supplies 54* Epler, J. E., Heat and Water Conserving	France, Western Ry. of, Bal. Comp. 4-6-2	ern Ry 349*
Systems for Cleaning and Washing Out	Loco	Gondola Car, 50-Ton Steel, Nor. Pac. Rv 251*
Boilers	Loco. Crank Axles 396*	Gondola Car, 50-Ton Steel, Virginian Ry 395* Good Principles Wrongly Applied 3128
Equipment Industries and Railroad Prosperity 471	Franey, M. D., Engine Failures and How They Are Overcome	Goss, W. F. M., Comparative Tests of Run-
Erasing Device for Drafting Room 259* Erecting and Machine Shop, Beech Grove 133*	Francy, M. D., The Shop Surgeon	of-Mine and Briqueted Coal on Locos. 628, 67* Goss, W. F. M., Locomotive Performance
Erecting and Machine Shop, Idaho & Wash-	Freezing of Air Brake Hose 27	with Saturated and Superheated Steam,
ington Nor. Ry 155°	Freight Car (see Steel Freight Cars). Freight Car Pool, General	Gossett, C. E., On the Mechanical Stokers. 281
Erecting Shops, Lighting of	Freight Car Pool, The Pennsylvania System 86	Grain Doors 296
European Locomotive Boiler Design, Tenden-	Freight Car Trucks 335*	Grain Door, Metal
cy of		
Europeon Maintonio, Diriginess on	Freight Locomotive.	Graphic Recording Wattmeter 323*
Funnaration and Combustion Locomotive 231	0-6-6-0, D. N. W. & P. Ry 61*	Graphic Recording Wattmeter
Funnaration and Combustion Locomotive 231	0-6-6-0, D. N. W. & P. Ry 61* 0-6-6-0, Tabular Comparison 275 0-8-8-0, Data	Graphical Recording Wattmeter
Evaporation and Combustion, Locomotive 231 Exhaust Nozzle, Virginian Mallet Loco 358° Exhaust Pipe, Virginian Mallet Loco 358° Exhibition of Railways and Land Transport,	0-6-6-0, D. N. W. & P. Ry. 61* 0-6-6-0, Tabular Comparison 275 0-8-8-0, Data 275 2-6-6-0, Data 275	Graphic Recording Wattmeter. 323* Graphical Records. 236* Grate Area and Heating Surface, Relative Importance of 231 Grates, Chain 446
Evaporation and Combustion, Locomotive 231 Exhaust Nozzle, Virginian Mallet Loco 358° Exhaust Pipe, Virginian Mallet Loco 358° Exhibition of Railways and Land Transport, Argentine Republic	0-6-6-0, D. N. W. & P. Ry. 61* 0-6-6-0, Tabular Comparison 275 0-8-8-0, Data 275 2-6-6-0, Data 275 2-6-6-0, Virginian Ry. 261*, 357* 2-6-6-2, Ingenio Angelina. 71*	Graphical Recording Wattmeter. 323* Graphical Records 236* Grate Area and Heating Surface, Relative Importance of 231 Grates, Chain 446 Grates for Lignite Burning Engines. 392
Evaporation and Combustion, Locomotive 231 Exhaust Nozzle, Virginian Mallet Loco 358° Exhaust Pipe, Virginian Mallet Loco 358° Exhibition of Railways and Land Transport, Argentine Republic	0-6-6-0, D. N. W. & P. Ry. 61* 0-6-6-0, Tabular Comparison 275 0-8-8-0, Data 275 2-6-6-0, Data 275 2-6-6-0, Virginian Ry. 261*, 357* 2-6-6-2, Ingenio Angelina. 71*	Graphic Recording Wattmeter 323* Graphical Records 236* Grate Area and Heating Surface, Relative Importance of 231 Grates, Chain 446 Grates for Lignite Burning Engines 392 Grease Cup for Crank Pins 415* Grease for Driving Boxes, Moulding 144*
Evaporation and Combustion, Locomotive 231 Exhaust Nozzle, Virginian Mallet Loco 358° Exhaust Pipe, Virginian Mallet Loco 358° Exhibition of Railways and Land Transport, Argentine Republic	0-6-6-0, D. N. W. & P. Ry. 61* 0-6-6-0, Tabular Comparison 275 0-8-8-0, Data 275 2-6-6-0, Data 275 2-6-6-0, Virginian Ry. 261*, 357* 2-6-6-2, Ingenio Angelina 71* 2-6-6-2, Tabular Comparison 275 2-8-0, C. P. R. 425* 2-8-0, Chicago & Alton Ry. 269*	Graphic Recording Wattmeter 323* Graphical Records 236* Grate Area and Heating Surface, Relative Importance of Grates, Chain 446 Grates Chain 446 Greates for Lignite Burning Engines 392 Grease Cup for Crank Pins 415* Grease for Driving Boxes, Moulding 144* Great Northern Ry., 4-6-2 Loco. With Superheater 413*
Evaporation and Combustion, Locomotive 231 Exhaust Nozzle, Virginian Mallet Loco 358° Exhaust Pipe, Virginian Mallet Loco 368° Exhibition of Railways and Land Transport, Argentine Republic	0-6-6-0, D. N. W. & P. Ry. 61* 0-6-6-0, Tabular Comparison 275 0-8-8-0, Data 275 2-6-6-0, Oxta 275 2-6-6-0, Virginian Ry. 261*, 357* 2-6-6-2, Ingenio Angelina. 71* 2-6-6-2, Tabular Comparison 275 2-8-0, C. P. R. 425* 2-8-0, Chicago & Alton Ry. 269* 2-8-0, Tabular Comparison 274	Graphical Recording Wattmeter. 323* Graphical Records . 236* Grate Area and Heating Surface, Relative Importance of . 231 Grates, Chain . 446 Grates for Lignite Burning Engines . 392 Grease Cup for Crank Pins . 415* Grease for Driving Boxes, Moulding . 144* Great Northern Ry., 4-6-2 Loco. With Superheater . 413* Great Northern R. R., Oxy-Acetylene Weld*
Evaporation and Combustion, Locomotive 231 Exhaust Nozzle, Virginian Mallet Loco 358° Exhaust Pipe, Virginian Mallet Loco 358° Exhibition of Railways and Land Transport, Argentine Republic	0-6-6-0, D. N. W. & P. Ry. 61* 0-6-6-0, Tabular Comparison 275 0-8-8-0, Data 275 2-6-6-0, Data 275 2-6-6-0, Virginian Ry. 261*, 357* 2-6-6-2, Ingenio Angelina. 71* 2-6-6-2, Tabular Comparison 275 2-8-0, C. P. R. 425* 2-8-0, Chicago & Alton Ry. 269* 2-8-0, Tabular Comparison 274 2-8-0, Wabash Pittsburgh Terminal Ry. 256* 2-8-2, Chicago, Milwaukee & Puget Sound	Graphical Recording Wattmeter
Evaporation and Combustion, Locomotive 231 Exhaust Nozzle, Virginian Mallet Loco 358° Exhaust Pipe, Virginian Mallet Loco 368° Exhibition of Railways and Land Transport, Argentine Republic	0-6-6-0, D. N. W. & P. Ry. 61* 0-6-6-0, Tabular Comparison 275 0-8-8-0, Data 275 2-6-6-0, Data 275 2-6-6-0, Virginian Ry. 261*, 357* 2-6-6-2, Ingenio Angelina. 71* 2-6-6-2, Tabular Comparison 275 2-8-0, C. P. R. 425* 2-8-0, Chicago & Alton Ry. 269* 2-8-0, Tabular Comparison 274 2-8-0, Wabash Pittsburgh Terminal Ry. 256* 2-8-2, Chicago, Milwaukee & Puget Sound Ry. 305*	Graphical Recording Wattmeter. 323* Graphical Records 236* Grate Area and Heating Surface, Relative Importance of 231 Grates, Chain 446 Grates for Lignite Burning Engines 392 Grease Cup for Crank Pins 415* Grease for Driving Boxes, Moulding 144* Great Northern Ry., 4-6-2 Loco. With Superheater 413* Great Northern R. R., Oxy-Acetylene Welding of Fireboxes 378 Great Northern Ry, Service Results of Mallet Comp. Locos. 17, 228
Evaporation and Combustion, Locomotive 231 Exhaust Nozzle, Virginian Mallet Loco 358* Exhaust Pipe, Virginian Mallet Loco 358* Exhibition of Railways and Land Transport, Argentine Republic	0-6-6-0, D. N. W. & P. Ry. 61* 0-6-6-0, Tabular Comparison 275 0-8-8-0, Data 275 2-6-6-0, Data 275 2-6-6-0, Virginian Ry. 261*, 357* 2-6-6-2, Ingenio Angelina. 71* 2-6-6-2, Tabular Comparison 275 2-8-0, C. P. R. 425* 2-8-0, Chicago & Alton Ry. 269* 2-8-0, Tabular Comparison 274 2-8-0, Wabash Pittsburgh Terminal Ry. 256* 2-8-2, Chicago, Milwaukee & Puget Sound Ry. 305* 2-8-2, Tabular Comparison 275 2-8-2, Tabular Comparison 255*	Graphic Recording Wattmeter 323* Graphical Records 236* Grate Area and Heating Surface, Relative Importance of Grates, Chain 446 Grates, Chain 446 Grates, Chain 415* Grease Cup for Crank Pins 415* Grease For Driving Boxes, Moulding 144* Great Northern Ry 46-2 Loco With Superheater Great Northern R R Oxy-Acetylene Welding of Fireboxes 378 Great Northern Ry Service Results of Mallet Comp 17 228 Grinder Link Hammett 30* Grinder Universal Cutter 116*
Expansition and Combustion, Locomotive 231 Exhaust Nozzle, Virginian Mallet Loco 358° Exhibition of Railways and Land Transport, Argentine Republic	0-6-6-0, D. N. W. & P. Ry. 61* 0-6-6-0, Tabular Comparison 275 0-8-8-0, Data 275 2-6-6-0, Data 275 2-6-6-0, Virginian Ry. 261*, 357* 2-6-6-2, Ingenio Angelina. 71* 2-6-6-2, Ingenio Angelina. 71* 2-6-6-2, Tabular Comparison 275 2-8-0, C. P. R. 425* 2-8-0, Chicago & Alton Ry. 269* 2-8-0, Tabular Comparison. 274 2-8-0, Wabash Pittsburgh Terminal Ry. 256* 2-8-2, Chicago, Milwaukee & Puget Sound Ry. 305* 2-8-2, Tabular Comparison. 275 2-8-2, Va. Ry. 255* 2-8-2, Va. Ry. 225*	Graphic Recording Wattmeter
Exaporation and Combustion, Locomotive 231 Exhaust Nozzle, Virginian Mallet Loco 358* Exhaust Pipe, Virginian Mallet Loco 358* Exhibition of Railways and Land Transport, Argentine Republic	0-6-6-0, D. N. W. & P. Ry. 61* 0-6-6-0, Tabular Comparison 275 0-8-8-0, Data 275 2-6-6-0, Data 275 2-6-6-0, Virginian Ry. 261*, 357* 2-6-6-2, Ingenio Angelina 71* 2-6-6-2, Ingenio Angelina 71* 2-6-6-2, Tabular Comparison 275 2-8-0, C. P. R. 425* 2-8-0, Chicago & Alton Ry. 269* 2-8-0, Tabular Comparison 274 2-8-0, Wabash Pittsburgh Terminal Ry. 266* 2-8-2, Chicago, Milwaukee & Puget Sound Ry. 305* 2-8-2, Tabular Comparison 275 2-8-2, Va. Ry. 225* 2-8-8-2, Santa Fe. 17*, 22\$, 477*	Graphical Recording Wattmeter
Exaporation and Combustion, Locomotive 231 Exhaust Nozzle, Virginian Mallet Loco 358* Exhaust Pipe, Virginian Mallet Loco 358* Exhibition of Railways and Land Transport, Argentine Republic	0-6-6-0, D. N. W. & P. Ry. 61* 0-6-6-0, Tabular Comparison 275 0-8-8-0, Data 275 2-6-6-0, Data 275 2-6-6-0, Virginian Ry. 261*, 357* 2-6-6-2, Ingenio Angelina 71* 2-6-6-2, Ingenio Angelina 71* 2-6-6-2, Tabular Comparison 275 2-8-0, C. P. R. 425* 2-8-0, Chicago & Alton Ry. 269* 2-8-0, Tabular Comparison 274 2-8-0, Wabash Pittsburgh Terminal Ry. 266* 2-8-2, Chicago, Milwaukee & Puget Sound Ry. 305* 2-8-2, Tabular Comparison 275 2-8-2, Va. Ry. 225* 2-8-8-2, Santa Fe. 17*, 22\$, 477*	Graphical Recording Wattmeter
Exaporation and Combustion, Locomotive 231 Exhaust Nozzle, Virginian Mallet Loco 358* Exhaust Pipe, Virginian Mallet Loco 358* Exhibition of Railways and Land Transport, Argentine Republic	0-6-6-0, D. N. W. & P. Ry. 61* 0-6-6-0, Tabular Comparison 275 0-8-8-0, Data 275 2-6-6-0, Data 275 2-6-6-0, Virginian Ry. 261*, 357* 2-6-6-2, Ingenio Angelina 71* 2-6-6-2, Ingenio Angelina 275 2-8-0, C. P. R. 425* 2-8-0, Chicago & Alton Ry. 269* 2-8-0, Tabular Comparison 274 2-8-0, Wabash Pittsburgh Terminal Ry. 256* 2-8-2, Chicago, Milwaukee & Puget Sound Ry. 305* 2-8-2, Tabular Comparison 275 2-8-2, Va. Ry. 225* 2-8-8-2, Data 17*, 22\$, 477* 2-8-8-2, So. Pac. Co.16*, 22\$, 181*, 199\$, 367* 2-10-2, Data 275 2-6-0, Tabular Comparison 275	Graphic Recording Wattmeter
Evaporation and Combustion, Locomotive 231 Exhaust Nozzle, Virginian Mallet Loco 358° Exhaust Pipe, Virginian Mallet Loco 358° Exhibition of Railways and Land Transport, Argentine Republic	0-6-6-0, D. N. W. & P. Ry. 61* 0-6-6-0, Tabular Comparison 275 0-8-8-0, Data 275 2-6-6-0, Data 275 2-6-6-0, Virginian Ry. 261*, 357* 2-6-6-2, Ingenio Angelina. 71* 2-6-6-2, Ingenio Angelina. 71* 2-8-0, C. P. R. 425* 2-8-0, Chicago & Alton Ry. 209* 2-8-0, Tabular Comparison 274 2-8-0, Wabash Pittsburgh Terminal Ry. 256* 2-8-2, Chicago, Milwaukee & Puget Sound Ry. 305* 2-8-2, Va. Ry. 225* 2-8-2, Va. Ry. 225* 2-8-8-2, Santa Fe. 17*, 22\$, 477* 2-8-8-2, So. Pac. Co.16*, 22\$, 181*, 199\$, 367* 2-10-2, Data 275 4-6-0, Tabular Comparison 275 4-6-0, Tabular Comparison 275 4-6-0, Tabular Comparison 275 4-6-0, Tabular Comparison 275 4-6-2, Gt. Nor. Ry. 413* 4-8-0, Data 275	Graphic Recording Wattmeter 323* Graphical Records 236* Grate Area and Heating Surface, Relative Importance of Grates, Chain 446 Grates, Chain 446 Grates for Lignite Burning Engines 392 Grease Cup for Crank Pins 415* Grease for Driving Boxes, Moulding 144* Great Northern Ry 46-2 Loco. With Superheater Heater 413* Great Northern R R Ory-Acetylene Welding of Fireboxes 378 Great Northern Ry Service Results of Mallet Comp. Locos Interpretable Comp. Locos 17 Grinder, Link Hammett Grinder, Universal Cutter 116* Grinding Car Axle Journals 1518 Grinding Car Wheels 208* Grip Nut Co., Car Window Fixtures 114* Guide, Loco., Machine Tools Required for 122 Guide Yoke, 2-8-0 Loco., C. P. Ry 430*
Exaporation and Combustion, Locomotive 231 Exhaust Nozzle, Virginian Mallet Loco 358° Exhaust Pipe, Virginian Mallet Loco 358° Exhibition of Railways and Land Transport, Argentine Republic	0-6-6-0, D. N. W. & P. Ry. 61* 0-6-6-0, Tabular Comparison 275 0-8-8-0, Data 275 2-6-6-0, Data 275 2-6-6-0, Virginian Ry. 261*, 357* 2-6-6-2, Ingenio Angelina 71* 2-6-6-2, Ingenio Angelina 275 2-8-0, C. P. R. 425* 2-8-0, Chicago & Alton Ry. 269* 2-8-0, Tabular Comparison 274 2-8-0, Wabash Pittsburgh Terminal Ry. 256* 2-8-2, Chicago, Milwaukee & Puget Sound Ry. 305* 2-8-2, Tabular Comparison 275 2-8-2, Va. Ry. 225* 2-8-2, Va. Ry. 225* 2-8-8-2, Data 17*, 228, 477* 2-8-8-2, So. Pac. Co.16*, 22\$, 181*, 199\$, 367* 2-8-10-2, Data 275 2-6-0, Tabular Comparison 275 2-6-0, Data 275 2-	Graphic Recording Wattmeter 323* Graphical Records 236* Grate Area and Heating Surface, Relative Importance of Grates, Chain 446 Grates, Chain 446 Grates for Lignite Burning Engines 392 Grease Cup for Crank Pins 415* Grease for Driving Boxes, Moulding 144* Great Northern Ry 46-2 Loco. With Superheater Great Northern R. R., Oxy-Acetylene Welding of Fireboxes 378 Great Northern Ry 8-rive Results of Mallet Comp. Locos Iet Comp. Locos 17, 22\$ Grinder, Link, Hammett 30* Grinder, Universal Cutter 116* Grinding Car Wheels 208* Grip Nut Co., Car Window Fixtures 114* Guide, Loco., Machine Tools Required for 122 Guide Yoke, 2-8-0 Loco., C. P. Ry 430*
Exaporation and Combustion, Locomotive. 231 Exhaust Nozzle, Virginian Mallet Loco. 358° Exhaust Pipe, Virginian Mallet Loco. 358° Exhibition of Railways and Land Transport, Argentine Republic 214† F Facing, Boring and Turning Machine. 171° Failures 80° Failures (see Engine Failures). Fairbanks, Morse & Co., Gasoline Motor Car for P. R. R. 460° Fatalities en Railroads Show Marked Decrease 483 Feed Water Heater, Loco., Tests of 241 Feed Water Heater, Santa Fe Mallet Comp. Locos. 465° Ferguson Furnaces for Heating Steel Car Parts 174° Files of Precision 117 Firebox, Locomotive.	0-6-6-0, D. N. W. & P. Ry. 61* 0-6-6-0, Tabular Comparison 275 0-8-8-0, Data 275 2-6-6-0, Data 275 2-6-6-0, Virginian Ry. 261*, 357* 2-6-6-2, Ingenio Angelina. 71* 2-6-6-2, Ingenio Angelina. 71* 2-6-6-2, Tabular Comparison 275 2-8-0, C. P. R. 425* 2-8-0, Chicago & Alton Ry. 269* 2-8-0, Tabular Comparison 274 2-8-0, Wabash Pittsburgh Terminal Ry. 266* 2-8-2, Chicago, Milwaukee & Puget Sound Ry. 305* 2-8-2, Tabular Comparison 275 2-8-2, Va. Ry. 225* 2-8-8-2, Va. Ry. 225* 2-8-8-2, So. Pac. Co.16*, 22\$, 181*, 199\$, 367* 2-10-2, Data 275 4-6-0, Tabular Comparison 275 4-6-0, Tabular Comparison 275 4-6-2, Gt. Nor. Ry. 413* 4-8-0, Data 275 Friction Draft Gear. 331 Friction Saw for Flues. 351*	Graphic Recording Wattmeter
Exaporation and Combustion, Locomotive 231 Exhaust Nozzle, Virginian Mallet Loco 358° Exhaust Pipe, Virginian Mallet Loco 358° Exhibition of Railways and Land Transport, Argentine Republic	0-6-6-0, D. N. W. & P. Ry. 61* 0-6-6-0, Tabular Comparison 275 0-8-8-0, Data 275 2-6-6-0, Data 275 2-6-6-0, Virginian Ry. 261*, 357* 2-6-6-2, Ingenio Angelina. 71* 2-6-6-2, Tabular Comparison 275 2-8-0, C. P. R. 425* 2-8-0, Chicago & Alton Ry. 269* 2-8-0, Tabular Comparison 274 2-8-0, Wabash Pittsburgh Terminal Ry. 256* 2-8-2, Tabular Comparison 274 2-8-2, Chicago, Milwaukee & Puget Sound Ry. 305* 2-8-2, Tabular Comparison 275 2-8-2, Va. Ry. 225* 2-8-2, Va. Ry. 225* 2-8-8-2, Va. Ry. 225* 2-8-8-2, Va. Ry. 225* 2-8-8-2, Data 275 2-8-8-2, Santa Fe. 17*, 228, 477* 2-8-8-2, Son Pac. Co.16*, 228, 181*, 1998, 367* 2-10-2, Data 275 4-6-0, Tabular Comparison 275 4-6-0, Tabular Comparison 275 4-6-2, Gt. Nor. Ry. 413* 4-8-0, Data 275 Electric, N. Y. N. H. & H. R. 498* Friction Draft Gear 331 Friction Saws for Metal. 351*	Graphic Recording Wattmeter 323* Graphical Records 236* Grate Area and Heating Surface, Relative Importance of 231 Grates, Chain 446 Grates for Lignite Burning Engines 392 Grease Cup for Crank Pins 415* Grease for Driving Boxes, Moulding 144* Great Northern Ry., 4-6-2 Loco. With Superheater 413* Great Northern R., Oxy-Acetylene Welding of Fireboxes 378 Great Northern Ry., Service Results of Mallet Comp. Locos 17, 228 Grinder, Link, Hammett 30* Grinder, Universal Cutter 116* Grinding Car Axle Journals 1518 Grinding Car Axle Journals 1518 Grip Nut Co., Car Window Fixtures 114* Guide Yoke, 2-8-0 Loco., C. P. Ry. 430* H Haig, M. H., Jacobs-Shupert Fire Box 202** Hallenbeck, Geo. E., Data on High Speed Drilling
Exaporation and Combustion, Locomotive 231 Exhaust Nozzle, Virginian Mallet Loco 358° Exhaust Pipe, Virginian Mallet Loco 358° Exhibition of Railways and Land Transport, Argentine Republic F Facing, Boring and Turning Machine 171° Failures (see Engine Failures). Fairbanks, Morse & Co., Gasoline Motor Car for P. R. R	0-6-6-0, D. N. W. & P. Ry. 61* 0-6-6-0, Tabular Comparison 275 0-8-8-0, Data 275 2-6-6-0, Data 275 2-6-6-0, Virginian Ry. 261*, 357* 2-6-6-2, Ingenio Angelina. 71* 2-6-6-2, Ingenio Angelina. 71* 2-6-6-2, Tabular Comparison 275 2-8-0, C. P. R. 425* 2-8-0, Chicago & Alton Ry. 209* 2-8-0, Tabular Comparison 274 2-8-0, Wabash Pittsburgh Terminal Ry. 256* 2-8-2, Chicago, Milwaukee & Puget Sound Ry. 305* 2-8-2, Tabular Comparison 275 2-8-2, Tabular Comparison 275 2-8-2, Va. Ry. 225* 2-8-8-2, Santa Fe. 17*, 22\$, 477* 2-8-8-2, Santa Fe. 17*, 22\$, 477* 2-8-8-2, Santa Fe. 17*, 22\$, 477* 2-8-8-2, Santa Fe. 275 2-8-8-2, Santa Fe. 36-2,	Graphic Recording Wattmeter 323* Graphical Records 236* Grate Area and Heating Surface, Relative Importance of 231 Grates, Chain 446 Grates for Lignite Burning Engines 392 Grease Cup for Crank Pins 415* Grease for Driving Boxes, Moulding 14* Great Northern Ry, 4-6-2 Loco. With Superheater 413* Great Northern R. R., Oxy-Acetylene Welding of Fireboxes 378 Great Northern Ry, Service Results of Mallet Comp. Locos 17, 28* Grinder, Link, Hammett 30* Grinder, Link, Hammett 30* Grinder, Universal Cutter 116* Grinding Car Wheels 208* Grip Nut Co., Car Window Fixtures 114* Guide, Loco., Machine Tools Required for 122 Guide Yoke, 2-8-0 Loco., C. P. Ry 430* H Haig, M. H., Jacobs-Shupert Fire Box 202** Hallenbeck, Geo. E., Data on High Speed Drilling 207* Hamilton Heavy Automatic Railway Cut-off Saw 421*
Exaporation and Combustion, Locomotive 231 Exhaust Nozzle, Virginian Mallet Loco 358* Exhaust Pipe, Virginian Mallet Loco 358* Exhibition of Railways and Land Transport, Argentine Republic 214† F Facing, Boring and Turning Machine 171* Failures 380† Failures (see Engine Failures). Fairbanks, Morse & Co., Gasoline Motor Car for P. R. R. 460* Fatalities en Railroads Show Marked Decrease 483 Feed Water Heater, Loco., Tests of 241 Files, Efficiency of 444\$, 454*, 487\$ Files of Precision 117 Firebox, Locomotive. Brick Arches and Water Tubes in 322 Improvement in 104\$	0-6-6-0, D. N. W. & P. Ry. 61* 0-6-6-0, Tabular Comparison 275 0-8-8-0, Data 275 2-6-6-0, Data 275 2-6-6-0, Virginian Ry. 261*, 357* 2-6-6-2, Ingenio Angelina. 71* 2-6-6-2, Ingenio Angelina. 71* 2-6-6-2, Tabular Comparison 275 2-8-0, C. P. R. 425* 2-8-0, Chicago & Alton Ry. 269* 2-8-0, Tabular Comparison 274 2-8-0, Wabash Pittsburgh Terminal Ry. 266* 2-8-2, Chicago, Milwaukee & Puget Sound Ry. 268* 2-8-2, Chicago, Milwaukee & Puget Sound Ry. 25-8-2, Tabular Comparison 275 2-8-2, Va. Ry. 225* 2-8-8-2, Data 275 2-8-8-2, Sonta Fe. 17*, 22\$, 477* 2-8-8-2, Son Pac. Co.16*, 22\$, 181*, 199\$, 367* 2-10-2, Data 275 4-6-0, Tabular Comparison 275 4-6-0, Tabular Comparison 275 4-6-2, Gt. Nor. Ry. 418* 4-8-0, Data 275 Electric, N. Y. N. H. & H. R. R. 498* Friction Draft Gear 331 Friction Saws for Metal. 377† Front End Arrangement, 2-8-0 Loco., C. P. Ry. 427* Front End for Lignite Burning Engines 391*	Graphic Recording Wattmeter 323
Exaporation and Combustion, Locomotive 231 Exhaust Nozzle, Virginian Mallet Loco 358* Exhaust Pipe, Virginian Mallet Loco 358* Exhaust Pipe, Virginian Mallet Loco 358* Exhibition of Railways and Land Transport, Argentine Republic F Facing, Boring and Turning Machine 171* Failures (see Engine Failures). Fairbanks, Morse & Co., Gasoline Motor Car for P. R. R	0-6-6-0, D. N. W. & P. Ry. 61* 0-6-6-0, Tabular Comparison 275 0-8-8-0, Data 275 2-6-6-0, Data 275 2-6-6-0, Virginian Ry. 261*, 357* 2-6-6-2, Ingenio Angelina. 71* 2-6-6-2, Tabular Comparison 275 2-8-0, C. P. R. 425* 2-8-0, Chicago & Alton Ry. 269* 2-8-0, Tabular Comparison 274 2-8-0, Wabash Pittsburgh Terminal Ry. 256* 2-8-2, Tabular Comparison 274 2-8-2, Chicago, Milwaukee & Puget Sound Ry. 258-2, Chicago, Milwaukee & Puget Sound Ry. 258-2, Tabular Comparison 275 2-8-2, Tabular Comparison 275 2-8-2, Sa-1, 2525* 2-8-8-2, Va. Ry. 225* 2-8-8-2, Data 275 2-8-8-2, Son Pac. Co.16*, 22\$, 181*, 1998, 367* 2-10-2, Data 275 4-6-0, Tabular Comparison 275 4-6-2, Gt. Nor. Ry. 413* 4-8-0, Data 275 Electric, N. Y. N. H. & H. R. 498* Friction Draft Gear 331 Friction Saws for Metal 3777 Front End Arrangement, 2-8-0 Loco., C. P. Ry. 427* Front Ends, Tests on the Lancashire & Yorkshire Ry. 408*	Graphic Recording Wattmeter 323
Exaporation and Combustion, Locomotive. 231 Exhaust Nozzle, Virginian Mallet Loco. 358* Exhaust Pipe, Virginian Mallet Loco. 358* Exhaust Pipe, Virginian Mallet Loco. 358* Exhibition of Railways and Land Transport, Argentine Republic 214† Facing, Boring and Turning Machine. 171* Failures . 380† Failures (see Engine Failures). Fairbanks, Morse & Co., Gasoline Motor Car for P. R. 460* Fatalities en Railroads Show Marked Decrease 483 Feed Water Heater, Loco., Tests of 241 Feed Water Heater, Santa Fe Mallet Comp. Locos. 465* Ferguson Furnaces for Heating Steel Car Parts 174* Files, Efficiency of 4448, 454*, 487; Files of Precision 117 Firebox, Locomotive. Brick Arches and Water Tubes in 322 Improvement in 1048 Jacobs-Shupert, 1048, 106*, 147*‡, 2003, 247;, 271‡ Jacobs-Shupert, Mallet Compound Loco., Santa Fe 475* Oxy-Acetylene Welding of 378	0-6-6-0, D. N. W. & P. Ry. 61* 0-6-6-0, Tabular Comparison 275 0-8-8-0, Data 275 2-6-6-0, Data 275 2-6-6-0, Virginian Ry. 261*, 357* 2-6-6-2, Ingenio Angelina 71* 2-6-6-2, Ingenio Angelina 71* 2-6-6-2, Ingenio Angelina 71* 2-8-0, C. P. R. 425* 2-8-0, Chicago & Alton Ry. 269* 2-8-0, Chicago & Alton Ry. 269* 2-8-0, Wabash Pittsburgh Terminal Ry. 256* 2-8-2, Chicago, Milwaukee & Puget Sound Ry. 305* 2-8-2, Tabular Comparison 275 2-8-2, Va. Ry. 225* 2-8-8-2, Va. Ry. 225* 2-8-8-2, Santa Fe. 17*, 22\$, 477* 2-8-8-2, Santa Fe. 17*, 22\$, 477* 2-8-8-2, So. Pac. Co.16*, 22\$, 181*, 199\$, 367* 2-10-2, Data 275 4-6-0, Tabular Comparison 275 4-6-0, Tabular Comparison 275 4-6-0, Tabular Comparison 375* Electric, N. Y. N. H. & H. R. 498* Friction Saw for Flues 351* Friction Saw for Flues 351* Friction Saw for Flues 351* Friction Saw for Metal 377* Front End Arrangement, 2-8-0 Loco, C. P. Ry. 427* Front End, Tests on the Lancashire & York-shire Ry. 408* Front End, Virginian Mallet Loco. 357*	Graphic Recording Wattmeter. 323* Graphical Records 236* Grate Area and Heating Surface, Relative Importance of 231 Grates, Chain 446 Grates for Lignite Burning Engines 392 Grease Cup for Crank Pins 415* Grease for Driving Boxes, Moulding 144* Great Northern Ry., 4-6-2 Loco. With Superheater 413* Great Northern R. R., Oxy-Acetylene Welding of Fireboxes 378 Great Northern R., Service Results of Mallet Comp. Locos 17, 228 Grinder, Link, Hammett 30* Grinder, Universal Cutter 116* Grinding Car Axle Journals 1518 Grinding Car Wheels 208* Grip Nut Co., Car Window Fixtures 114* Guide, Loco., Machine Tools Required for 122 Guide Yoke, 2-8-0 Loco., C. P. Ry. 430* H Haig, M. H., Jacobs-Shupert Fire Box 202* Hamilton Heavy Automatic Railway Cut-off Saw 421* Hamilton Machine Tool Company, All-Geared Head Lathe 502* Hamilton Single, Spindle Horizontal Car Boring Machine 501*
Expansition and Combustion, Locomotive. 231 Exhaust Nozzle, Virginian Mallet Loco. 358* Exhaust Pipe, Virginian Mallet Loco. 358* Exhaust Pipe, Virginian Mallet Loco. 358* Exhibition of Railways and Land Transport, Argentine Republic 214† F Facing, Boring and Turning Machine. 171* Failures 380° Failures (see Engine Failures). 580° Fairbanks, Morse & Co., Gasoline Motor Carfor P. R. R. 460* Fatalities en Railroads Show Marked Decrease. 483 Feed Water Heater, Loco., Tests of. 241 Feed Water Heater, Santa Fe Mallet Comp. Locos. 465* Ferguson Furnaces for Heating Steel CarParts 174* Files, Efficiency of. 444\$, 454*, 487; Files of Precision 117 Firebox, Locomotive. Brick Arches and Water Tubes in 322 Improvement in 104\$, 106*, 147**, 200*, 247*, 271*, 13cobs-Shupert, Mallet Compound Loco. Santa Fe 432* Sheets, Failure of 70*	0-6-6-0, D. N. W. & P. Ry. 61* 0-6-6-0, Tabular Comparison 275 0-8-8-0, Data 275 2-6-6-0, Virginian Ry. 261*, 357* 2-6-6-0, Virginian Ry. 261*, 357* 2-6-6-2, Ingenio Angelina. 71* 2-6-6-2, Ingenio Angelina. 71* 2-6-6-2, Tabular Comparison 275 2-8-0, C. P. R. 425* 2-8-0, Chicago & Alton Ry. 269* 2-8-0, Tabular Comparison 274 2-8-0, Wabash Pittsburgh Terminal Ry. 266* 2-8-2, Chicago, Milwaukee & Puget Sound Ry. 305* 2-8-2, Chicago, Milwaukee & Puget Sound Ry. 255* 2-8-8-2, Data 275 2-8-8-2, Data 275 2-8-8-2, Data 275 2-8-8-2, Santa Fe. 17*, 22\$, 477* 2-8-8-2, So. Pac. Co.16*, 22\$, 181*, 199\$, 367* 2-10-2, Data 275 4-6-0, Tabular Comparison 275 4-6-2, Gt. Nor. Ry. 413* 4-8-0, Data 275 Electric, N. Y. N. H. & H. R. 498* Friction Draft Gear 351* Friction Saw for Flues 351* Friction Saw for Flues 351* Friction Saw for Metal 377† Front End Arrangement, 2-8-0 Loco., C. P. Ry. 427* Front End Arrangement, 2-8-0 Loco., C. P. Ry. 408* Front Ends, Tests on the Lancashire & Yorkshire Ry. Front Ends, Tests on the Lancashire & Yorkshire Ry. Front End, Virginian Mallet Loco. 357* Fry, L. H., Combustion and Evaporation. 231	Graphic Recording Wattmeter
Exaporation and Combustion, Locomotive 231 Exhaust Nozzle, Virginian Mallet Loco 358* Exhaust Pipe, Virginian Mallet Loco 358* Exhibition of Railways and Land Transport, Argentine Republic	0-6-6-0, D. N. W. & P. Ry. 61* 0-6-6-0, Tabular Comparison 275 0-8-8-0, Data 275 2-6-6-0, Data 275 2-6-6-0, Virginian Ry. 261*, 357* 2-6-6-2, Ingenio Angelina 71* 2-6-6-2, Ingenio Angelina 71* 2-6-6-2, Ingenio Angelina 71* 2-6-6-2, Tabular Comparison 275 2-8-0, C. P. R. 425* 2-8-0, Chicago & Alton Ry. 269* 2-8-0, Chicago & Alton Ry. 269* 2-8-0, Wabash Pittsburgh Terminal Ry. 256* 2-8-2, Chicago, Milwaukee & Puget Sound Ry. 305* 2-8-2, Tabular Comparison 275 2-8-2, Va. Ry. 225* 2-8-8-2, Va. Ry. 225* 2-8-8-2, So. Pac. Co.16*, 22\$, 181*, 199\$, 367* 2-10-2, Data 17*, 22\$, 477* 2-6-0, Tabular Comparison 275 4-6-0, Tabular Comparison 275 4-6-0, Tabular Comparison 275 4-6-0, Tabular Comparison 275 4-6-0, Tabular Comparison 375* 4-8-0, Data 275 4-6-0, Tabular Comparison 275 4-6-0, Ta	Graphic Recording Wattmeter
Expansation and Combustion, Locomotive 231 Exhaust Nozzle, Virginian Mallet Loco 368* Exhaust Pipe, Virginian Mallet Loco 368* Exhaust Pipe, Virginian Mallet Loco 358* Exhibition of Railways and Land Transport, Argentine Republic	0-6-6-0, D. N. W. & P. Ry. 61* 0-6-6-0, Tabular Comparison 275 0-8-8-0, Data 275 2-6-6-0, Data 275 2-6-6-0, Virginian Ry. 261*, 357* 2-6-6-2, Ingenio Angelina. 71* 2-6-6-2, Tabular Comparison 275 2-8-0, C. P. R. 425* 2-8-0, Chicago & Alton Ry. 269* 2-8-0, Tabular Comparison 274 2-8-0, Wabash Pittsburgh Terminal Ry. 256* 2-8-2, Tabular Comparison 274 2-8-2, Chicago, Milwaukee & Puget Sound Ry. 305* 2-8-2, Tabular Comparison 275 2-8-2, Va. Ry. 225* 2-8-2, Va. Ry. 225* 2-8-2, Va. Ry. 225* 2-8-8-2, Data 275 2-8-8-2, Sonta Fe. 17*, 228, 477* 2-8-8-2, Son Pac. Co.16*, 228, 181*, 1998, 367* 2-10-2, Data 275 4-6-0, Tabular Comparison 275 4-6-0, Tabular Comparison 275 4-6-2, Gt. Nor. Ry. 413* 4-8-0, Data 275 Electric, N. Y. N. H. & H. R. R. 498* Friction Draft Gear 31* Friction Saws for Metal 377† Front End Arrangement, 2-8-0 Loco., C. P. Ry. 427* Front End for Lignite Burning Engines 391* Front Ends, Tests on the Lancashire & Yorkshire Ry. 408* Fry, L. H., Combustion and Evaporation 281 Fry, L. H., Combustion and Evaporation 281 Fry, L. Sand Pricage 281 Fry, L. Sand Pricage 284 3-458 4-589 Fry, L. H., Combustion and Evaporation 281 Fry, L. Sand Pricage 284 5-3658	Graphic Recording Wattmeter
Exaporation and Combustion, Locomotive 231 Exhaust Nozzle, Virginian Mallet Loco 358* Exhaust Pipe, Virginian Mallet Loco 358* Exhaust Pipe, Virginian Mallet Loco 358* Exhibition of Railways and Land Transport, Argentine Republic	0-6-6-0, D. N. W. & P. Ry. 61* 0-6-6-0, Tabular Comparison 275 0-8-8-0, Data 275 2-6-6-0, Data 275 2-6-6-0, Virginian Ry. 261*, 357* 2-6-6-2, Ingenio Angelina. 71* 2-6-6-2, Ingenio Angelina. 71* 2-6-6-2, Ingenio Angelina. 71* 2-8-0, C. P. R. 425* 2-8-0, C. P. R. 425* 2-8-0, Chicago & Alton Ry. 269* 2-8-0, Tabular Comparison. 274 2-8-0, Wabash Pittsburgh Terminal Ry. 266* 2-8-2, Chicago, Milwaukee & Puget Sound Ry. 305* 2-8-2, Chicago, Milwaukee & Puget Sound Ry. 255* 2-8-8-2, Va. Ry. 225* 2-8-8-2, Va. Ry. 225* 2-8-8-2, So. Pac. Co.16*, 22\$, 181*, 199\$, 367* 2-10-2, Data 175* 2-10-2, Data 275 4-6-0, Tabular Comparison 275 4-6-2, Gt. Nor. Ry. 412* 4-8-0, Data 275 Electric, N. Y. N. H. & H. R. 498* Friction Draft Gear. 351* Friction Saw for Metal. 377† Front End Arrangement, 2-8-0 Loco., C. P. Ry. 408* Front End Arrangement, 2-8-0 Loco., C. P. Ry. 408* Front End For Lignite Burning Engines. 391* Front End, Virginian Mallet Loco. 357* Front End, Virginian Mallet Loco. 357* Fry, L. H., Combustion and Evaporation. 231 Fry, Lawford H., Diagram for Determining the Relation Between Cylinder Power and Heating Surface. 345*, 365\$ Fry, Lawford H., Diagram for Determining the Relation Between Cylinder Power and Heating Surface. 345*, 365\$ Fry, Lawford H., Diagram for Determining the Relation Between Cylinder Power and Heating Surface. 345*, 365\$ Fry, Lawford H., Diagram for Determining the Relation Between Cylinder Power and Heating Surface. 345*, 365\$ Fry, Lawford H., Diagram for Determining the Relation Between Cylinder Power and Heating Surface. 345*, 365\$ Fry, Lawford H., Diagram for Determining the Relation Between Cylinder Power and Heating Surface. 345*, 365\$ Fry, Lawford H., Diagram for Determining the Relation Between Cylinder Power and Heating Surface. 345*, 365\$	Graphic Recording Wattmeter 323
Expansation and Combustion, Locomotive 231 Exhaust Nozzle, Virginian Mallet Loco 368* Exhaust Pipe, Virginian Mallet Loco 368* Exhaust Pipe, Virginian Mallet Loco 358* Exhibition of Railways and Land Transport, Argentine Republic	0-6-6-0, D. N. W. & P. Ry. 61* 0-6-6-0, Tabular Comparison 275 0-8-8-0, Data 275 2-6-6-0, Data 275 2-6-6-0, Virginian Ry. 261*, 357* 2-6-6-2, Ingenio Angelina. 71* 2-6-6-2, Ingenio Angelina. 71* 2-6-6-2, Ingenio Angelina. 71* 2-8-0-2, C. P. R. 425* 2-8-0, C. P. R. 425* 2-8-0, Chicago & Alton Ry. 269* 2-8-0, Tabular Comparison. 274 2-8-0, Wabash Pittsburgh Terminal Ry. 256* 2-8-2, Chicago, Milwaukee & Puget Sound Ry. 256* 2-8-2, Tabular Comparison. 275 2-8-2, Tabular Comparison. 275 2-8-2, Va. Ry. 225* 2-8-8-2, Santa Fe. 17*, 22\$, 477* 2-8-8-2, So. Pac. Co.16*, 22\$, 181*, 199\$, 367* 2-10-2, Data 275 4-6-0, Tabular Comparison. 275 4-6-0, Tabular Comparison. 275 4-6-0, Tabular Comparison. 275 4-6-0, Tabular Comparison. 275 4-6-2, Gt. Nor. Ry. 412* 4-8-0, Data 275 Friction Saw for Flues. 351* Friction Saw for Metal. 377† Front End Arrangement, 2-8-0 Loco, C. P. Ry. 408* Front End for Lignite Burning Engines. 377† Front End, Virginian Mallet Loco. 357* Fry, L. H., Combustion and Evaporation. 231 Fry, Lawford H., Diagram for Determining the Relation Between Cylinder Power and Heating Surface 345* Fry, Lawford H., The Heat Treatment of Spring Steel 492* Fry, Lawford H., Train Resistance Formulas 472	Graphic Recording Wattmeter 323
Expansation and Combustion, Locomotive. 231 Exhaust Nozzle, Virginian Mallet Loco. 368* Exhaust Pipe, Virginian Mallet Loco. 358* Exhaust Pipe, Virginian Mallet Loco. 358* Exhibition of Railways and Land Transport, Argentine Republic 214† F Facing, Boring and Turning Machine. 171* Failures (see Engine Failures). Fairbanks, Morse & Co., Gasoline Motor Car for P. R. R. 460* Fatalities en Railroads Show Marked Decrease 483 Feed Water Heater, Loco., Tests of. 241 Feed Water Heater, Santa Fe Mallet Comp. Locos. 465* Ferguson Furnaces for Heating Steel Car Parts 174* Files, Efficiency of. 4448, 454*, 457* Files of Precision. 117 Firebox, Locomotive. Brick Arches and Water Tubes in. 322 Improvement in 1048 Jacobs-Shupert, 1048, 106*, 147**, 200\$, 247\$, 271\$; Jacobs-Shupert, Mallet Compound Loco. Santa Fe Oxy-Acetylene Welding of. 378 Repairing With Oxy-Acetylene. 432* Sheets, Failure of 70* Sheets, Life of. 20, 238 Water Legs, Circulation in. 58 Wide, Failure of Side Sheets on 70* Wide. Side Sheets of 20, 288 Wood's 271\$ Wood's C. B. & Q. Ry. 378* Fire Losses in the United States. 347†	0-6-6-0, D. N. W. & P. Ry. 61* 0-6-6-0, Tabular Comparison 275 0-8-8-0, Data 275 2-6-6-0, Data 275 2-6-6-0, Virginian Ry. 261*, 357* 2-6-6-2, Ingenio Angelina. 71* 2-6-6-2, Tabular Comparison 275 2-8-0, C. P. R. 425* 2-8-0, Chicago & Alton Ry. 269* 2-8-0, Tabular Comparison 274 2-8-0, Wabash Pittsburgh Terminal Ry. 256* 2-8-2, Tabular Comparison 275 2-8-2, Chicago, Milwaukee & Puget Sound Ry. 209* 2-8-2, Tabular Comparison 275 2-8-2, Va. Ry. 225* 2-8-2, Va. Ry. 225* 2-8-2, Va. Ry. 225* 2-8-8-2, Data 275 2-8-8-2, Santa Fe. 17*, 22\$, 477* 2-8-8-2, Son Pac. Co.16*, 22\$, 181*, 199\$, 367* 2-10-2, Data 275 4-6-0, Tabular Comparison 275 4-6-0, Tabular Comparison 275 4-6-2, Gt. Nor. Ry. 412* 4-8-0, Data 275 Electric, N. Y. N. H. & H. R. 498* Friction Draft Gear 31 Friction Saws for Metal 2-0, 277 Front End Arrangement, 2-8-0 Loco, C. P. Ry. 427* Front Ends, Tests on the Lancashire & Yorkshire Ry. 408* Front End, Virginian Mallet Loco. 357* Fry, Lawford H., Diagram for Determining the Relation Between Cylinder Power and Heating Surface 345* Fry, Lawford H., The Heat Treatment of Spring Steel 492* Fry, Lawford H., Train Resistance Formulas 472	Graphic Recording Wattmeter 323
Expansation and Combustion, Locomotive. 231 Exhaust Nozzle, Virginian Mallet Loco. 368* Exhibition of Railways and Land Transport, Argentine Republic 214† F Facing, Boring and Turning Machine. 171* Failures 380° Failures (see Engine Failures). 280° Failures (see Engine Failures). 460° Fatalities en Railroads Show Marked Decrease. 483 Feed Water Heater, Loco., Tests of 241 Feed Water Heater, Santa Fe Mallet Comp. 241 Feed Water Heater, Santa Fe Mallet Comp. 465° Ferguson Furnaces for Heating Steel Car Parts 174° Files, Efficiency of 4448, 454°, 487° Files of Precision 117 Firebox, Locomotive. Brick Arches and Water Tubes in 322 Improvement in 1048, 106°, 147°*, 200°, 247°, 271°, 13cobs-Shupert, Mallet Compound Loco. Santa Fe 0xy-Acetylene Welding of 378 Repairing With Oxy-Acetylene 432° Sheets, Failure of Side Sheets on 70° Sheets, Life of 20, 288 Water Legs, Circulation in 688 Wide, Failure of Side Sheets on 70° Wide, Side Sheets of 20, 238 Wood's 271° Wood's 271° Fire Losses in the United States 347° Firemen, Rest Men for 322	0-6-6-0, D. N. W. & P. Ry. 61* 0-6-6-0, Tabular Comparison 275 0-8-8-0, Data 275 2-6-6-0, Virginian Ry. 261*, 357* 2-6-6-2, Ingenio Angelina 71* 2-6-6-2, Ingenio Angelina 71* 2-6-6-2, Ingenio Angelina 71* 2-8-0, C. P. R. 425* 2-8-0, Chicago & Alton Ry. 269* 2-8-0, Chicago & Alton Ry. 269* 2-8-0, Tabular Comparison 274 2-8-0, Wabash Pittsburgh Terminal Ry. 266* 2-8-2, Chicago, Milwaukee & Puget Sound Ry. 25* 2-8-2, Tabular Comparison 275 2-8-2, Va. Ry. 225* 2-8-8-2, Santa Fe. 17*, 22\$, 477* 2-8-8-2, Santa Fe. 17*, 22\$, 477* 2-8-8-2, Sonta Fe. 17*, 22\$, 477* 2-8-8-2, Sonta Fe. 17*, 22\$, 477* 2-8-8-2, Sonta Fe. 375 4-6-0, Tabular Comparison 275 4-6-0, Tabular Comparison 275 4-6-0, Tabular Comparison 275 4-6-0, Tabular Comparison 375* Electric, N. Y. N. H. & H. R. R. 498* Friction Draft Gear 331 Friction Saw for Flues 351* Friction Saw for Metal 377* Front End Arrangement, 2-8-0 Loco, C. P. Ry. 427* Front End, Virginian Mallet Loco 357* Fry, L. H., Combustion and Evaporation 231 Fry, L. H., Combustion 2472 Fry, L. Lawford H., The Heat Treatment of Spring Steel 492* Fry, Lawford H., Train Resistance Formulas 472 Fuel. Accounting 316	Graphic Recording Wattmeter 323
Expansation and Combustion, Locomotive. 231 Exhaust Nozzle, Virginian Mallet Loco. 368* Exhaust Pipe, Virginian Mallet Loco. 358* Exhibition of Railways and Land Transport, Argentine Republic 214† F Facing, Boring and Turning Machine. 171* Failures (see Engine Failures). Fairbanks, Morse & Co., Gasoline Motor Car for P. R 460* Fatalities en Railroads Show Marked Decrease 483 Feed Water Heater, Loco., Tests of. 241 Feed Water Heater, Santa Fe Mallet Comp. Locos. 465* Ferguson Furnaces for Heating Steel Car Parts 174* Files, Efficiency of. 444\$, 454*, 457* Files of Precision. 117 Firebox, Locomotive. Brick Arches and Water Tubes in. 322 Improvement in 104\$, 106*, 147*\$, 200\$, 247\$, 271\$; Jacobs-Shupert, Mallet Compound Loco. Santa Fe 0xy-Acetylene Welding of. 378 Repairing With Oxy-Acetylene. 432* Sheets, Failure of 70* Sheets, Life of. 20, 238 Water Legs, Circulation in. 58 Wide, Failure of Side Sheets on 70* Wide. Side Sheets of 20, 288 Wood's 271\$ Wood's C. B. & Q. Ry. 378* Fire Losses in the United States. 347†	0-6-6-0, D. N. W. & P. Ry. 61* 0-6-6-0, Tabular Comparison 275 0-8-8-0, Data 275 2-6-6-0, Data 275 2-6-6-0, Virginian Ry. 261*, 357* 2-6-6-2, Ingenio Angelina. 71* 2-6-6-2, Tabular Comparison 275 2-8-0, C. P. R. 425* 2-8-0, Chicago & Alton Ry. 269* 2-8-0, Tabular Comparison 274 2-8-0, Wabash Pittsburgh Terminal Ry. 256* 2-8-2, Tabular Comparison 275 2-8-2, Chicago, Milwaukee & Puget Sound Ry. 209* 2-8-2, Tabular Comparison 275 2-8-2, Va. Ry. 225* 2-8-2, Va. Ry. 225* 2-8-2, Va. Ry. 225* 2-8-8-2, Data 275 2-8-8-2, Santa Fe. 17*, 22\$, 477* 2-8-8-2, Son Pac. Co.16*, 22\$, 181*, 199\$, 367* 2-10-2, Data 275 4-6-0, Tabular Comparison 275 4-6-0, Tabular Comparison 275 4-6-2, Gt. Nor. Ry. 412* 4-8-0, Data 275 Electric, N. Y. N. H. & H. R. 498* Friction Draft Gear 31 Friction Saws for Metal 2-0, 277 Front End Arrangement, 2-8-0 Loco, C. P. Ry. 427* Front Ends, Tests on the Lancashire & Yorkshire Ry. 408* Front End, Virginian Mallet Loco. 357* Fry, Lawford H., Diagram for Determining the Relation Between Cylinder Power and Heating Surface 345* Fry, Lawford H., The Heat Treatment of Spring Steel 492* Fry, Lawford H., Train Resistance Formulas 472	Graphic Recording Wattmeter 323

Handling Loco. Supplies (see Loco. Supplies,	J	2-10-2, Data
Handling). Hardening of Steam Hose	Jack, Hydro-Pneumatic Pit	
Coaches 488*	Jacks, Pushing and Pulling for Steel Car	P. Rv
Harriman, Edward H	Repairs	* 4-4-2, Nor. Pac. Ry
Harriman Lines, Inspection on	104§, 106*, 147*‡, 200‡, 247‡, 271 Jacobs-Shupert Firebox, Mallet Comp. Locos.,	‡ 2-8-8-2, Santa Fe
Harriman Lines Unit System of Organization 445 Hauck Mfg. Co., Hydro-Carbon Burner 457	Santa Fe	* Reading Ry 459*
Hauling Power of Locomotive, Effect of	Jacobs, H. W., On Superheaters 288	the P. & R 473*
Superheated Steam on	Jib Crane Design	4 4 6 0 N C & C+ T D 50*
Havana, Western Ry. of, Eight-Wheel Switching Loco. 310 Hayden Mechanical Stoker. 280	Johns-Manville Co., "Phoenix" Smoke Jacks Johns-Manville Co., Pipe Joint Cement	* 4-6-0, Tabular Comparison275, 277 4-6-2, Chicago & Alton Ry268*
Heat Value Basis, Buying Coal on 189, 314, 347; Heater, Portable Rivet97*, 174	Johnston, W. E., Arcs Equal to Straight	4-0-2, C. B. & Q
Heater for Steel Car Repairs92*, 95*, 174'	Johnston, W. E., Failure of Side Sheets on	4-6-2. Gt. Nor. Ry 413*
Heating Surface and Cylinder Power, Dia- gram for Determining the Relation Be-	Wide Firebox Locos	4-6-2, Nor. Pac. Ry
tween	Journal Bearings, Machine for Boring 410	4-6-2. Western Rv. of France 26*
Importance of	Journals, Grinding Axle	§ 0-6-6-0, D. N. W. & P. Ry 61*
Hefielinger, Arthur E., Steel Passenger Car	Joy valve Gear on Locomotives320 , 300	0-8-8-0, Data 275
Design	K	2-6-6-0, Data
Henderson, G. R., On Mechanical Stokers 280 Hennessey, J. J., Abuse of the M. C. B. Re-	Kansas City Southern Railroad Co-operates	2-6-6-0, Virginian Ry261*, 357* 2-6-6-2, Ingenio Angelina
pair Card	With Forest Service	2-6-6-2, Tabular Comparison 275
Herbert, Edward G., The Efficiency of Files 454 Hibbard, H. Wade, On Superheaters. 28 "Highpower" Drill, Pratt & Whitney. 419 High Speed, Cost of. 411	Kirkwood Down Flame Flue Welding Fur- nace	
"Highpower" Drill, Pratt & Whitney 419 High Speed, Cost of	Kirkwood Oil Furnaces	* 2-0-0-2, 50. Idc. Co.,
High Speed Drilling, Data on	Knapp, S. H., The Lighting of Shops 298 Knuckle Pins	4-4-4-4, Electric
High Speed Steel Cutters for Surfacing 78	Kruttschnitt, J., Inspection on the Harriman Lines 31	Tion a dista (ode along a distay)
High Speed Steel Cutters for Woodworking. 363 High Speed Steel Milling Cutters (see Mill-		Balanced Comp., N. C. & St. L. Ry 52*
ing Cutters). High Speed Steel Tools, Tempering 393	L	Balanced Compound, Santa Fe 478* Balanced Comp., Western Ry. of France 26*
High Speed Twist Drills	Labor Organization, Functions of	
Hine System of Organization 445	Lake Shore & Michigan Southern Ry., Cast	Compound (see Hal Comp.)
Hoist for Handling Large Compound Air Pumps 143	Iron Ash Pan With Swinging Doors 24 Lake Shore & Michigan Southern Ry., En-	5* Compound (see Mallet Compound). Compound, Vauclain, C. M. & St. P. Ry. 115* Counterbalancing
Holes, Boring Square	gine Failures and How They Are Over-	Counterbalancing
Hood, Prof. O. P., The Slipping Point of Rolled Boiler Tube Joints3648, 370	Lake Shore & Michigan Southern Ry., Flue	Data Tables
Hopper Car for Coke, P. R. R 187	Lake Shore & Michigan Southern Ry Forg-	Flectric Freight N V N H & H D D 408*
Hopper Car for Ore, Summers	ing at the Collinwood Shops	1* Electric, Detroit River Tunnel
of	Ing Brake Rod Jaws	2* Electric, Pennsylvania261†, 490* Electric, With Connecting Rods 307*
Horizontal Milling Machines	draulic Press for Valve Chamber Bushings 48 Lake Shore & Michigan Southern, Machine	
Horwich Shops, Locos. Designed and Built	for Boring Car Journal Bearings 41	0* Mallet Comp., So. Pac. Co181*, 1998
at	Gear	6* Mallet, Tabular Comparison 275
Hose, Air Brake, Freezing of	and Ruilt at the Harwich Shaps 40	Mallet, Weight Distribution of 51* 6* Oil Burning, Design of
"NB" 40 Hose Coupling, Air Brake	Lang Tool Holder	0* Oil Burning, So. Pac. Ry181*, 199§
Hose Gaskets, Air Brake		Performance Records
Howard, John, On Apprenticeship 385 Hughes, George, Locos. Designed and Built	All-Geared Head 50	Superheater Air and Steam 19
at the Horwich Shops 406	Axle, Heavy 3	6*
Hungarian Engineers and Architects, Am. Soc. of	Car Wheel	Locomotive Supplies, Handling.
Hydraulic Coping Machine 383	High Speed, Motor Application to 17	7* 1908.
Hydraulic Jacks	Turret for Pin Work 26	2* Chisel Bar, Engineer's Standard 55*
Hydraulic Press for Valve Chamber Bushings 48: Hydro-Carbon Burner	Turret, Vertical, in Railroad Shops 26	Costs, Reliability of Comparative Ac-
Hydro-Pneumatic Pit Jack 450	Leaky Gasume Tanks, How to Repair 30	
1	Leather Belting	55 Oil Measuring Cup, Standard 57*
Idaho & Washington Nor. Ry. New Loco.	LeBlond Machine Tool Co., High Duty Engine Lathes	Standard Articles
and Car Shops	Lewis Institute, Plan for Joint Shop and	Valve Stem Clamp Emergency 56*
With Blowers 24	Lewis, Wilfred, High Speed Milling Cutters	Learnetine Terminal (see Boundhouse)
Sliding Doors	With Inserted Blades	Lodge & Shipley Heavy Axle Lathe 36*
Indicator Cards, Baker-Pilliod Valve Gear 3	Life of Side Sheets	172* Stocks London & Southwestern Ry., Joy Valve Gear 347*
Individual Drinking Cups	Lightfoot, Cecil, Locomotive Firebox Repairs 4:	
Individual Efficiency Records	Lighting Passenger Equipment, Electric 29	Lubrication Progress in Rosnoms of 901
Individual Fuel Records	Lignite Coal, Analysis of	Lumber, Decay of
Industrial Education, Cincinnati Continuation	Line Insulation, New Haven Electrification.	Tomber The Devine of
Schools	Lining of Steel Passenger Cars, Inside 2 Link Belt Coaling Station, East Buffalo	Dumber, Opermentions officers of the party and
Industrial Education, Important Development in	Roundhouse	9* Lunkenheimer Locomotive Blow-off Valve 500*
ment in	Ť ·	
Ingenio Angelina Loco., 2-6-6-2	Locomotive.	McAuliffe, Eugene, On Testing Locomotive
Inspection of Coal	T 0-6-0, Data 2	
Inspection on the Harriman Lines	† 0-8-0, Va. Ry	75 MacBain, D. R., On the Education of Fire- men
Instructions for Each Employee	0-8-0. Western Rv. of Havana 3	10* MacBain, D. R., On Firemen 322
Insulation of Line, New Haven Electrifica-	2-6-2, Tabular Comparison 2	76 MacFarland, H. B., Experience With Jacobs-
Insurance for Employees	2-8-0, Chicago & Alton Ry 2	25* Shupert Fire Rox
Interheater, So. Pac. Mallet Comp. Locos 18	* 2-8-0, Wabash Pittsburgh Terminal Ry 2	56* McKenna, R. F., President's Address, M. C.
Interstate Commerce Commission Needs Ex-	2-8-2, Chicago, Milwaukee & Puget Sound Ry	B. Association
Iowa Railway Club209, 422, 462, 48 Iron, Weights of Round	2-8-2. Tabular Comparison	75 Machine and Erecting Shop, Idaho & Wash-

ą

Machine Shop, East Buffalo Roundhouse 7*	Frame, Loco., Machine Tools Required	Saw, Cut-off, Metal 456*
Machine Shops, Lighting of	for	Saw, Friction, Metal
Locomotive	Friction Saw for Flues 351*	matic
Machine Shop Practice, George J. Burns, 134*, 150\$, 185, 219	Gate Shear, 125-Inch	Sensitive Radial Drill
Machine Tool Builders' Convention, National 462 Machinery, Photographing	Grinding Car Wheels	Shaper, Back Geared Crank112*, 166* Shapers, Boring Jigs in the Manufacture
Maher, Peter, On the Mechanical Stokers 281	for 122	of 118*
Maine Central 50-Ton Steel Gondola Car 252*	Hamilton Heavy Automatic Railway Cut- off Saw	Shaper Tests
Machine Tools.	Hamilton Machine Tool Co., All-Geared Head Lathe	Shear and Punch
Abrasion Cut-off Saw for Flues 351* Abrasion Saws for Metal 377†	Hamilton Single Spindle Horizontal Car	Boiler Shop 127
Air Brake Work in Loco. Shops, Ma-	Boring Machine	Shoes and Wedges, Machine Tools Required for 124
chine Tools Required for	Hamilton Vertical Car Boring Machines,	Spring and Brake Rigging, Loco., Ma- chine Tools Required for 124
American Tool Works Co. Sensitive Ra-	Hammer, Electric 1717	Springfield Machine Tool Co., Machine for Boring Loco. Driving Axles 173*
dial Drill	Hammett, H. G., Link Grinders 30* Hilles & Jones 125-Inch Gate Shear 88*	Staybolt Nipper, Pneumatic 173*
American Tool Works Co., Shaper 166* American Tool Works Co., Triple Geared	Horizontal Milling Machines168*, 214*	Staybolts, Machine Tools Required for 125
Head Lathe With Turret 34* American Wood Working Machinery	How One Railroad Selects Its	Steam Chests, Machine Tools Required for
Co.'s New Outside Moulder 175*	Journal Bearings, Machine for Boring 410* Lassiter Pneumatic Staybolt Nipper 178*	Steam Drop Hammer
Axle Lathe, Heavy, Lodge & Shipley 36* Axles, Locomotive, Boring	Lathe, All-Geared Head 502*	Shaper
Axles, Loco., Machine Tools Required for 122 Baker Bros., High Duty Drill 207*	Lathe, Axle, Heavy	Shaper
Bearings, Car Journal, Machine for Bor-	Lathe Headstocks, Modern Heavy Duty. 172* Lathe, High Duty374*, 420*	quired for
Bement-Miles High Power Milling Ma-	Lathe, High Speed, Motor Application to 177*	Tool Room, Loco. Shop, Machine Tools
chine	Lathe, Triple Geared 36-Inch With Tur- ret 34*	Required in 126 Truck Work, Engine and Tender, Ma-
Cut-off Saw 421*	Lathe, Turret for Pin Work 262* Lathe, Turret, Vertical, in Railroad	chine Tools Required for
Bentel & Margedant Co., Single Spindle Horizontal Car Boring Machine 501*	Shops 260*	Tubes, Abrasion Cut-off Saw for 351*
Bentel & Margedant Co., Vertical Car Boring Machines167*, 213*	LeBlond Machine Tool Co., High Duty Engine Lathes	Tubes, Machine Tools Required for 126 Turret Head Bolt Cutter
Bentel & Margedant Universal Wood-	Link Grinders, Hammett 30*	Turret Lathe for Pin Work
worker	Lodge & Shipley Heavy Duty Lathe	Turret on 36-Inch Triple Geared Lathe. 34*
quired in a Locomotive	Headstocks	Underwood Universal Boring, Turning and Facing Machine 171*
Bolt Cutter With Turret Head 8* Boring, Drilling & Milling Machine,	in a Locomotive	Universal Saw Bench. 262* Valve Gear, Machine Tools Required for 123
Horizontal	Milling, Boring and Drilling Machine, Horizontal	valves, Machine Loois Required for 123
Boring Machine, Single Spindle Horizon-	Milling Machine, Extra Heavy Rod 161* Milling Machine, Heavy Plain 214*	Vertical Boring Mill, 30-Inch
tal (Wood)	Milling Machine High Power 308*	Vertical Drill, High Speed
Boring Mill, Vertical	Milling Machines, Horizontal. 168* Milling Machine Tests. 309* Milling Machine, Vertical. 168* Milling Machine, Vertical, Worm Driven 212*	Vertical Milling Machine, Newton 212*
Brake and Spring Rigging, Loco., Ma-	Milling Machine, Vertical	Vertical Turret Lathe in Railroad Shops 260* Watson-Stillman Co., Forcing Press 209*
Brass Work in Loco. Shops, Machine	Motor Application to Geared Head High	Watson-Stillman Hydraulic Coping Ma-
Tools Required for	Speed Lathe	Chine
Brown & Sharpe Fleavy Flain Milling	Mueller Machine Tool Co., Radial Drill. 176* Multiple Spindle Drills in Railroad Shops 160*	quired for
Machine 214* Bullard Vertical Turret Lathe, Work	National-Acme Mfg. Co., Automatic	Woodworker, Hamilton Universal 342*
Bullard Vertical Turret Lathe, Work Done by	National-Acme Mfg. Co., Automatic Screw Machine	Woodworker, Hamilton Universal 342* Mailet Compound Locomotive.
Bullard Vertical Turret Lathe, Work Done by	National-Acme Mfg. Co., Automatic Screw Machine 300* Newton Cold Saw Cutting-off Machine. 456* Newton 3-Spindle Horizontal Drilling	Mailet Compound Locomotive. 0-6-6-0, D. N. & P. Ry
Bullard Vertical Turret Lathe, Work Done by	National-Acme Mfg. Co., Automatic Screw Machine	Mailet Compound Locomotive. 0-6-6-0, D. N. & P. Ry
Bullard Vertical Turret Lathe, Work Done by	National-Acme Mfg. Co., Automatic Screw Machine	Mailet Compound Locomotive. 0-6-6-0, D. N. & P. Ry
Bullard Vertical Turret Lathe, Work Done by	National-Acme Mfg. Co., Automatic Screw Machine	Woodworker, Hamilton Universal
Bullard Vertical Turret Lathe, Work Done by	National-Acme Mfg. Co., Automatic Screw Machine	Woodworker, Hamilton Universal
Bullard Vertical Turret Lathe, Work Done by	National-Acme Mfg. Co., Automatic Screw Machine	Woodworker, Hamilton Universal
Bullard Vertical Turret Lathe, Work Done by	National-Acme Mfg. Co., Automatic Screw Machine	Woodworker, Hamilton Universal. 342* Mailet Compound Locomotive. 0-6-6-0, D. N. & P. Ry. 61* 2-6-6-0, Va. Ry. 261*, 357* 2-6-6-2, Narrow Gauge, Ingenio Angelina 71* 2-8-8-2, Santa Fe. 17*, 22\$, 477* 2-8-8-2, So. Pac. Co. 16*, 22\$, 367* 4-4-6-2, Santa Fe. 17*, 22\$, 475* Design of 1998 Editorial Comment 14*, 22\$ Front Truck on. 14 Service Results on the Gt. Nor. Ry. 17*, 22\$ So. Pac. Co. 181*
Bullard Vertical Turret Lathe, Work Done by	National-Acme Mfg. Co., Automatic Screw Machine	Woodworker, Hamilton Universal. 342* Mailet Compound Locomotive. 0-6-6-0, D. N. & P. Ry 61* 2-6-6-0, Va. Ry. 261*, 357* 2-6-6-2, Narrow Gauge, Ingenio Angelina 71* 2-8-8-2, Santa Fe. 17*, 228, 477* 2-8-8-2, So. Pac. Co. 16*, 228, 367* 4-4-6-2, Santa Fe. 17*, 228, 475* Design of 1998 Editorial Comment 14*, 228 Front Truck on 14 Service Results on the Gt. Nor. Ry. 17, 228
Bullard Vertical Turret Lathe, Work Done by	National-Acme Mfg. Co., Automatic Screw Machine	Woodworker, Hamilton Universal. 342* Mailet Compound Locomotive. 0-6-6-0, D. N. & P. Ry. 61* 2-6-6-0, Va. Ry. 261*, 357* 2-6-6-2, Narrow Gauge, Ingenio Angelina 71* 2-8-8-2, Santa Fe. 17*, 22\$, 477* 2-8-8-2, So. Pac. Co. 16*, 22\$, 367* 4-4-6-2, Santa Fe. 17*, 22\$, 475* Design of 199\$ Editorial Comment 14* Service Results on the Gt. Nor. Ry. 17, 22\$ So. Pac. Co. 181*, 199\$ Tabular Comparison 275 Weight, Distribution of 51* Manufacture, Should the Railroads 146
Bullard Vertical Turret Lathe, Work Done by	National-Acme Mfg. Co., Automatic Screw Machine	Woodworker, Hamilton Universal. 342* Mailet Compound Locomotive. 0-6-6-0, D. N. & P. Ry. 61* 2-6-6-0, Va. Ry. 261* 357* 2-6-6-2, Narrow Gauge, Ingenio Angelina 71* 2-8-8-2, Santa Fe. 17*, 228, 477* 2-8-8-2, So. Pac. Co. 16*, 228, 367* 4-4-6-2, Santa Fe. 17*, 228, 475* Design of 1998 Editorial Comment 14*, 228 Front Truck on. 14 Service Results on the Gt. Nor. Ry. 17, 228 So. Pac. Co. 181*, 1998 Tabular Comparison 275 Weight, Distribution of 51* Manufacture, Should the Railroads 146 Marshall, W. H., The Equipment Industries
Bullard Vertical Turret Lathe, Work Done by	National-Acme Mfg. Co., Automatic Screw Machine	Woodworker, Hamilton Universal. 342* Mailet Compound Locomotive. 0-6-6-0, D. N. & P. Ry. 61* 2-6-6-0, Va. Ry. 261*, 357* 2-6-6-2, Narrow Gauge, Ingenio Angelina 71* 2-8-8-2, So. Pac. Co. 16*, 228, 477* 2-8-8-2, So. Pac. Co. 16*, 228, 475* Design of 1998 Editorial Comment 14* 228 Front Truck on 14 Service Results on the Gt. Nor. Ry. 17, 228 So. Pac. Co. 181*, 1998 Tabular Comparison 275 Weight, Distribution of 51* Manufacture, Should the Railroads 146 Marshall, W. H., The Equipment Industries and Railroad Prosperity. 471 M. C. B. Association Convention, Report of. 471
Bullard Vertical Turret Lathe, Work Done by	National-Acme Mfg. Co., Automatic Screw Machine	Woodworker, Hamilton Universal. 342* Mailet Compound Locomotive. 0-6-6-0, D. N. & P. Ry. 61* 2-6-6-60, Va. Ry. 261*, 357* 2-6-6-2, Narrow Gauge, Ingenio Angelina 71* 2-8-8-2, Santa Fe. 17*, 22\$, 367* 4-4-6-2, Santa Fe. 17*, 22\$, 475* Design of 199\$ Editorial Comment 14*, 22\$ Front Truck on 14*, 22\$ Front Truck on 181*, 199\$ Tabular Comparison 275 Weight, Distribution of 51* Manufacture, Should the Railroads 146 Marshall, W. H., The Equipment Industries and Railroad Prosperity 471 M. C. B. Association Convention, Report of 289* 290* 394*
Bullard Vertical Turret Lathe, Work Done by	National-Acme Mfg. Co., Automatic Screw Machine	Mailet Compound Locomotive. 0-6-6-0, D. N. & P. Ry
Bullard Vertical Turret Lathe, Work Done by	National-Acme Mfg. Co., Automatic Screw Machine	Woodworker, Hamilton Universal. 342* Mailet Compound Locomotive. 0-6-6-0, D. N. & P. Ry. 61* 2-6-6-0, Va. Ry. 261*, 357* 2-6-6-2, Narrow Gauge, Ingenio Angelina 71* 2-8-8-2, Santa Fe. 17*, 22\$, 477* 2-8-8-2, So. Pac. Co. 16*, 22\$, 367* 4-4-6-2, Santa Fe. 17*, 22\$, 475* Design of 199\$ Editorial Comment 14* Service Results on the Gt. Nor. Ry. 17, 22\$ So. Pac. Co. 181*, 199\$ Tabular Comparison 275 Weight, Distribution of 51* Manufacture, Should the Railroads 146 Marshall, W. H., The Equipment Industries and Railroad Prosperity. 471 M. C. B. Association Convention, Report of. 289*, 324* M. C. B. Association, President's Address. 289 M. C. B. Association, Revision of Constitution 289
Bullard Vertical Turret Lathe, Work Done by	National-Acme Mfg. Co., Automatic Screw Machine	Mailet Compound Locomotive. 0-6-6-0, D. N. & P. Ry
Bullard Vertical Turret Lathe, Work Done by	National-Acme Mfg. Co., Automatic Screw Machine	Mailet Compound Locomotive. 0-6-6-0, D. N. & P. Ry
Bullard Vertical Turret Lathe, Work Done by	National-Acme Mfg. Co., Automatic Screw Machine	Mailet Compound Locomotive. 0-6-6-0, D. N. & P. Ry
Bullard Vertical Turret Lathe, Work Done by	National-Acme Mfg. Co., Automatic Screw Machine	Mailet Compound Locomotive. 0-6-6-0, D. N. & P. Ry
Bullard Vertical Turret Lathe, Work Done by	National-Acme Mfg. Co., Automatic Screw Machine	Mailet Compound Locomotive. 0-6-6-0, D. N. & P. Ry
Bullard Vertical Turret Lathe, Work Done by	National-Acme Mfg. Co., Automatic Screw Machine	Mailet Compound Locomotive. 0-6-6-0, D. N. & P. Ry
Bullard Vertical Turret Lathe, Work Done by	National-Acme Mfg. Co., Automatic Screw Machine	Mailet Compound Locomotive. 0-6-6-0, D. N. & P. Ry
Bullard Vertical Turret Lathe, Work Done by	National-Acme Mfg. Co., Automatic Screw Machine	Mailet Compound Locomotive. 0-6-6-0, D. N. & P. Ry
Bullard Vertical Turret Lathe, Work Done by	National-Acme Mfg. Co., Automatic Screw Machine	Mailet Compound Locomotive. 0-6-6-0, D. N. & P. Ry
Bullard Vertical Turret Lathe, Work Done by	National-Acme Mfg. Co., Automatic Screw Machine	Mailet Compound Locomotive. 0-6-6-0, D. N. & P. Ry
Bullard Vertical Turret Lathe, Work Done by	National-Acme Mfg. Co., Automatic Screw Machine	Mailet Compound Locomotive. 0-6-6-0, D. N. & P. Ry
Bullard Vertical Turret Lathe, Work Done by	National-Acme Mfg. Co., Automatic Screw Machine	Mailet Compound Locomotive. 0-6-6-0, D. N. & P. Ry
Bullard Vertical Turret Lathe, Work Done by	National-Acme Mfg. Co., Automatic Screw Machine	Mailet Compound Locomotive. 0-6-6-0, D. N. & P. Ry
Bullard Vertical Turret Lathe, Work Done by	National-Acme Mfg. Co., Automatic Screw Machine	Mailet Compound Locomotive. 0-6-6-0, D. N. & P. Ry
Bullard Vertical Turret Lathe, Work Done by	National-Acme Mfg. Co., Automatic Screw Machine	Mailet Compound Locomotive. 0-6-6-0, D. N. & P. Ry
Bullard Vertical Turret Lathe, Work Done by	National-Acme Mfg. Co., Automatic Screw Machine	Mailet Compound Locomotive. 0-6-6-0, D. N. & P. Ry
Bullard Vertical Turret Lathe, Work Done by	National-Acme Mfg. Co., Automatic Screw Machine	Mailet Compound Locomotive. 0-6-6-0, D. N. & P. Ry
Bullard Vertical Turret Lathe, Work Done by	National-Acme Mfg. Co., Automatic Screw Machine	Mailet Compound Locomotive. 0-6-6-0, D. N. & P. Ry
Bullard Vertical Turret Lathe, Work Done by	National-Acme Mfg. Co., Automatic Screw Machine	Woodworker, Hamilton Universal. 342* Mailet Compound Locomotive. 0-6-6-0, D. N. & P. Ry. 61* 2-6-6-0, Va. Ry. 261* 357* 2-6-6-2, Narrow Gauge, Ingenio Angelina 2-8-8-2. 367* 2-6-6-2, Narrow Gauge, Ingenio Angelina 2-8-8-2. 367* 2-8-8-2, Son Pac. Co. 16*, 22\$, 367* 4-4-6-2, Santa Fe. 17*, 22\$, 475* Design of 199\$ Editorial Comment 14*, 22\$ Front Truck on. 14 Service Results on the Gt. Nor. Ry. 17, 22\$ So. Pac. Co. 181*, 199\$ Tabular Comparison 275 Weight, Distribution of 51* Manufacture, Should the Railroads 146 Marshall, W. H., The Equipment Industries and Railroad Prosperity 471 M. C. B. Association, Officers of 289*, 324* M. C. B. Association, President's Address 289 M. C. B. Association, Revision of Standards and Recommended Practice 297 M. C. B. Repair Card, Abuse of 39, 229, 336 M. C. B. Repair Card, Standard 33* M. M. Association, Officers o
Bullard Vertical Turret Lathe, Work Done by	National-Acme Mfg. Co., Automatic Screw Machine	Mailet Compound Locomotive. 0-6-6-0, D. N. & P. Ry
Bullard Vertical Turret Lathe, Work Done by	National-Acme Mfg. Co., Automatic Screw Machine	Mailet Compound Locomotive. 0-6-6-0, D. N. & P. Ry

Michigan Central Ry., Ash Pan for Six Wneel Switcher	Official, Broadening the Viewpoint of an Official, Principles Underlying the Work of a		Forging Coupler Yoke Fillers	129*
Puget Sound Ry	Successful Oil Barrels, Device for Elevating Oil Burning Loca, 2-8-8-2 So Pac Co 181*	10*	Maintenance and Repair of Steel Freight Cars at Altoona Mechanical Stoker	81*
Mikado Type Loco., Va. Ry	Oil Burning Loco., 2-8-8-2, So. Pac. Co.181*, Oil Burning Locomotives, Design of1, 22\$, Oil Burning Locos., Santa Fe	1111	Motor Car, Gasoline "Pennsylvania Special," Record of	460*
Milling, Boring and Drilling Machine, Hori-	Oil Burning Locos., So. PacOil Burning Locomotives, Through Adiron-	181*	Preparing Packing Leathers for Air Brake Cylinders	
zontal	dack Forests Oil for Freight Car Journal Boxes	4458	Statistics Steel Car for Carrying Plate Glass	197
Blades	Oil Furnaces for R. R. Shops174*, Oil Houses Oil Measuring Cup	417t	Steel Coke Car, Four-Hopper Steel Combination Passenger and Bag-	
Milling Machine, Heavy Plain	Oliver Machinery Co., Universal Saw Bench Olsen & Co., Tinius, 10,000,000 lb. Testing	262*	gage Car , Steel Freight Cars, Number and General	
Milling Machines, Horizontal	Machine O'Neil, J. B., Metal Grain Door	102 31*	Dimensions Stockholders Surprise Tests on	337
Milling Machine, Vertical	Operating Official, The Mechanical Official as a Successful	2418	Train Between New York and St. Louis Tunnels at New York	4611
Mine Rescue Station, University of Ill 149 Mineral Production in the U. S 129 Mines, Loss of Life in Coal 176	Ore Car, Summers, Air Operated Drop Doors Ore Cars, Summers, Good Work of4448, Ore Car, Summers', Duluth & Iron Range	461†	Performance Records, Loco	236
Mining, Wastes in	D D	375†	Permanent Instructions	219
Morrison, C. J., Design of Milling Cutters 136 Morrison, C. J., Efficiency of Files 487 Morrison, C. J., Tests of Staybolt Threads 433	Organization of Car Department, P. R. R Organization, Efficient	2405	383, 423, 463, Philadelphia & Reading Ry., 3-Cylinder Sim-	502*
Motive Power Official (see Mechanical Department Official).	Organization, Efficiency of Organization, A Successful	224† 217	ple Loco	4594
Motor Application to Geared Head High Speed Lathe 177 Motor Cars 317	Organization, Unit System of on Harriman Lines Oxy-Acetylene Welding	4458 628	Loco., Fast Run on the New York Branch "Phoenix" Smoke Jacks	473
Motor Car, Gas-Electric, So. Ry	Oxy-Acetylene Welding and Cutting Machine,	84*	Photographing Machinery	1351
Motor Cars on the Rock Island	Oxy-Acetylene Welding of Fireboxes Oxy-Acetylene Welding for Firebox Repairs.	378	Piece Work on Steel Car Repairs Pin Work, Locomotive, Machine Tools Re-	
Motor Cars on the Union Pacific	Oxy-Acetylene Welding, Flux for	393†	quired for	2624
Moulding Grease for Driving Boxes 144 Moulding Packing Rings	P		Pipe Fittings, Cast Iron, Effect of Superheated Steam on	177
Moulding Packing Rings	Pacific Type Loco., Chicago & Alton Ry	268* 376*	Pipe Taps, Power Required to Drive Piston Rods, Machine Tools Required for	355
Murray, W. S., Results of Electrification of the N. Y. N. H. & H. R. R	Pacific Type Loco., Gt. Nor. Ry	413* 194*	Piston Thrusts, Table of	103
Mussey, Wm. H., Semi-Elliptic Spring Data. 59	Pacific Type Loco., Chicago & Alton Ry Pacific Type Loco., G. B. & O Pacific Type Loco., Gt. Nor. Ry Pacific Type Loco., Tor. Pac. Ry. Pacific Type Loco., Tor. Pac. Ry. Pacific Type Loco., Tor. Pac. Ry. Pacific Type Loco., Western Ry. of France. Packing Leathers for Air Brake Cylinders, Preparing	276 26*	I. & P. Ry	469
N .	Preparing		Fe Piston Valve Packing, Gt. Nor. Loco	479
Narrow Gauge Mallet Locomotive, Ingenio Angelina	Packing Dings Machining on Vertical Turnet		Piston Valves, Are By-Pass Valves Necessary With	
Nashville, Chattanooga & St. Louis Ry., Balanced Compound Passenger Loco	Packing Rings Moulding	135*	Pistons, Machine Tools Required for Pit Jack, Hydro-Pneumatic Pittsburgh & Lake Erie R. R., Labor and	459
Nashville, Chattanooga & St. Louis Ry., Shallow Ash Pan With Longitudinal Sliding	Paint Spraying Machine, P. R. R.	157	Time Saving Devices in the Roundhouse Pittsburgh & Lake Erie R. R., Moulding	141
Doors	Painting Steel Cars	293 101*	Packing Rings Pittsburg Plate Glass Co., Steel Car for Carrying Plate Glass.	135
National Tube Company, Tube Data139, 192 Nelson, E. D., Bank vs. Level Firing 318	"Paragon" Flat Twisted Drills	343*	rying Plate Glass Pittsburgh, Railway Club of,	231
New England Railroad Club, 25, 65, 113, 152, 209, 237, 422, 462, 486	Passenger Agents, Enginemen as	487†	25, 65, 113, 153, 209, 422, 462, Piston Heads, Machining on Vertical Turret	
Newhall Engng. Co., Air Brake and Signal Hose Connection		4477	Lathe Piston Valve, American Semi-Plug Planer Drive, Two Speed	117
Newton Cold Saw Cutting-off Machine 456 Newton 3-Spindle Horizontal Drilling Ma- chine	Steel	131÷	Planer for Loco. Cylinders, Cincinnati Planer, Plate, for Loco. Boiler Shop	73
Newton Vertical Milling Machine 212 New York Central Lines Apprentice Instruc-	Steel, Common Standard	252†	Planer Records, Good	370
tors' Conference, Abstract of Proceedings,	Steel, Design	434*	Planer Type Milling Machine	161
New York Central Lines Apprenticeship, Notes	Steel, Painting Steel, Seat Arms and Window Sills on	273†	Plate Glass, Steel Car for Carrying Plymouth Cordage Co., Compressed Air Trac-	
New York Central Lines Electric Loco., Detroit River Tunnel	Steel Suburban, Long Island R. R Steel Underframe, C. R. R. of N. J Suburban, Steel, Long Island R. R	488*	Pneumatic Dispatch Tube at Engine House Pneumatic Drill Testing Machine	72
New York Central & Hudson River R. R., East Buffalo Roundhouse			Pneumatic Gasket Cutter	143
New York Leather Belting Co., Victor-Balata Belting	Passenger Locomotive.		Pomeroy, L. R., Mallet Comp. vs. Electric	150
N. Y. N. H. & H. R. R. Electric Locomotive, Results of	2-6-3, Tabular Comparison	276 277	Pomeroy, L. R., A Study of the Number and	
New York, New Haven & Hartford R. R., Electric Freight Loco	P. Ry.	467*	Kind of Machine Tools Required in a Railway Locomotive Machine and Boiler Shop,	
New York, New Haven & Hartford R. R., Results of Electrification of	4-4-2, Nor. Pac. Ry	195* 478*	Pomeroy, L. R., On Superheaters	288
25, 65, 113, 153, 209, 355, 492, 462, 486 New York, Pennsylvania Tunnels at 379	Reading Ry.	459*	Pop Valves, Steam Wasted Through	315
Niles-Bement-Pond Co., Extra Heavy Rod	the P. & R		Portable Air Motor Testing Machine Portable Drilling Apparatus	355
Milling Machine	KV.	52*	Portable Heaters	
Niles-Bement-Pond Turret Lathe for Pin	4-6-2, Chicago & Alton Ry	268*	pound Air Pumps Portable Oxy-Acetylene Welding and Cutting	g
Work Noiseless Gears Norfolk & Western Ry., 50-Ton Steel Gon-	4-6-2, C. B. & O	413*	Machine Portable Rivet Heater Portable Rivet Heating Furnace	97
dola Car	4-6-2, Tabular Comparison276,	277	Portable Vise Bench	141
Northern Pacific Ry., 50-Ton Steel Gondola	4-4-6-2, Santa Fe	475*	"Positive" Water Glass Guard Powell, R. C., Portable Air Motor Testing	382
Car 251 Northern Pacific Ry., Hopper Type Ash Pan	Passenger Travel, Safety of	263†	Machine Power Brakes on Trains, Percentage of Power House for New Haven Electrification,	258
With Sliding Doors	Paxson, Levi B., Obituary Notice	215	Results of	27
Type Locos	Pedestal Binders, Device for Pulling Down	141*	Power Plant, Depreciation of	185
Norton Grinding Co., Car Wheel Grinder 208 Nut Locks, Bartley	Pennsylvania Lines West, Locomotives for Pennsylvania Railroad.	4957	Prairie Type Locos., Tabular Comparison Pratt & Whitney "Highpower" Drill	276 419
Nut Locks on Trucks	Car Wheel Grinder	208*	Pratt & Whitney Turret Head Bolt Cutter Prentice Bros. Co., High Speed Lathe, Motor	
0	Cleaning and Repairing Triple Valves Electric Locomotives261†,	158* 490*	Press, 1500-Ton Press, Forcing	91
Oesterlein Machine Co., Universal Cutter	Electrification, Direct Current Fires on Property of	497†	Press, Forcing	483
Grinder 116			Pressures in the Metric System	176

Principles Wrongly Applied, Good	3125	Running Board Brackets, Former for Forging	210*	Smoke Box Doors, Lancashire & Yorkshire	
Process for Squaring Mentally		Rupert, J. W., Welding Boiler Tubes to the Tube Sheet	254+	Ry Smoke Box for Lignite Burning Engines	409
Protection of Railroad Men	135†	Rutland Ry., Welding Locomotive Frames	453*	Smoke Box Tor Lightle Burning Engines Smoke Box Temperatures With Superheated	391*
Public Opinion and Harriman Lines		c		and Saturated Steam221*, 283,	284
Public and the Railroads, The	299†	S		Smoke Box, Tests of on the Lancashire & Yorkshire Ry.	408*
Publicity of Railroad Accidents	288†	Safety Appliances, Report of Committee on		Smoke Box, Virginian Mallet Loco	357*
Pumps (see Air Pumps). Punch and Shear, Royersford	342*	Safety League, Canadian Pacific Ry Safety, Museum of		Smoke, Burning Briquets	
Punching Machines Required in Loco. Boiler	107	Safety of Passenger Travel263†, 443†,	446†	Smoke Jacks, "Phoenix" Smoke Prevention in Locomotive Operation	5*
Shop	121	Safety Valve Capacity	162* 822	Smoke Stack and Deflector, 2-8-8-2 Loco., So.	4097
Q		Safety Valves, Steam Wasted Through	315	Pac. Co	368*
Quayle, Robert, On Fuel Economy	216	St. Louis Railway Club, 25, 65, 113, 153, 209, 237, 422, 462,	497	Smokeless Combustion	205†
Quayle, Robert, On Superheaters	287	Salt Water Drippings from Refrigerator Cars	292	Socket (see Drill Socket).	
Queen City Machine Tool Co., Boring Jigs in the Manufacture of Shapers	118*	Sand Boxes, Repairing in Roundhouse Sand House, East Buffalo Roundhouse	141*	Soule, Richard H., Obituary Notice Southern & Southwestern Ry. Club,	42
Queen City Machine Tool Co., Shaper Tests.	171*	Sanitation, Museum of	203†	65, 209, 422,	462
R		Santa Fe, Atlantic Type Locomotive Santa Fe, Mallet Comp. Freight Loco.		Southern Pacific Mallet Comp. Loco., 16*, 22\$, 181*, 199\$,	367*
		(2-8-8-2)	477*	Southern Ry., Gas-Electric Motor Cars	495
Rack for Flues	351*	Santa Fe, Mallet Comp. Passenger Loco. (4-4-6-2)	475*	Souvenirs at the Conventions	255
Radial Drill, Sensitive	458*	Santa Fe Type Loco., Data	275	Splicing Center Sills	291*
Radical Angular Drill & Tool Co., Device for	00#	Saturated Steam, What It Is	220	Spring and Brake Rigging, Loco., Machine Tools Required for	124
Boring Square Holes	288†	Saw, Cut-off for Flues, Abrasion	351*	Springfield Machine Tool Co., Machine for	
Railroad Clubs, Are They Worth While? Railroad Clubs, Co-operation With the M. M.	64	Saw, Cut-off, Heavy Automatic	421*	Spring Hanger, Dies and Former for Forging	173*
Association	266	Saw, Friction, Metal	377†	Spring Steel, Heat Treatment of	492*
Railroad Club Notes, 25, 65, 113, 152, 209, 237, 365§, 422, 462,	487	Saw Mill, Large	13†	Springs, Helical, Design of	59
Railroad Club Statistics	278†	Pac. Ry	197*	Square Holes, Boring	38*
Railroad Club, The Value of		Schmidt Superheaters, Number of Locos. Equipped With	10+	Squaring Mentally, Process for Stack, Diamond, for Burning Lignite	391*
Railroad Employees' and Investors' Associa-	2001	Schneider, Prof. Herman	.1998	Standard Allowances	217
Railroad Employees and the Public	145	Schneider, Prof. Herman, Industrial Educa-	3128	Standard Costs or Allowances Standard Tool Co., Circular Shank for Drills	178*
Railroad Fatalities Show Marked Decrease	483	Scranton Shops, D. L. & W. Ry., Machine		Standard Tool Co., Circular Shank for Drills Standard Tool Co., "Economy" Sockets and	70
Railroads, Fulton Bill Dangerous to	66	Tools for the Locomotive Machine and Boiler Shops	1508	Standardization of Locomotive Supplies	54
134*, 150§, 185,		Screw Machine, Multiple Spindle, Automatic.	300*	Standardization Need Not Check Progress Standardization, Practical Benefits from	299†
Railroad Men, Best Means of Training Railroad Outlook Improving		Seat Arms in Steel Pass. Cars	2737	Standards, Revision of M. M. Association "Stantool" Shank for Drills	281
Railroad Prosperity and the Equipment Inter-		20,	23§	"Stantool" Shank for Drills Statistics, Records of	178*
ests Railroad Regulation		Seley, C. A., Superheater Tests on the Rock Island	281	Staybolts, Flexible322,	389†
Railroad Service, College Men in	176	Sellers Car Wheel Lathe	340*	Staybolts, Flexible, A Criticism Staybolts, Flexible, Applying	4941
Railroad Y. M. C. A	403†	Semi-Elliptical Springs, Design of	458*	Staybolts, Flexible, A New Departure in	190*
Railroads and the Public	213†	Setting Valves (see Valves, Setting).	166*	Staybolt Nipper, Pneumatic Staybolts, Machine Tools Required for	178*
Railroads, Should They Manufacture	146 47	Shaper, Back Geared Crank112*, Shapers, Boring Jigs in the Manufacture of	118*	Staybolt Threads, Test of	433*
Railroads Want Fair Treatment	149‡	Shaper Tests	171*	Stays (see Boiler Stays). Steam, Action of in a Locomotive	220
Railway Appliances Exhibition, A. R. E. & M. of W. Assn	119	Shear, Gate, 125-Inch	88*	Steam Chests, Machine Tools Required for	123
Railway Business Association238, 24, 66, Railway Business Assn. Dinner	461	Shear and Punch	842*	Steam Drop Hammer	
Railway Business Association, Inside View 1		Shop	127	Steam Per I. H. P., Saturated Steam Per I. H. P., Superheated	283
Railway Business Assn., Mr. Marshall's Address at the Annual Dinner	471	Shellov Seamless Steel Tubing, Data Concerning	192*	Steam Pipes Between Cylinders and Saddle Casting, 2-8-2 Loco., Va. Ry	200
Railway Business Association Statement	151	Shimer High Speed Steel Cutters for Surfac- ing	78*	Casting, 2-8-2 Loco., Va. Ry	227*
Railway Business Association, Work of 8 Railway Club of Pittsburgh,	313	Shimer & Sons, Samuel J., High Speed Steel		Steam, Saturated, What It Is	
25, 65, 113, 153, 209, 422,	462	Cutters for Woodworking	363† 191†	Steam, Superheated (see Superheated Steam). Steam, What Is it?	53†
Railway and Engineering Review, A Good Convention Issue	302†	Shoes and Wedges, Machine Tools Required		Steel, Alloy	638
Railway and Engineering Review, Daily at A. R. E. & M. W. Assn	178÷	for		Steel Car for Carrying Plate Glass Steel Car Repairs	174*
R. E. & M. W. Assn	1101			Steel Car Wheels, Design of	324*
Meeting of	233	Shop.		Steel Freight Car, Coke, Four Hopper, P. R. R.	187*
Railway Materials Co. Furnaces	133†	Blacksmith, Idaho & Washington Nor.	157*	Steel Freight Car, Gondola, 50-Ton Steel,	250*
Railway Storekeepers' Convention	2617	Boiler, Machine Tools Required in121,	1508	Denver & Rio Grande Steel Freight Car, Gondola, 50-Ton Steel,	200
Records, Graphical 2	236*	Car, Beech Grove			252*
Records, Individual Efficiency		Car, Idaho & Washington Nor. Ry	154*		251*
Refrigerator Cars, Salt Water Drippings from a Regulation of Railroads	193†	Car, Steel Freight, Altoona Coach and Paint, Idaho & Washington	87"	Steel Freight Car, Gondola, 50-Ton, Norfolk	349*
Reheater, Santa Fe Mallet Comp. Locos 4 Reheater, So. Pac. Mallet Comp. Locos 1	169*	Nor. Ry	157	Steel Freight Car, Gondola, 50-Ton, Virgin-	
Reilly, T. S., Obituary Notice	20	Efficiency, Building Up		ian Ry	395*
Repair Card, Abuse of the M. C. B. 39, 229, 3 Repair Card, Freight Car, P. R. R	93*	Erecting and Machine, Idaho & Washington Nor. Ry		Steel Freight Car, Hopper, Summers	49*
Repair Card, M. C. B. Standard 8	337*	Erecting, Lighting of	298*	Steel Freight Cars, Ore, Summers, Air Operated Drop Doors on	360*
Reversing Gear, 2-8-8-2 Loco, So. Pac. Co 3	19	Freight Car, P. R. R			000
Richmond Railroad Club,		Lighting of	298*	Steel Freight Cars, Maintenance and Repair of at Altoona, Penn-	
25, 153, 209, 422, 462, 4 Riegel, S. S., Comparative Tests of Water	187	Locomotive and Car, Beech Grove Locomotive, Idaho & Washington Nor.	133*	sylvania Railroad.	
Tube and Standard Fireboxes 2		Ry	154*	All-Steel Cars, Number and General Di-	
Ritter Folding Doors for Roundhouses 2		Machine, East Buffalo Roundhouse Machine and Erecting, Peech Grove	133*	Blacksmith Shop, Straightening Damaged	84
Rivet Heater, Portable,	97*	Machine and Erecting, Idaho & Washington Nor. Ry		Parts for Steel Cars	100*
Road Foreman of Engines, A Bonus Sched-		Machine, Lighting of	298*	Body Bolster Reinforced on Steel Hopper Cars	99*
ule for		Machine, Machine Tools Required in 121, Operation, Comparative Cost of		Bolt for Drawing Up Parts Car Equipment on Pennsylvania R. R	91 83
Rock Island 4-Cylinder Simple Loco. With		Surgeon		Cars Repaired at Altoona, Number of	87
Superheater		Telephone System		Car Shop, Steel	87* 90*
Rock Island System, Tests of Superheaters		Side Bearings on Tender Trucks, Location of,		Center Sills, Splicing of	90*
on Rocker Arm and Support, 4-6-2 Loco., C. B.		Side Sheets, Firebox, Life of20,		Center Sills, Splicing on Steel Hopper Cars	97*
& Q 3	77*	Side Sheets on Wide Fireboxes, Failure of	70*	Classification of Freight Cars	85
Rod Brasses, Machine Tools Required for 1 Rod Brasses, Machining on Vertical Turret		Signal Blades, Gold Leaf for	10† 78†	Coupler Yokes, Method of Riveting to	86
Lathe 2		Sills (see Center Sills).		Couplers	91
Rod Milling Machine	22	Sills, Splicing of Wooden	138	Cranes, Locomotive, for Freight Car Repair Yard	99*
Rogers, R. H., Flange Wear on Driving Tires 2 Roller Bearings	19†	Slipping Point of Rolled Boiler Tube Joints, 3648,		Drawbar Yokes, Method of Riveting to Couplers	91
Rolls Required in Loco. Boiler Shop 1	26	Sloat, H. M., Weight Distribution of Mallet		East Bound Repair Yard	99*
Roundhouse (see Engine House). Round Iron, Weights of	61	Articulated Locos	51*	End Sills, Reinforcing on Steel Hopper	96*
Royersford Motor Driven Punch and Shear 8		Rv	427*	Freight Car Shop	100

Heaters for Steel Car Repairs. Hopper Car Cross Ties. Indestructibility of Steel Cars. Introductory Jacks, Pulling and Pushing, for Steel Car Repairs. Life of Steel Cars. Locomotive Cranes for Freight Car Repair Yard Number of All-Steel Freight Cars. Number of Cars Repaired at Altoona. Number of Steel Underframe Freight Cars. Organization of Car Department. Paint Spraying Machine. Paint Spraying Machine. Paint Spraying Machine. Piece Work for Steel Car Repairs. Pneumatic Drills, A Simple Device Used in Connection With. Poof, P. R. R. Freight Car. Press, 1500-Ton, Chambersburg. Press for Straightening Damaged Parts of Steel Cars. 94°, 1 Repair Card for Steel Car Repairs. Repairs, How Made Repairs, How Made Repair Yards, Altoona Repair Yards, Altoona Repair Yards, East Bound.	101* 101* 93* 95* 86 97* 91* 100* 93* 92* 91* 81* 99*	Fire Tube, Cost of Maintenance. Fire Tube vs. Smoke Box. Fire Tube, Wabash-Pittsburgh Terminal Ry. Great Northern Ry. Jacobs Relative Cost of Smoke Box and Fire Tube Results from on the Rock Island. Scamidt, 4-4-2 Loco., Nor. Pac. Ry. Schmidt, Number of Locos. Equipped With Superheaters Tubes, Life of. Supplies, Locomotive (see Loco. Supplies). Supplyman, His Position and Influence. Supplyman, The Surfacing, High Speed Steel Cutters for. Surgeon, The Shop. Switching Locos., 0-6-0, Data. Switching Locos., 0-8-0, Data. Switching Locos., 0-8-0, Va. Ry. Switching Loco., 0-8-0, Western Ry. of Havana Switching Locos., 0-10-0, Data. Switching Locos., Tabular Comparison.	256* 413* 481* 222 197* 10† 281 222 485§ 311† 78* 311† 375 359* 310*	Truck, 6-Wheel for 12,000 Gal. Tender, Santa Fe Truck, Tender Truck, Tender, Location of Side Bearings on, 232*, Truck, Trailer (see Trailer Truck). Truck, Virginian Mallet Loco Truck Work, Engine and Tender, Machine Tools Required for. Tubes. Abrasion Cut-off Saw for. Area of Inside Surface Collapsing Pressures Copper Safe-Ends for. Cubic Capacity of. Engineering Data Concerning. 139, Joints, The Slipping Point of Rolled Boiler	351 124 351 133 183 193 370 222 126 350 351 78 193 135 354
Repair Yard, West Bound	97*		200	Tube Work, Machine Tools Required for Tunnels at New York City, P. R. R	279
Shop, Freight Car	84 97* 00* 95*	Tank Cars 3 Tank, How to Repair Leaky Gasoline 3 Tank Switch, Automatic 3 Tapping Holes in Boiler 4 Tapping Pipes, Power Required for 8 Tate, Jones & Co., Kirkwood Down Flame 4 Tate, Jones & Co., Oil Furnaces 4 Tate, Jones & Co., Oil Furnaces 8 Taylor, Wm. H., High Speed Milling Cutters With Inserted Blades 3 Team Work 10†, 2 Technical Publicity Association 14	350† 381* 433* 355 460* 341* 808* 218 462†	Turner, L. H., On Apprenticeship	386 76 9 8 262 260 34 275 20,
Car Parts	93*	Telephone Train Dispatching 4 Telephones or Calling Enginemen	18†	U	
Torch for Heating Damaged Parts of Steel Cars	95* 99* 92* 85* 99* 92* 81* 93 31† 73*	Ten-Wheel Loco., Tabular Comparison 275, 2 Tender, 12,000 Gallon, Santa Fe. 4 Fender Derailments 3 Tender Trucks 3 Tender Truck, 6-Wheel, for 12,000 Gal. Tender, Santa Fe. 4 Yender Trucks, Location of Side Bearings cn, 4	93† 52* 77* 16 16 79*	Underwood Universal Boring, Turning and Facing Machine Union, Kewanee Union Pacific Educational Bureau of Information Union Pacific, Motor Cars on Union Railroad Steel Hopper Car, Summers' Universal Saw Bench University of Cincinnati, Co-operative Engineering Courses "Use-Em-Up" Drill Socket.	392 317 49 262
Steel Passenger Cars, Common Standard 28 Steel Passenger Car Design198§, 43	52†	Testing Locomotive Fuel	96	v	
steel Passenger Cars, Inside Lining of	03 71† 73†	Festing Machine for Air Motors	41* 02 67* 59*	Valve Chamber Bushings, Hydraulic Press for Valve Ellipses, Baker Pilliod	821
steel, Spring, Heat Treatment of	12* 11‡ 64\$ 37 9* 57 97* 61† 11*	Three-Cylinder Simple Loco., Fast Run on the Philadelphia & Reading. 47 Throttle Rigging, Machine Tools Required for	24 97* 89 83 18† 48*	Valve Gear, Baker-Pilliod, 4-6-2 Loco., Chicago & Alton Ry. Valve Gear, Joy (see Joy Valve Gear). Valve Gear Link Grinders	268 ⁴ 30 ⁴ 123
steel, Spring, Heat Treatment of	12* 11‡ 64\$ 87 9* 57 97* 61† 11*	the Philadelphia & Reading. 4' Throttle Rigging, Machine Tools Required for 1' lickell, W. D., Pivoted Equalizer Stand. 4' l'illotson Bequest 279, 3' l'imber Decay Costs Millions 4' l'imber Waste 1' l'ires, Driving, Flange Wear on 28' l'ires, Machine Tools Required for 1' l'ires, Machine Tools Required for 1' l'ires, Renewal of on the Lancashire & York-	24 97* 89 83 18† 48*	Valve Gear, Baker-Pilliod, 4-6-2 Loco., Chicago & Alton Ry	30° 123 430°
steel, Spring, Heat Treatment of	12* 11: 645 37 9* 57 90* 11: 43* 43* 43* 44: 69* 44: 610*	the Philadelphia & Reading. Throttle Rigging, Machine Tools Required for	24 97* 89 83 13† 48* 22 07 08 32* 41* 20* 26 93* 93*	Valve Gear, Baker-Pilliod, 4-6-2 Loco., Chicago & Alton Ry. Valve Gear, Joy (see Joy Valve Gear). Valve Gear Link Grinders. Valve Gear, Machine Tools Required for Valve Gear, Walschaert (see Walschaert Valve Gear). Valve Rod Extension, 2-8-0 Loco., C. P. Ry. Valve, Safety (see Safety Valve). Valve Stetting Apparatus, Care of in Roundhouse Valve Stetting Apparatus, Care of in Roundhouse Valve, Triple (see Triple Valve). Valves, Machine Tools Required for Valves, Setting With Walschaert Gear Vanadium Steel for Forging Dies Van Arsdale, Robert M	268° 30° 123° 430° 143° 56° 128° 497° 484° 115° 22°
steel, Spring, Heat Treatment of	12* 11: 11: 12: 13: 14: 15: 16: 16: 16: 16: 16: 16: 16: 16: 16: 16	the Philadelphia & Reading. Throttle Rigging, Machine Tools Required for	24 97* 89 18† 48* 20 07 08 32* 41* 20* 93* 93* 93* 95; 61†	Valve Gear, Baker-Pilliod, 4-6-2 Loco., Chicago & Alton Ry	268° 30° 123 430° 143° 56° 128° 497 484° 115° 22° 1149° 45°
steel, Spring, Heat Treatment of	12* 11148 37* 57* 57* 69* 69* 69* 69* 69* 69* 69* 69* 69* 69	the Philadelphia & Reading. Throttle Rigging, Machine Tools Required for	24 97* 983 18† 422 07 08 32* 420* 26 93* 93* 555* 64† 772 638 638 638 638 638 638 638 638	Valve Gear, Baker-Pilliod, 4-6-2 Loco., Chicago & Alton Ry	268' 30' 123' 430' 143' 56' 128' 497 484 115' 22! 405! 318' 405! 318' 4168' 280' 4168' 280' 4168' 280' 4168' 4168' 4168' 4168' 4168' 4168' 4168' 4168'

Von Schrenck, Hermann, The Handling of Lumber in the Yard	Weighing Coal for Locomotives. Weight Distribution of Mallet Articulated Loco. Weight of Superheated Steam. Weights of Round Iron. Welding Boiler Tubes to the Tube Sheet. Welding Grieboxes by Oxy-Acetylene. Welding Locomotive Frames, Rutland Ry Welding Locomotive Frames, Rutland Ry Welding With Oxy-Acetylene Methods. Welding With Oxy-Acetylene Methods. Welfare Work Among Workmen. West, Geo. W., Obituary Notice. Western Canada Railway Club, 114, 153, 209, 237, 422, 462, Western Electric Co., Shop Telephone System Western Railway Club, 25, 66, 113, 153, 209, 422, 462, Western Ry. of France, Bal. Comp. 4-6-2 Loco. Western Ry. of France, Increasing the Life of Loco. Crank Axles. Western Railway of Havana, Eight-Wheel Switching Loco. Westinghouse Electric Freight Loco., N. Y. N. H. & H. R. Westinghouse Electric Locomotive. Westinghouse Electric Locomotive. Westinghouse Graphic Recording Wattmeter. Wheels, Car. Wheels, Car. Wheels, Car. Wheels, Gauges for. Wheels, Gauges for. Wheels, Garaphical Record of Pressures in Pressing on	459* Whitworth Thread for Staybolts
Watson-Stillman Co., Forcing Press 209 Watson-Stillman Hydraulic Coping Machine. 381	Pressing on Wheels, Grinding Car	
THE PAGE NUMBERS	FOR THE DIFFERENT MONTHS OF THE Y	EAR 1909 ARE AS FOLLOWS:
January 1-4 February 45-8 March 81-12	June	7-264 October
April 121-18		







DESIGN OF OIL BURNING LOCOMOTIVES.

HARRINGTON EMERSON.

A locomotive is an apparatus in which the heat evolved by the combustion of carbon, hydrogen and sulphur with oxygen is transferred to water in an enclosed receptacle, the water being converted into steam under pressure, which by its pressure and expansion drives the steam engine.

To a coal-burning locomotive there are two principal limitations:

(1) The ability of the draft arrangements to furnish sufficient air for combustion.

(2) The ability of the fireman to feed coal properly.

Draft.—The draft is created by the escape of steam. Exhaust steam is preferably used and the more work it does in making draft, the greater the back pressure. If live steam is used, to that extent the steam available for the engine cylinder is curtailed. It is evident that with very little draft there will be very little combustion and consequently very little available steam. If, however, all the steam is used to create a draft there will be none left over for power purposes. The problem, therefore, is to obtain the maximum of draft without using too much of the steam for this purpose. Of the power used for draft, one-third is consumed in drawing the air through the bed of coals, one-third in drawing the air through the tubes and onethird in the resistance in the front end, diaphragm, etc. Dratt, therefore, could be very much increased if there were no bed of coals, if there were no diaphragm and if tubes were larger, fewer and shorter.

The Fireman.—There is a limit to the ability of the fireman:

- (1) To shovel coal.
- (2) To shovel coal so as to reach the further parts of a large grate.
 - (3) To shovel coal so as to maintain an even bed of fire.

Even when the fireman shovels coal perfectly, if the furnace, the tubes and the front end are not of proper design, the results will fall off

The draft is often so strong as to lift the bed of coals from the grate and to plug the small flues with big cinders. Very small flues would not do.

The combustion space above the bed of coals must be large enough to complete the combustion of the coal before the gases enter the tubes.

Perhaps the chief faults in the design of the large modern coal-burning locomotives are:

- (1) The tubes have been unnecessarily lengthened beyond the length of maximum result, 13 feet.
- (2) The fire box has not been enlarged sufficiently to provide an ample combustion chamber.

Nevertheless, modern coal-burning locomotives, both in Europe and America, are well designed and efficient power generators.

When it comes to oil-burning locomotives, every principle of correct power generation has been violated. Oil burning locomotives were not specially designed for oil, but are in fact nothing but coal burners with an oil-spraying nozzle substituted for the grate. It stands to reason that designs and dimensions suited for coal are not suitable for oil. The sole excuse for using a coal-burning furnace and boiler design for oil is that it seems economical to put an oil nozzle in a fire box and to call the locomotive an oil burner. Also when oil-becomes scarce it seems cheap to remove the nozzle, put back a grate and rechristen the locomotive a coal burner.

When, however, it is considered that a coal-burning fire box may last from 8 to 15 years, and the same fire box racked by oil

combustion will last only from I to 5 years, and must then be renewed at a cost of from \$2,000 to \$5,000, the economy of adaptation proves fallacious, especially as a suitably designed oil furnace and boiler would not prove as inefficient for coal, as a coal furnace is for oil.

The particular limitations which apply to coal burning apparatus do not apply to oil:

- (1) Because the oil is pumped in or injected, the limit of the fireman's strength or skill is eliminated.
- (2) The limit to the amount of fuel is the amount of air that can be supplied.
- (3) As there is no bed of coals through which to draw the air, this source of friction falls away.
- (4) As there is no need of a diaphragm or screen to catch cinders, the front end friction is also reduced.
- (5) As a consequence of reduced friction a very much larger volume of air can be furnished for combustion than in a coal
- (6) This larger volume of combustion requires a larger combustion chamber.
- (7) With coal burners the gases enter the tubes at a temperature of about 1,300 degrees F., which 13 to 20 feet away drops to 500 degrees F.
- (8) In modern oil burners the temperature of the gases is 2,800 degrees as they enter the tubes. This high heat enormously and rapidly damages the flue sheet and tube ends.
- (9) Temperature of escaping gases is no higher than in coal
- (10) Therefore in an oil burner more heat is transmitted through the fire box and through part of the tubes near the fire than in a coal burner.
- (II) As no cinders are dragged into the tubes to clog them up, tubes could be made much smaller in diameter, probably not over one-half inch.
- (12) Tubes could also be limited to the best length for maximum result, about 13 feet.
- (13) Many tubes are now 22 feet long. These might be shortened to 13 feet, thus making available 9 feet, a large part of which could be devoted to enlarging the combustion chamber, and the balance to a steam superheating or feed water heating device.
- (14) The water spaces around the fire box ought to be much larger and the 9 feet extra length available for combustion chamber will permit water spaces one foot in width without making combustion chamber too small.
- (15) With tubes one inch or less in diameter, although only 13 feet long, there will be more tube-heating surface than with tubes 22 feet long but 2½ inches in diameter.
- (16) These smaller tubes can be thinner and because the gases have been fully burned in the combustion chamber before reaching the tubes, there will be in operation less deposit of carbon. Carbon deposits are in any case removed by sand and more easily from small than from large tubes.
- (17) In consequence of lessened air friction, greater volume of air, unlimited oil supply, big combustion chamber, lower temperatures of gases entering tubes, big water spaces, greatly increased fire box heating surface and tube heating surface for same sized locomotive, the oil-burning combination could provide steam abundantly and economically as to fuel, and operate at low repair cost for furnace and boiler even in the largest Mallet compounds.

THE USE OF WOOD IN BUILDING CONSTRUCTION

Great as the advance in fireproof construction has been during the last ten years there has been no let-up in the use of lumber, and both architects and builders find themselves so dependent on wood to-day that they are compelled to admit that the forests of the country are likely to be the chief source of building material for many years to come.

"The use of cement, terra cotta, brick and stone, with a frame-work of steel, will make it possible soon to do away with wood entirely," is a remark often heard. As a matter of fact, the popular idea that fireproof materials will do away with the need of using lumber in a comparatively few years is a very erroneous one. All of the various fireproof materials going into the approved construction of the more substantial buildings are used in greater quantities now than the world dreamed of a few years ago, yet the heavy demand for lumber continues.


That wood predominates is shown by the annual building records. Of the permits used for buildings erected last year, approximately 61 per cent. were constructed of wood, and the remaining 39 per cent. of fire-resisting material, according to a report issued by the Geological Survey on operations in forty-nine leading cities of the country. These figures are the more significant when it is realized that they only represent the building activities in the largest cities; they do not take into account the construction of dwellings, stores and other buildings in the thousands of small cities and towns scattered over and not included in the forty-nine cities on which the reckoning is made.

In towns and small cities wood is usually the predominating building material and it is safe to say that if the statistics had included figures for all places of whatever size, the percentage of wooden construction would have been much greater.—From a report of the Forest Service of the U. S. Dept. of Agriculture.

The Importance of Knowing Costs Promptly.—The accounts showing what is actually spent each day must be in the hands of those in control as soon as possible after it is spent; not a month's nor a week's report at a time, but a day's report at a time, and it must be in the possession of the officer or man in charge of the expenditure as soon as possible. The section foreman must know at the close of to-day what he has spent to-day. The same is true of the shop foreman. The supervisor should know to-morrow what has been spent by his section foreman to-day.

At first thought it may seem that this would involve an immense amount of bookkeeping and complication of accounts, and consequently a large additional force of men. This, however, is not so. It does not involve the putting on of any additional men, as this daily check can be carried out by the present force without difficulty, as the necessary accounts are so simple and are kept by so many that it puts but little work on each, and in the larger offices, such as the division superintendents and master mechanics, it means but a consolidation of figures. This is no theoretical or fanciful scheme whatever, but is a definite practice which has been in actual operation for sufficient time to thoroughly demonstrate its practicability. It simply means system in expending the money for operating expenses and adapting to the railroac. business the same rules as to knowing and watching cost that apply to all other lines of business.-W. J. Harahan, before the New York Railroad Club.

FREEZING OF AIR BRAKE HOSE.—The reason that air brake hose gets hard in cold weather is generally due to freezing. If we could get some kind of rubber that would not freeze we would be very happy. Crude rubber will freeze at about 20 degrees F., and vulcanized rubber freezes at about zero. All rubber companies have experimented in different ways to prevent this, and they have added oils and all kinds of things that do not freeze so readily, but in this country the temperature gets so low that it frequently gets beyond us.—A. D. Thornton, general technical superintendent, Canadian Rubber Company, before the Canadian Kailway Club.



EAST BUFFALO ROUNDHOUSE.

NEW YORK CENTRAL & HUDSON RIVER RAHLROAD.

A new 30 stall roundhouse for passenger locomotives has recently been placed in operation by the New York Central & Hudson River Railroad at East Buffalo. It lies between the West Shore Railroad tracks and the Pullman Parlor Car Works, near the old 28 stall roundhouse of the West Shore Railroad.


General Arrangement.—As shown by the dotted lines on the general plan, provision has been made for the addition of a 50 stall roundhouse to meet future requirements; also for additional ash pits and water tanks and for the extension of the coaling station and the power plant.

Engines enter the plant from the east, on one of the incoming tracks, and take coal and sand, after which they move forward and take water and then move on to the ash pits. The coaling station is about 650 ft. from the turntable and the standpipes are a sufficient distance from the coaling station so that one engine may take water while another is coaling on the same track. Coal for the power house is brought in over the track at the north, the cars unloading into coal bins from a trestle. Coal for the

may be taken out at the western end over the track which separates the main portion of the engine house from that part containing the drop pits, machine shop and offices.

The Roundhouse.—The main portion of the roundhouse, consisting of 26 stalls, is divided by two fire walls, with steel fire doors, into three portions. The drop pit section contains three stalls, and the machine shop, which has a common wall with the drop pit section, has a pit which may be used for engines requiring light repairs. Two of the pits in the main portion of the house are equipped with a drop pit for engine truck wheels. The building has a depth of 90 ft., measured from center to center of the wall columns and the distance from the center of the turntable to the inner wall of the house is 130 ft. 134 in. The tracks radiate at an angle of 5 deg. 44 min. 52 sec. from the center of the turntable.

The foundation, pits and floor of the house are of concrete and the walls are of brick. The columns are of yellow pine, of the dimensions shown, and the roof trusses are of timber. The



CROSS-SECTION THROUGH THE DROP PIT SECTION OF THE ROUNDHOUSE.


coaling station is also brought in on the track at the north and may be stored on the three tracks just east of the roundhouse. These tracks are on an incline and, as the coal is needed, a car may be started down the grade with the aid of a pinch bar and be stopped over the hopper, into which it is dumped and from which it is elevated to the storage bins above the tracks. The sand, after being dried in the sand house, is elevated to storage tanks in the coaling plant by compressed air.

The tracks over which the coal and sand are brought in do not in any way interfere with the incoming and outgoing tracks for the engines; the only place where there is liable to be any interference is in connection with the cinder cars from the ash pit and this can readily be guarded against. Ordinarily the engines come in and go out at the eastern end of the plant but provision has been made so that in case of emergency engines

roof consists of 2 in timbers upon which "Special Brooks Brand" roofing, furnished by the H. W. Johns-Manville Cc., is laid.

The most noticeable feature of the house is the large amount of window space, which furnishes splendid day-lighting, and the amount of head room. The wall above the windows is supported by two 9 in. I beams, which extend crosswise above the windows. Wooden doors are used; they are held in an open position by bolts which fit in sockets in concrete piers, about 2 ft. square in section.


The cross-sectional view of the house shows a section through the drop pits. The pits in the main part of the house are 67 ft: 9½ in. long, extending to within 8 ft. ½ in. of the outer wall. They are 3 ft. 4 in. deep at the inner end and 2 ft. 8 in. deep at the outer end. A 15 in. jacking timber is placed alongside the rails of each pit.




PARTIAL VIEW OF THE END OF THE ROUNDHOUSE NEAREST THE COALING STATION


CINDER PIT TO THE RIGHT

COALING STATION.



CINDER PIT AND COALING STATION.





VIEW OF THE ROUNDHOUSE FROM THE COALING STATION, CINDER PIT IN THE FOREGROUND.

Smoke Jacks.—The smoke jacks are of a new type, known as the "Phoenix," furnished by the H. W. Johns Manville Co. of New York. They are fire and acid proof, being made of a compound of asbestos and magnesia, reinforced by galvanized iron cloth, which is imbedited in this material. The material and the moulds were shipped to the roundhouse and the jacks were moulded on the premises in three pieces—the hood, circular part or stack, and the cowl. The plastic material sets hard in a few hours, after which it is very hard and durable and is not affected by fire, acids or moisture.

The jacks are supported by rods which are attached to lugs on the hood. These lugs, which are moulded on the hood, are reinforced by heavy wire cable, the ends of which are unraveled and interwoven with the wire cloth. After the jacks were installed the supporting rods were covered with the "Phoenix" material to prevent deterioration. The interior of the jack is smooth, having no protruding bolt heads or tlanges. The average thickness of the material is 5% in. and it weighs from 4 to 4½ lbs. per square foot. The jacks shown on the cross-sectional view, over the drop pits, have a hood 19 ft. in length at the bottom, but in the main part of the house this length is only 8 ft. They are 4 ft. wide.

Locomotive Boiler Water Changing and Washing Out Equipment.-The W. L. Miller Heating Company's system for changing the water and washing out the locomotive boilers is used. The piping for this system, as well as the air pipes and the live steam pipes for blowing purposes, are carried overhead and have branches extending downward alongside the columns between every other pit. The live steam and hot water pipes are covered to prevent radiation. The Miller heating system consists of a 3 in. hot water pipe, a 4 in, cold water pipe, and a 6 in. blow-off pipe. There is a mixing box and a connection for attaching two hose lines on the columns between every other pit In the section of the power house containing the heating fans are two large tanks, one above the other, in which the water for washing out and filling the boilers is heated from the exhaust steam from the locomotive boilers, when they are emptied. The larger of the heating tanks is 22 ft. 10 in. long over the heads and 72 in. inside diameter; the inner one is 18 st. long and 48 in. inside diameter.


This system is guaranteed to give the following results: When water and steam at about 190 lbs. pressure are blown from the locomotive boiler, sufficient fresh water at 55 degs. F. will be heated to 195 degs, F. to fill a similar locomotive boiler to the same level without the use of any steam or hot water, except that supplied by the first boiler and the exhaust steam from the water pump. When water and steam at about 190 lbs. pressure are blown off, sufficient fresh water at 55 degs. F. will be heated to 125 degs. F. to thoroughly wash out a locomotive boiler of the same size. The time required for this operation should not exceed 2 hours. The same operation may be performed on two adjacent pits without affecting the above results.

Heating System.—The heating fans are contained in the section of the power house nearest the roundhouse and connected to it by a passageway. Hot air is forced into a duct, or tunnel, which extends around the outer circle of the house. This tunnel is of concrete and is 9 ft. 6 in. wide by 7 ft. deep where it enters, tapering gradually as it extends to either end of the house. Between every other pit a conduit, 36 in. in diameter, leads from the main duct and from either side of this three 18 in. ducts lead to the pits; two of these ducts enter the pit near the ends, and the other one near the middle. The 36 in duct gradually decreases in diameter, ending in a 10 in. duct which extends upward and opens into the house at the column alongside the doorway. These openings, as well as those leading into the pits, are fitted with dampers. The branch ducts, where they lead from the main tunnel, are equipped with deflectors, so that under normal conditions the same amount of air is delivered to each pit. Pipes, 5 in. in diameter, extend upward, from the main tunnel, underneath the windows at the outer wall of the house and have at the upper ends a T into which perforated pipes 5 in. in diameter, with caps at the ends, are fitted. The upper member of the T thus formed is 9 ft. in length and has several 11/4 in. perforations.

in the top side, spaced 6 in. apart. A 33 in. galvanized iron pipe extends upward from the end of the heating duct and into the machine shop; branches lead off from it directing the heated air downward thus heating this part of the building.

The heating system was installed by the Buffalo Heating Co. and is guaranteed to maintain an even temperature of 65 degs. F. when the external air is 10 degs below zero, and when fresh air only is supplied to the fans. It is guaranteed to maintain the same temperature inside when the temperature of the external air is 20 degs, below zero and 25 per cent of the air taken into the heater is from the inside and is recirculated. The temperature of 65 degs. F. is to be obtained after the thorse leading from the turntable have been closed five minutes. It is also expected that the house will be kept clear of four and steam. The fans have a capacity for changing the entire contents of the house every eight minutes, and of the annex every fifteen. Steam for the heating coils is furnished at a pressure of 4 lb or less.

The heating coils consist of two systems of inverted U shaped coils, constructed with two groups in each system. These




SMOKE JACKS. ALSO SHOWS THE PIPING USED IN CONNECTION WITH THE BOILER WATER CHANGING AND WASHING OUT SYSTEM.

groups are arranged in four divisions, so that the amount of heating surface may be varied to suit conditions. The heaters contain an aggregate length of 14,000 actual lineal feet of 1 in. pipe. The free area in any row of coils is not less than 40 per cent. of the total cross-section through the row nearest the point of admission of cold air. The ians are of the three-quarter housed, steel plate type and have a capacity for delivering 88,000 cu. ft. of air per minute, with a pressure of not less than 34 oz. at the discharge orifice, and when operating at 140 r. p. m. The fans are driven by 14 x 14 in. direct connected horizontal steam engines, using steam at 80 lbs. pressure and having an indicated horsepower of 52, with a back pressure of not less than 1 lb. and cut-off at half stroke.


Lighting.—The large amount of window space in the outer walls of the house furnishes splended day-lighting. The electrical power for artificial lighting is furnished by the Niagara Falls Power Co. An Edison two-three wire system provides alternating current at 60 cycles and 104 and 208 volts. A multiple


INTERIOR OF THE MACHINE SHOP,



TURNTABLE. ALSO A VIEW OF THE OFFICE—MACHINE SHOP—DROP PIT SECTION OF THE HOUSE.

OFFICES AND MACHINE SHOP.





CROSS-SECTION THROUGH THE MACHINE SHOP AND OFFICE.

enclosed type arc lamp, for six amperes at 110 volts, is suspended between the stalls, except at the ends and at the fire walls. A portable outlet, snap switch and two incandescent lights are placed on each side of the fire walls and at the end walls, and a snap switch and cutout control each pit light circuit. Recesses are placed in the drop pits for incandescent lights. All the wiring is carried in loricated iron conduits.

Equipment.—At the head end of each pit an iron block or stop is fastened to the track and prevents the locomotive from running into the wall. It is also the practice to place a heavy chain on the track in front and behind of one of the drivers, so that if for any cause the throttle should accidentally become opened, or leak, it would be impossible for the engine to move out of place. The machinists have portable tool boxes, which are about 3 ft. long, 18 in. wide and 13 in. high and are fastened upon trucks, so that they can easily and quickly be moved to any part of the house. There are also two or three portable vises, which are fastened on trucks. The boiler washer's tools and hose reels are carried on trucks. One of the illustrations shows the simple and substantial method by which a vise bench is fastened to the wooden columns. The table upon which the vise is placed is of cast iron, 20 x 30 in. x 1/8 in. in size and about 30 in. above the floor. The vises are the No. 6 size made by the Howard Iron Works.

At about the center of the middle section of the house, against the wall of the outer circle, is a tool room, 8 by 13 ft. in size. Here all of the heavy and special tools are kept, the mechanics drawing them as they are needed and returning them as soon as the job they are working on is finished. The jacks are stored just outside this room and are looked after and kept in good condition by the man in charge of the tool room.

Drop Pits.—That section of the house, consisting of three stalls adjacent to the machine shop, is entirely separated from the main part of the house and is equipped with two drop pits extending under all three tracks, one for driving wheels and the other for truck wheels. These drop pits are 8 ft. 3 in apart and are connected by three passageways, one of which has a track with a turntable at each end, so that the trucks carrying the telescopic jacks can be transferred from one pit to another. The driver pit is 7 ft. 4 in. wide and the pony or truck wheel pit 5 ft. wide.

In removing a pair of wheels from an engine the pedestal binders are taken down and the rods disconnected. Jacks are placed under the engine frame. The telescopic jack is placed underneath the middle of the axle and the drivers are raised sufficiently to allow the 10 in. I-beams, to which the rails are bolted, to be pulled aside. The wheels are then lowered into the

pit. A 6 ton electric hoist will be installed over the drop pits. There is also a pony or truck wheel drop pit extending under two tracks in the main part of the roundhouse, as shown on the plan view.


Machine Shop.—The machine shop is adjacent to the drop pit section of the roundhouse, having a common wall with it. It is 40 ft. wide inside, 102 ft. long, and has a concrete floor. Along the side nearest the offices is a pit upon which light repairs may be made. The remaining portion of the shop is used for machine tools and a forge and anvil for the smith. The construction of the roof, which is supported by light steel trusses, is shown in the cross-sectional view of this shop, and on the photographs, and furnishes a plentiful supply of daylight. The machine tools are driven by a 40 h.p. alternating current motor, which is mounted on a wall bracket. At the present time the following machine tools are in use:

Lathe, Putnam Machine Co.
Small Drill Press, Bement-Miles & Co.
Shaper, Gould & Eberhardt.
Bolt Cutter, Acme.
Turret Bolt Cutter, No. 4, Pratt & Whitney.
Grinder, Bridgeport Safety Emery Wheel Co.
Drill Press, Cincinnati Machine Tool Co.
Boring Mill, Two Head, Bullard Machine Tool Co.
Lathe, McMahon & Co.

There is also a forge, with a stack to carry off the smoke and gases, and an anvil. A crane will be installed to serve the heavier machine tools.


The Pratt & Whitney No. 4 turret head bolt cutter has a revolving head carrying nine dies, any one of which may be presented instantly to the bolt to be cut. The turret is secured in position by a spring lock-bolt. The spindle is hollow to receive bolts of any length and by removing the die, opposite the one that is at work, allowing the bolts to project through the turret, the thread may be cut any length required. The spindle is equipped with a chuck for holding the bolt or tap and is driven by a cone pulley. The chips and oil are caught in the bed and the oil drains free from the chips through a strainer into a receiver, from which it may be drawn and used again. As the machine is fitted with nine different dies, this many different size bolts may be threaded almost as quickly as the same number of one size. Such a machine is especially valuable in a roundhouse, where the number of bolts of one size, to be cut at one time, is small and where changes of size are frequent. The machine is furnished with two nut plates and one nut plate holder, and the following sizes of taps and dies, 1/2, 5/8, 3/4, 7/8, 1, 11/8, 11/4, 13/8 and 11/2.

Offices, Rest Room and Toilet.—A small addition to the machine shop, 16 ft. wide and about 59 ft. long, is divided into four parts, two of the rooms, with wooden floors, being used as



PRAIT & WHITNEY TURRET HEAD BOLT CUTTER.


VISE BENCH ATTACHED TO WOODEN COLUMN.



OUL STORAGE TANKS, POWER HOUSE AND A PORTION OF THE ROUNDHOUSE,



POWER HOUSE,



GENERAL ARRANGEMENT OF THE COALING STATION.

offices. The toilet and wash room has a concrete floor and is equipped with iron fixtures furnished by the J. L. Mott Iron Works. The rest room is furnished with a bench around two sides and may be used by the workmen while cating their lunch, or when off duty. A railroad Y. M. C. A. building is located only a few blocks from the roundhouse and is very convenient for the engine crews.

Turntable.—The turntable is 85 ft. long and was built by the King Bridge Company, of Cleveland, O. The pit is of concrete construction. The table is driven by electric power. The electrical controlling apparatus is enclosed in a small house, which is heated and lighted by electricity. A hand brake and sanding apparatus are also provided.

Coaling Station.—The coaling station consists of two circular pockets constructed of $\frac{1}{2}$ 6 in. steel and having a storage capacity of 300 tons. The flow of coal from these tanks to the tenders is controlled by under-cut gates. The conveying apparatus and the storage tanks are covered by a monitor, consisting of a steel frame-work covered with corrugated galvanized steel. The two smaller tanks shown between the larger ones are used for sand. As shown on the general plan, the coal is stored on three tracks near the engine house. As occasion requires the cars are moved down the slight incline and over the hopper, which is covered by a structure 14 ft. wide and 40 ft. long. The coal is unloaded into the hopper, and from this a reciprocating feeder feeds it in regular and uniform quantities to the conveying apparatus.

The conveying apparatus is furnished in duplicate, each unit having an elevating capacity of 100 tons per hour. This apparatus, extending from the feeder to above the first storage tank, measures 127 feet between centers and is placed at an angle of 30 degs. with the horizontal. A horizontal conveyor is used for carrying the coal from the inclined conveyor to the storage hoppers. These conveyors are driven by alternating current motors, operating on 3-phase, 25 cycle, 140 volt service. The plant is heated by steam and lighted by incandescent lights. It was designed and installed by the Link-Belt Company, of Philadelphia.

Sand.—The sand house is 55 ft. long by 15 ft. 8 in. wide and is located near the hopper house of the coaling station. The sand is shoveled into the storage space in the house and from there is wheeled up an incline in barrows and dumped above the sand stoves, of which there are two. As it dries it drops into a pit and is fed into tanks, 3 ft. in diameter. It is forced from these tanks to the storage tanks in the coaling station, through

2½ in. extra heavy pipe, by compressed air. The storage tanks above the tracks have a capacity for 190 cu. ft. of sand.

Water Supply.—At the present time there is a 50,000 gallon tank which supplies the water columns. As the plant is extended it will be necessary to add additional water tanks, as indicated. The location of the water columns is shown on the general plan.

Cinder Pits.—There are two cinder pits, each 200 ft. long, with a depressed track between them. The pits are 26 in. deep and the cinders, after they have been wet down, are shoveled from these into gondola cars. The pits are of concrete construction and the rails are carried on cast iron chairs, as shown in the illustration.

Store House.—The store house is 61 ft. 4 in. in length and 30 ft. 8 in. wide. The platform, on two sides of it, is of paving brick, laid herringbone, with a concrete curbing. The building is a steel frame brick structure with concrete floors and fire-proof roofing. The doors are covered with metal and the windows are wire glass in galvanized iron frames. One end of the storehouse, about 34 ft. in length, is used for oil and waste, and the other, and smaller part, is used for the storage of other supplies.

In the oil room are four large oil tanks. The oil is unloaded from the cars in barrels, which are rolled across the platform and into a frame work, or basket, shown in the accompanying illustration. This is then raised by means of an air hoist, which is attached to the roof beams inside of the building. When the basket, or frame work, is flush with the opening the barrel rolls by gravity into the building and onto a gallery above the oil tanks; it is then discharged into these tanks by gravity. Kerosene and fuel oil are stored in two large tanks west of the power house, each having a capacity of 10,000 gallons. These are supported on concrete piers and are connected by pipes to the oil house, being high enough so that the oil flows to the house by gravity.


Power Plant.—Mention has already been made of that part of the power house which contains the heating apparatus and the equipment for the boiler water changing and washing out system. This part of the building is 51 ft. 6 in. wide by 67 ft. long, except that one corner is cut off and a passage way extends from it to the engine house. It also contains an air compressor, of the Ingersoll-Rand, class H, type, having 16 x 16 and 26 x 16 in. steam cylinders and 16¼ x 16 and 25¼ x 16 in. air cylinders.

Connected to this portion of the building is a pump room, about 25½ ft. square, which contains the fire and service pumps.

The Underwriter's fire pump has a capacity for 1,000 gallons per minute, or four good 1½ in. smooth nozzle streams. There are two M. T. Davidson Co., 14 x 8¼ x 14 in. service pumps.

The remaining portion of the building consists of a boiler room, 66 ft. long and 43 ft. 6 in. wide. It contains three 200 h. p. Heine Safety Boiler Company boilers, with space for an additional unit if it should be required. The boilers are designed for 180 lbs. working pressure and are equipped with McClave shaking grates. The feed water heater is the No. 3 size made by The Platt Iron Works Co., Dayton, O. A Worthington 7½ x 4½ x 10 in. feed pump is used.

Along one side of the boiler room are the coal and ash rooms.



DEVICE FOR ELEVATING OIL BARRELS AT THE STOREHOUSE.

The coal is brought in over these rooms by means of a 16 ft. trestle, with a 5 per cent down grade, and is dropped into them by gravity. That part of the trestle leading to the building is supported by timbers resting on concrete piers. The track above the coal and ash rooms is supported by concrete piers, 3 ft. in section and spaced about 16 ft. apart.

The radial brick chimney, 125 ft. high, 12 ft. 4 in. in diameter at the base and 7 ft. 2½ in. in diameter at the top, was built by the Alphons Custodis Chimney Construction Company, New York. It has a capacity to supply draft for boilers aggregating 800 h. p. and is fitted with an automatic draft regulator.

CORRESPONDENCE.—Correspondence should not be shifted around simply to relieve desks of the presence of papers, but it should be thoroughly gone into, all questions answered, and, if an answer naturally develops another question, it should also be answered. It is exasperating to receive returned papers in which all questions are not answered, in an effort evidently to easily get rid of the correspondence, and such methods are insensibly treasured against those performing such indifferent service. It should be the pride of a man conducting correspondence to feel that his superior officer did not have to return it for additional facts, if such additional facts could have been reported on in the first instance by a conclusive investigation. Where possible and consistent, definite recommendations should always be made, otherwise a man's office becomes but a clearing house for correspondence, and such clearing houses are not essential or even desirable.-W. J. Harahan, before the New York Railroad Club.

A GOOD MIXTURE FOR CASE HARDENING.

John Buckley, foreman blacksmith at the Burnside shop of the Illinois Central Railroad, uses the following mixture for case-hardening. It gives splendid results and is much less expensive than the method in use at many shops:


Take charcoal broken fine, about one inch in size. Put a twoinch layer of this in the bottom of the box and pack it down with a mallet. Sprinkle about one pound of common salt over the charcoal, one pound of pulverized sal soda over the salt, one pound of pulverized rosin over the sal soda, and one pound of black oxide manganese over the rosin. Lay the material to be case-hardened on this, taking care not to have the pieces too close together nor too close to the sides of the box, where metal boxes are used. Fill in between the pieces with charcoan and pack well, taking care to have about two inches of charcoal between the work to be case-hardened. Repeat the sprinkling of compounds over the second layer of work, the same as in the bottom of the box. Finish off with about two inches of charcoal at the top of the box and sprinkle a little salt over it. Put the cover on the box, calk with clay, and place in the furnace for ten to fifteen hours, according to the amount and size of the work to be case-hardened. Heat to a bright red and cool in cold clear water.

The size of the box used for the above mixture is about twelve inches deep, fifteen inches wide, and forty inches long. It will hold one set of links, blocks, plates and pins.

TEAMWORK.—The gift of creating harmony is the keystone of the arch of success without which the structure will not sustain itself. True harmony, when carried to a finality, familiarly known as teamwork, engenders enthusiasm on the part of the individuals forming the organization. An organization without harmony disintegrates and soon becomes utterly demoralized, so that a disturber should be ejected from it with little ceremony, or he will prove its undoing. Departmental lines should vanish before the company's welfare. If, by sustaining an expense, another department can be helped sufficiently to justify the expense assumed, there should be not only no hesitancy, but an eagerness to do so, bearing in mind that the ultimate result to the company as a whole is what should govern. Where possible to do so, however, it will be found that the introduction of a friendly rivalry between officers of the same relative grade will, if properly handled, produce far reaching results, without in any manner affecting harmony, because of the incentive thus given them to use their intelligence and ability to accomplish at least as much, and, if possible, more than their fellows .- W. J. Harahan, before the New York Railroad Club.

Gold Leaf for Signal Blades, B. & O. R. R.—For some time past the signal and paint departments of the Baltimore & Ohio R. R. have been experimenting with gold leaf as a covering for signal arms, in an effort to retain distinctness of color without having to resort to painting the arms three or four times a year. The signal engineer of the road is reported as greatly pleased with the results of the experiment, which seem to justify its continuance as standard practice, for the reason that under all varieties of background the arm so prepared presents a more distinct aspect, which consequently is favorable to the runner. While the first cost is comparatively high, the results indicate that the reduction in maintenance will more than offset this and make the gold leaf arms cheaper in the long run.

Locomotives with Schmidt Superheaters.—On December 2, 1908, there were 1,898 locomotives in actual operation and 1,743 in course of construction, fitted with Schmidt superheaters. These are distributed over 101 different railway systems. Among the American railways participating are the Canadian Pacific, 33 locomotives; Great Northern, 2 locomotives; Chicago, Burlington and Quincy, 2 locomotives; Northern Pacific, 1 in operation and 2 on order; Pennsylvania, 1 ordered; making a total of 41 locomotives.



DATA OF SPECIAL INTEREST TO THE DRAFTING ROOM

PROCESS FOR SQUARING MENTALLY.

(Furnished by W. E. Johnston, Nor. Pac. Ry., St. Paul, Minn. Taken from Robinson's "Higher Arithmetic," page 236.)

Rule:—Add to, and subtract from the number (a) to be squared, a number (b) whose square is known and which will make the sum (a+b) or the difference (a-b) a multiple of ten so as to be a convenient multiplier. Multiply this sum by the difference, $[(a+b) \ (a-b)$, and add the square (b^2) of the number added and subtracted. The result $(a+b) \ (a-b) + b^2$ equals the square (a^2) of the number as desired.

For $(a + b) (a - b) = a^2 - b^2$

Therefore $(a + b) (a - b) + b^2 = a^2 - b^2 + b^2 = a^2$ Arithmetical example:—

(1) $89^2 = (89 + 11) (89 - 11) + 11^2$

(2) $(100 \times 78) + 121 = 7921$ $(2) \qquad 56^2 = (56 - 6) (56 + 6) + 6^2$

(3) $(50 \times 62) + 36 = 3136$ $(21\frac{1}{2}^2 = (21\frac{1}{2} - 1\frac{1}{2}) (21\frac{1}{2} + 1\frac{1}{2}) + 1\frac{1}{2}^2$

(4) $(20 \times 23) + 2\frac{7}{4} = 462\frac{7}{4}$ $192^{2} = (192 + 8) (192 - 8) + 8^{2}$ $(200 \times 184) + 64 = 36864$

JIB CRANE DESIGN.

(From Theo. F. H. Zealand, Whiting Foundry Equipment Company, Harvey, Ill.)

Frequently motive power officials, when contemplating the purchase of jib crane equipment, prefer to submit designs of their own upon which crane manufacturers are invited to offer quotations; often cranes built from the designs thus submitted would be unsafe in the service for which they are intended, the weak member of the design being the jib C.


The stresses in this member are imposed as follows:

Bending due to the load W.

Bending due to the weight of the jib.

Compression due to the tension in A.

All these produce compression in the top flange of the beam C, which compression is a maximum when the load is placed approximately two-thirds of the jib length from the mast B. These



calculations are usually made with sufficient accuracy but, when choosing the size of the beam or channel for the jib C, no account is taken of the tendency of the top flange of the beam to deflect laterally due to the compression. To guard against this the allowable compressive stress in this member must be reduced, necessitating the use of a larger size beam than would otherwise be required.

The allowable compression per square inch of cross sectional area is given by the following empirical column formula, where I equals the length of the jib from the mast to the extreme end

and b equals the flange width of the beam, both dimensions expressed in inches; the working compressive stress used throughout the design being 10,000 pounds per square inch:

$$P = \frac{11250}{1 + \frac{1^2}{3000 \text{ b}^2}}$$

P is the allowable compression per square inch in the top flange.

No claim is made to originality in connection with the formula given. It is to be found in any good structural steel handbook, as

$$P = \frac{18000}{1 + \frac{l^2}{3000 \ b^2}}$$


giving a reduced allowable stress corresponding to a working stress of 16,000 pounds, as used for quiescent loads.

ARCS EQUAL TO STRAIGHT LINES.

(Furnished by W. E. Johnston, Nor. Pac. Ry., St. Paul, Minn. From "Elementary Mechanism" by Stahl and Woods, pages 75-76. Rankine's Methods.)

1.—To find a straight line whose length is equal to a given arc of a circle.


Let AB be the given arc. Draw AC tangent to the arc at A,



also draw the chord AB and extend it to D, making AD equal to one-half of the chord AB. With D as a center and DB as a radius, draw the arc CE intersecting the given circle AB at the point E. Then the arc AE equals the line AC.


2.—To find an arc of a given circle whose length is equal to a given straight line.

Let AB be the given circle and AC the given line. Lay off AD equal to one-fourth of AC. With D as a center and DC as a



radius, draw the arc CE intersecting the given circle AB at the point E. Then the arc AE equals the line AC.

The error in each of the above methods is about 1/900 when the arcs AB and AE in Figs. 1 and 2 respectively are 60°, and varies as the fourth power of the angle so that the error at 30° is about 1/14400, the line being shorter than the arc.



ALL-STEEL SUBURBAN CAR-LONG ISLAND RAILROAD.

ALL-STEEL SUBURBAN CARS.

LONG ISLAND RAILROAD.

The Long Island Railroad is putting into service the order of fifty all-steel suburban cars, which it recently received from the American Car and Foundry Company. These cars represent the latest development in equipment of this class and are excellent in every particular. While they were designed for and can easily be adapted to electric service, they are for the present to be used in steam service and are being operated out of the Long Island City terminal.

As can be seen by the illustrations, they are of the standard design for all-steel passenger equipment adopted about a year and a half ago by the Pennsylvania Railroad, which was described and illustrated in the June and July, 1907, numbers of this journal. Reference can be made to those issues for drawings and photographs of all details. The theory on which the de-

signs were based has been fully treated in the series of articles on "Steel Passenger Equipment," by Messrs. Barba and Singer, which has been running in these columns during the past year. Reference can be made to the December, 1907, and June, 1908, numbers for discussion on the design of underframe for suburban cars of this class.

In brief, the structure consists of two 9-in., 15-lb. channels, with a ½-in. cover plate on top and ¾-in. plates on the bottom, forming a box girder center sill. The side sills are 5 x 3½-in. angles and transfer the load of superstructure and one-half the lading to the center sills through four special cantilevers, two of which form the body end sills and the others, of heavier construction, being located at the proper points between the center plates. No bolsters are provided, the center plates, which are of a special extension design to reach the same trucks used on heavier equipment, being secured directly to the bottom of the center sill girder. Cross bearers are provided between the sills for horizontal stiffeners, but do not assist in carrying the




INTERIOR OF ALL-STEEL SUBURBAN CAR-LONG ISLAND PAILROAD.

load coming to the side sills or on the floor. The main side posts are of pressed steel in channel section, with the edges flanged out parallel to the web and riveted to the sheathing. The upper ends are narrowed down and curved inward, forming the lower deck carlines. The upper leck carlines are of the same section. The inside and outside sheathing, roof, etc., is of steel sheets of varying thickness. A combination deck sill and plate of special flanged shape, stiffened by malleable iron posts is an interesting feature of the roof construction. All mouldings for interior finish are pressed steel as are also the guides in the window frames. The window sashes are wood, but the frames are flanged steel in one piece. The floor is formed of plastic cement laid on corrugated steel plates.

The interior finish is unusually attractive, the color being a warm tone of green relieved by a small amount of border stripping. The seats are of the Hale & Kilborn walk-over type with steel frames, wooden arm rests and rattan covering. Hand holds are formed in the outer corner of the backs. A continuous basket rack of substantial design has been provided. All doors are of

AN AIR AND STEAM SUPERHEATER FOR LOCOMOTIVES.

The New Century Engine Company, Ltd., London, is introducing an apparatus for the purpose of combining and superheating air and steam for use on a locomotive, which has been devised by Messrs. Field & Morris and is illustrated and described in *The Engineer*. This apparatus consists of two air compressors which are attached ahead of the cylinders and operated by an extension of the piston rod, or can be operated by connection to the cross head, and furnish compressed air at boiler pressure. A relief valve is provided to prevent excess of pressure. This compressed air is fed into a superheater of practically the Pielock design, except that it is located in the front end and adjacent to the front flue sheet, the boiler tubes being extended to pass through it. The steam from the dry pipe enters near the same points as the air and in passing through the baffles of the superheater they are thoroughly mixed and superheated.



UNDERFRAME OF STEEL SUBURBAN CARS FOR THE LONG ISLAND RAILROAD.

the sliding type, the vestibule doors being operated by the guard standing on the buffers between the cars. A trap door and step are provided for use where there are no raised platforms.

The trucks are of special design and are arranged for the easy installation of motors. They were fully illustrated and described on page 237 of the June, 1907, issue of this journal. The trucks under these cars differ from those illustrated in having quadruple instead of sextuple elliptical springs under the bolster. They have 36-in. wheels and a 7-ft. wheel base.

The cars have a length of 54 ft. 5¹/₄ in. over the body and 64 ft. 5¹/₄ in. over buffers. They weigh 77,100 lbs., which, of course, is without any electric equipment.

KEEP IN TOUCH WITH PROGRESS.—He who would seek to develop his capabilities to the fullest extent and keep that proper pace with progress, absolutely required for the continuation of success, should read carefully the literature of the profession. It is as necessary for the successful railroad officer to follow the changed conditions surrounding railway practices, and to know the new and advanced ideas and physical improvements as it is for the lawyer or doctor to do so in his profession. The railway and engineering periodicals and certain books on railroad subjects are the most valuable aid to him and should be freely used. They contain everything that is current and information pertaining to all departments so that a man may inform himself fully as to not only the work of his own department, but as to that of other departments.—W. J. Harahan, before the New York Railroad Club.

Large Saw Mill.—A saw mill at Bogalusa, La., belonging to the Great Southern Lumber Co., has a capacity of 600,000 ft. of sawed lumber boards per day. This is sufficient to build a little town of 40 houses in addition to a good-sized church and a school house.

This apparatus has been given a very thorough test on the North British Railway and has indicated a very substantial economy in coal consumption. This economy is explained in two different ways, one being that the air forms an envelope around the steam particles and thus resists the tendency to condensation as the temperature and pressure falls during expansion. Another explanation is that the compressed air itself contains considerable heat and since its temperature is higher than the steam at the same pressure it exerts a superheating action to some degree which allows the superheater itself to give a much higher degree than it would give with steam alone.

INSTRUMENT FOR MEASURING COLOR.—The difficulty of maintaining a standard by which colors for car bodies, etc., can be accurately gauged is easily understood and an instrument for performing this service has been invented by Frederick E. Ives and is in use in the Arthur D. Little Laboratory in Boston. This instrument is called a colorimeter, and is arranged to give a scale reading. After the standard shade has been determined, a board is carefully painted in the same manner as the paint will be used in practice and the color measured by the instrument, which thus gives a scale reading. This reading being recorded, the same color can be duplicated at any time by preparing sample boards which will be correct only when the instrument will record the same reading as was originally given as the standard. The same procedure is, of course, possible for determining the exact shades of different components which go to make up the composite color desired.

AIR COMPRESSORS IN ROUNDHOUSES.—The air compressor should have a capacity of about twenty cubic feet of air per minute per engine house pit, delivering the air into a receiver or reservoir at a pressure of one hundred pounds per square inch.—R. D. Smith before the New England Railroad Club.

ARTICULATED COMPOUND LOCOMOTIVES

AMERICAN SOCIETY OF MECHANICAL ENGINEERS.

At the annual meeting, held in New York, December 1 to 4, C. J. Mellin, member of the Society and consulting engineer of the American Locomotive Company, presented a paper on the above subject, which was discussed by a number of the best-known locomotive experts. Mr. Mellin stated in part:

"The constantly increasing demand for heavier power, made by most railways in the country during the last decade, and especially by those roads having heavy gradients combined with sharp curves, brought out various designs which on account of rail pressure limitations required so many coupled wheels that the length of the rigid wheel base made them unwieldy to operate with efficiency. This demand for greater power was, of course, greatest in mountain districts where heavy grades and sharp curvatures generally go together, necessitating, for safe operation, comparatively short wheel bases, reduction in engine resistance and wear of wheel flanges and rail, together with moderate weight of the working parts of the engine.

"In striving to meet this demand the locomotive designers and builders were brought face to face with an unsurmountable barrier to further progress in the enlargement of engines on the old lines; and in 1902 the American Locomotive Company decided to work out a design of a heavy, powerful locomotive for the Baltimore & Ohio Railroad, having two sets of engines under one boiler, capable of adjusting themselves independently to the alignment of roads with curvatures up to 30 degrees, on the principle developed by the prominent French engineer, M. Anatole Mallet, of Paris.

"Mr. Loree, then president of the Baltimore & Ohio Railroad, considered the question seriously; but it was first thought that it would be of no advantage to the Baltimore & Ohio Railroad, even if it proved successful, and the subject was left undecided for some time. In the latter part of 1903, on the recommendation of Mr. J. E. Muhlfeld, who in the meantime had become general superintendent of motive power, the Baltimore & Ohio ordered one engine of this type,* which was built at the Schenectady Works of the American Locomotive Company during the winter of 1903 and 1904, to suit the conditions of that railway.

"The Mallet articulated arrangement presents the advantages of enormous tractive power concentrated in the combination of the two sets of engines, with practically no increase in the individual weights of the moving and wearing parts over those of engines of the ordinary types; double expansion of the steam; simplicity and ease in operation and a short rigid wheel base, with the weight distributed over a long total wheel base, resulting in the greatest flexibilty and ease on track and brdges. It was also found possible at the very first to provide an engine under the control and operation of a single crew, having double the power of the largest engines of the ordinary type.

"Opinions on the use of a truck in the articulated engine are, however, divided, but, because of the many objections connected with the application of a front truck in freight service as to the first cost, maintenance, dead weight and unfavorable distribution of the machinery sometimes causing serious obstructions, nothing is gained by this objectionable feature, as it is practically the same as putting a truck ahead of a truck.

"The front engine in going ahead being a truck in itself, the first pair of drivers have a leverage in their favor on entering the curve. The reason for this is that the virtual support of the weight of the rear system, which is carried by the front system, falls back on the latter and in the rear of the sliding bearing; thus allowing a great part of the load of the rear engine to be carried by the hanger bolts between the frames.

"This alone reduces the pressure very materially on the sliding plate, which together with the short arm for friction resistance

* See AMERICAN ENGINEER, June and July, 1904, pages 287 and 262.

and long guiding arm for the flanges, reduces the pressure on them to a small fraction of the total friction load on the sliding plate and comparatively light centering springs will therefore suffice for this purpose and still further reduce the flange pressure.

"These same leverages and resistances act equally favorably in backing, as it is simply a reverse operation and the rear drivers have to swing the boiler against these resistances. Therefore, it is important that these should be small and with the shortest possible leverage, which naturally also minimizes the flange pressure on the rear wheel, that is, the last wheel of the engine, which then has to do the guiding.

"With the use of a front truck, the center of support is shifted forward and with it the virtual and actual supporting points of the weight of the rear engine carried on the front system. The weight on this support, must, therefore, be increased with the carrying capacity of the truck and offer little or no opportunity for transferring any of this load to the hanger bolts, practically doubling both the load on the sliding plate and the length of the resistance arm. At the same time, by the application of a front truck, the guiding point is moved forward so that the leverage has been increased to offset the increased side resistance of the engine. The guiding power of the truck, however, is limited to its swing resistance. This, therefore, may leave as much or more guiding to be done by the front drivers as where no truck is used because of the increased moments of resistance of the engine when curving.

"A more serious matter, however, is the backing with a front truck. The high resistance moments in the front must be overcome by the rear drivers, which are doing the guiding, and it is easy to understand how fast the flange pressure is multiplied by this displacement of the load and the safety margin for derailing dangerously reduced. It is, therefore, evident that a rear truck is a necessity when a front truck is used where backing is to be considered, thus curing one evil with another. Even with the application of a rear truck, the objections caused by the application of the front truck will be only partly compensated for; as the following very essential objections still remain:

- a. The application of a front truck increases the distance of the front buffers from the first pair of drivers by 15 to 20 per cent., and consequently throws the front drawhead of the engine further from the center of the track in curves than with shorter extensions where no front truck is used.
- b. It increases the total wheel base of the engine about 8 ft. 6 in., requiring an 80 ft. turn-table to take an average sized engine with its tender.
- c. Additional dead weight to be carried by the truck must be provided and the expenses in maintenance and first cost by the use of it are items that should not be overlooked.
- d. The long arms for friction resistance on the sliding plate with increased load on them, due to the front truck, will not be lessened by the application of a rear truck.
- e. When only a front truck is applied, the boiler is necessarily moved so far forward that it leaves scant room for the valve motion on the rear engine. The result of this is that the width of the firebox is necessarily limited to about 72 in.

"In the case of the passenger engines of the articulated type, however, large wheels would be used, and only four pairs of drivers can or need be applied. A four wheel front truck, with rigid center pin and rigid trailing wheels, works in conveniently in the place of a third pair of drivers in each engine front and rear, respectively, which otherwise, with their large diameter, would make the engine unduly long.

"Among the various differences between this class of engines and that of the ordinary type, is the action of this engine when

loaded to the slipping point. While the former is less liable to slip than the latter, due to a more uniform pressure on the pistons, they will not be considered loaded to anywhere near their capacity until slipping takes place, and consequently slipping does occur on heavy grades. With the ordinary engine, slipping at such times is a serious matter, as the train is losing speed and may stall on that account after a few repetitions. In the case of the articulated engines, the loss in power by the slipping of one engine is practically gained by the other in the increase of unbalanced pressure that thereby results.

"The effect on cars and draft gears in starting heavy trains by this type of engine, as well as convertible compound engines on the same principle, is a most important feature, as it is accomplished with a so-called dead pull, without the necessity of taking advantage of the slack in the train with its destructive jerks. These locomotives are, therefore, easier on the draft gears than simple engines of half their size loaded to their full capacity. The reason for this is found in the great starting and emergency power, with which these engines are provided, so that the slack is taken up under very slow speed. This is generally done with light throttles. The front cars start successively under a slight acceleration of the engine, gradually going over to a retardation before the last cars get into motion, after which the engine is given full throttle. In other words the train is stretched first and then it is started under direct pull, so that there need not be any but slight shocks or jerks.

"These engines are adaptable to a greater variety of conditions than the older types, rendering it possible to double the engine power on a given rail weight; and their advantages are most pronounced as displayed on heavy grades and sharp curvatures.

"It should also be remarked that, due to the absence of jerks and slack in starting, as well as the more uniform cylinder pressure, the stresses on the machinery and framework are considerably reduced; and, further, that the milder exhaust produces a less intense heat and a better utilization of it, all of which contribute to a reduction in the repairs of the locomotive as a whole, compared with a simple engine, if it were practical to construct one of this type. This has never been advanced as a feature to the credit of the articulated engine because it is difficult to give it any definite value; but is referred to as a reply to the often repeated supposition that these engines are hard to keep in repair. As a matter of fact, the opposite is the case, because on account of sub-division of the work in two engines the parts are lighter and easier to handle in repairs and renewals."

The paper also discussed briefly the distribution of weight in an articulated locomotive, which subject will be fully treated in a special article in the next issue of this journal. There was also included illustrations and descriptions of details of various locomotives that have been built, most of which have been illustrated in these columns. A number of proposed designs, for both passenger and freight articulated locomotives, were included, as well as photographs and general dimensions of all of this type of locomotive that has been built in this country.

DISCUSSION.

In opening the discussion F. J. Cole analyzed the features of construction which differentiate the Mallet from other types and enables it to perform satisfactorily and efficiently its remarkable work in Europe and this country. Among these he mentioned the short rigid wheel base, the fact that the flexible steam connection has only to carry low pressure, the practical impossibility of both engines slipping at the same time and the extreme flexibility of the machine. The possibilities of the designing of enormous locomotives with a reasonable axle load was commented upon and tables given. He mentioned the surprising ease with which these engines were fired and attributed it largely to the use of compounding, which reaches its maximum efficiency at slow speeds and long cut-offs. He stated that, "in ordinary service, especially for helping and pushing, the use of leading truck wheels is entirely unnecessary. It is of great advantage to utilize the entire weight for adhesion and no useful purpose is served by adding the additional complication of truck wheels. No sharp flanges have developed on the Baltimore & Ohio locomotive after four years of service, although this locomotive is operated twenty-four hours a day pushing up hill and backing down over sharp curves. In comparison with ordinary consolidations in use on this road, which do wear their flanges badly, this fact is extremely gratifying, and proves conclusively that the extreme flexibility of this engine is sufficient in itself to move freely around curves without the use of guide wheels. * * * * Except for the possible use in road service, where the speeds exceed 40 or 45 miles per hour and the requirements from the boiler are such as to render it impossible to utilize the entire weight for adhesive purposes, the employment of leading or trailing wheels does not seem to be necessary and it seems to me that the principle justification for their use may be found in cases where the extreme boiler capacity is required and that under such conditions only will their use be justified."


Harrington Emerson stated that a few years ago Bion J. Arnold had remarked that there was no known way of moving freight as cheaply as putting a steam locomotive ahead of the train. In connection with the contention of the electrical engineers during the past few years, who had attempted to prove their case by assuming ideal conditions for electric traction and that the current locomotive practice was the best attainable, he remarked that two things had put the electrification far into the future, one was the panic, which reminded railroad managers very forcibly of the financial situation and the other was the Mallet type of locomotive. He related a few instances in connection with the large Santa Fe type of locomotives which, while operating most economically, had so long a wheel base as to cause considerable trouble with the track, and said that the Mallet type would give all, and more, advantages than the Santa Fe and at the same time would correct the trouble with the long wheel base.

L. R. Pomeroy considered briefly the commercial side of the introduction of the Mallet type of locomotive, which in a number of special cases had proven to be the remedy for present conditions that it has previously been believed could only be improved by the substitution of electric traction. He took up a special instance of a 50-mile mountain section, having a maximum grade of 2.2 per cent., with seven trains per day in each direction. The reduction of one-half in train mileage, with the same tonnage, at 50 cents per train mile, this rate covering the items directly affected and used in computing the saving to be advantageous in grade reduction, would save \$65,000 per year, which capitalized at 6 per cent. would equal \$1,000,000. In order to obtain this saving electrically the complete electric apparatus would cost considerably more than this capitalized amount, whereas the required number of Mallet compound steam locomotives to perform the service would cost about one-third the amount necessary for an equivalent electric service. Stating the case in another way and basing the saving on the reduction in train crew expense, leaving out all other advantages, it is seen that with a total of 14 trains, which is equivalent to about 700 train miles per day, the cost of the train crews amounting to 121/2 cents to 15 cents per train mile, the saving then, in reducing the train mileage one-half, would equal \$17,800 per annum, which at 6 per cent. is a capitalization of about \$300,000, or more than enough to pay for the required number of Mallet locomotives to perform the

This is not meant to be a reflection upon the possibilities of electric traction in general, but was simply a particular case, which was not at all unusual, where the magnitude of the business would not justify an electric proposition, but where the Mallet locomotive could obtain all of the savings that electric traction would obtain on a larger basis, and would serve as a very profitable bridge between the present conditions and the eventual traffic density where electric service would be advisable.


George L. Fowler, on request of Dr. Goss, drew attention to the credit that is due Mr. Mellin for developing Mallet's engine, which was originally designed for narrow-gauge lines and was of light weight, into the enormous and powerful machines that are now being built on this principle.

G. R. Henderson briefly drew attention to the fact that in order to obtain the full advantage of these large locomotives it would




2422444 About 410. -16'6 Tubes 0 -55'10' Total Wheel Base 0 26 x 30 0 -11'2'Tubes 0 40 x 30 To Sai 116 oT 0 ot lian oT

DESIGN FOR ARTICULATED FREIGHT LOCOMOTIVE WITH FLEXIBLE BOILER, PROPOSED AND DESIGNED BY S. M. VAUCLAIN OF THE BALDWIN LOCOMOTIVE WORKS.



ARTICULATED COMPOUND PASSENGER LOCOMOTIVE FOR THE SANTA FE, UNDER CONSTRUCTION AT THE BALDWIN LOCOMOTIVE WORKS.



ARTICULATED COMPOUND FREIGHT LOCOMOTIVE FOR THE SANTA FE, UNDER CONSTRUCTION AT THE BALDWIN LOCOMOTIVE WORKS.

be necessary to give careful attention to the development of automatic stokers.

S. M. Vauclain, general manager of the Baldwin Locomotive Works, discussed the subject at some length by means of a large number of lantern slides. He showed a photograph of Monsieur Mallet and spoke most highly of his great ability as a designer and expressed regret that owing to the expiration of patents, etc., he would not receive the pecuniary returns which by right should be his. Mr. Vauclain briefly followed the early history of this type of locomotive, showing drawings of the DeCauville Railway locomotive, which he believed to be the first one of the type ever publicly exhibited. He stated that it was in 1877 that Mallet first designed an articulated compound locomotive.

Lantern slides were then shown of a design which was submitted in 1898, by the Baldwin Locomotive Works, to the Erie, but was not accepted. Following this a large number of slides were shown of outline diagrams of studies which had been made for locomotives of this type for use on the Santa Fe. These studies included a great variety of arrangements of cylinders, combustion chambers, re-heaters, feed water heaters, etc., and all of them, except the first, included a leading pony truck and most of them also had a trailing truck. This series of studies was completed by the design of freight and passenger locomotives which are shown in the above illustrations and are now under construction at the Baldwin Locomotive Works. It will be seen that in both of these the boiler proper, with the ordinary firebox and 19 and 20 ft. tubes, ends in a large combustion chamber, ahead of which the shell is continued and tube plates, with a nest of large tubes, are arranged to form a feed water heater, ahead of which is the front end with the exhaust pipe and stack. In the combustion chamber is to be located a superheater, or a re-heater, or possibly both, and the boiler shell is arranged to be easily disconnected at this point for inspection and cleaning of the apparatus. The freight locomotive is of the 2-8-8-2 type and has 63 in. drivers with a 34 in. stroke, the cylinders being 26 and 38 in. in diameter. The passenger locomotive is of the 4-4-6-2 type, with 73 in. drivers.

Following this series of studies, examples were shown, by means of drawing and photographs, of other articulated compound locomotives built by the Baldwin Locomotive Works during the past few years, all of which have been illustrated in these columns.

Mr. Vauclain then showed a series of diagrams illustrating the development of a design of articulated compound locomotive

for the Southern Pacific. This started out with a desire to apply the principle to a tank locomotive which would carry its coal and water on the locomotive frames. This however, was finally given up as impractical and after several different steps the design shown on the opposite page was accepted and two of this arrangement are now being built at the Baldwin Works. It will be seen that this is somewhat similar to the Santa Fe freight locomotive, the wheel arrangement being the same, but that the reheater is located in the front end proper, the combustion space being considerably shorter, as is also the feed water heater. In this case the boiler is not arranged to be disconnected at the combustion chamber, but a manhole is fitted for admission to this space from the top. These locomotives have 57 in. drivers and a 30 in. stroke, the cylinders being 26 and 40 in. in diameter.

Mr. Vauclain then threw a design on the screen, which he presented as a proposed arrangement of what he guaranteed would be an entirely satisfactory design for a heavy freight locomotive. This design is also shown on the opposite page. In it there is introduced an entirely new and novel feature and idea; that is, of having a flexible boiler as well as an articulated frame, so that there would be no necessity for the front group of frames to move relative to the boiler in taking curves. Mr. Vauclain is willing to back up this design to the fullest extent. The illustration shows the general features very clearly and it will be seen that it includes both a superheater and a reheater, located in a large combustion chamber, at which point the bellows connection is also placed, and it has the low pressure cylinders attached to the front end in the ordinary manner.

The remarks of the speaker were closed by showing some foreign locomotives of small size which had been equipped with front and trailing trucks.

Mr. Vauclain also briefly referred to a discussion on the paper that had been furnished by Mr. Emerson of the Great Northern Railway, which will be printed in full in the proceedings of the society. Mr. Emerson confined himself to a report of the service that the locomotives on his road, which now number about 68 of two sizes, had given during the past two years. This experience was so favorable that it has been decided to extend the use of this type of locomotive to disfricts having grades as low as .72 per cent.

On the Cascade division of that road, where the ruling grades vary from I per cent to 2.2 per cent the service had previously

been performed by consolidation locomotives having 20 x 32 in. cylinders, 55 in. drivers, 210 lbs. of steam and weighing 180,000 lbs. on drivers.

"In the beginning the large Mallets were first introduced on the hill between Skykomisk and Leavenworth on the Cascade division with a consolidation engine used as road engines and the Li* helpers used on the hill only. Up to the present time the tonnage over these mountains has been gradually increased from 1050, with two consolidations, to 1600 tons now being hauled with the LI engines. The LI engines have now entirely replaced the consolidation engines and it is the practice to start out from Everett with one LI engine used as a road engine, taking 1600 tons as far as Skykomisk, over a ruling grade of 1 per cent. At Skykomisk another LI engine is put on as a pusher and takes the 1600 ton train over the mountain. The tonnage hauled in the opposite direction is the same and the LI Mallet has proven itself to be not only valuable for helper service but a good reliable road engine and the combination of road and helper service works out admirably on this division, making it unnecessary, going east, to reduce the tonnage at Skykomisk in order to get over the heavy grade. Recent performances show that on a round trip over this division the L1 engines hauled 1600 tons with a total consumption of 43.8 tons of coal, equivalent to 25.13 lbs. of coal per 100 ton miles. The consolidation engines could only handle 1050 tons, with practically the same amount of coal consumed, equivalent to 38.29 lbs. of coal per 100 ton miles. In other words the tonnage on this division has been increased at least 52 per cent with the result due to the Mallet engine of a saving of 34.39 per cent lbs. of coal per 100 ton miles.

"Since putting the LI engines in road service the performance has been so satisfactory that there are now but four of them used exclusively as pushers, two as helpers over the Cascade mountains and two on the Butte division in transfer service.

"On the Spokane division the 1600 tons delivered at Leavenworth is reduced to 1450 tons and a small Mallet, class L2,† takes this train to Hillyard, a distance of 195 miles. These engines have enabled us to increase the tonnage from 1100 tons hauled by the consolidation to 1450 tons, an increase of 31.8 per cent. The run is so long that this tonnage has been established in order to get the trains over the district in a reasonable time and they handle the tonnage at from eight to ten miles per hour on the heaviest hills and up to 30 miles per hour where the grades are not so heavy. The engines are run straight through but crews are changed half-way at Wilson Creek.

"The performance for the year ending June 30, 1908, shows 22.04 lbs. of coal per 100 ton miles on this district, a saving of 27.5 per cent. over the consolidation.

"On the next division east the L2 engine takes a train of 1700 tons from Whitefish to Essex, where the ruling grade is .8 per cent. At this point an LI helper is put on to assist the train to Summit, a distance of 18 miles, where the ruling grade is 1.8 per cent. West bound an L2 engine takes a train of 1450 tons through, the ruling grade being I per cent. On this district the tonnage has been increased 20 per cent, with a reduction of coal per 100 ton miles of 20 per cent. In the next district, from Cut Bank to Havre, a distance of 125 miles, with a ruling grade of .8 per cent, an L2 engine takes 1700 tons over the division. West the ruling grade is I per cent and this engine handles 1450 tons. The round trip on this division, with the L2 engine, is made with 32 tons of coal, or an equivalent of 15.75 lbs. of coal per 100 ton miles. The consolidation previously used handled but 1200 tons west and 1425 tons east and used 18.9 lbs. of coal per 100 ton miles, showing an increase of 20 per cent in tonnage and a decrease of 16.6 per cent. in coal per 100 ton miles.

"At another point, where the ruling grade is 2.2 per cent, the L2 engines have increased the tonnage previously handled by the consolidations from 550 to 700 tons.

"The question of maintenance we would naturally expect to be higher on the Mallet engines and for the year ending June 30, 1908, the cost of repairs on the L2 class was 10.47 cents, which

* Large type Mallets. See American Engineer, Oct., 1906, page 371. † Small type Mallet. See American Engineer, June, 1907, page 218.

is not considered at all excessive. The cost of maintaining the consolidation engines in the same service has seldom been less than 8 cents per mile.

"Another feature which has been noticed is that the Mallet engines are not at all hard on draw bars, owing to the fact that the train is not jerked by the engine slipping and catching, since both engines do not slip at the same time. The tire wear on these engines is very light and the flange wear is not excessive. In fact the Mallet engines have been put on some divisions where the flange wear on the consolidations was very bad and no wear has been noticed on them.

"We still have in service two of the first L1 Mallet engines which have never yet been in the shop for general overhauling. in fact have never been off their wheels and have been in continual service since October, 1906."

COPPER SAFE-ENDS FOR FLUES.—Extensive experiments have been made attempting to use copper flues and iron flues with copper safe-ends; brass flues have also been tried, but it appears that the most serious problem is to prevent the rapid destruction of the beads on account of the abrasive action of the fire-box gases and cinder. This was very well proven in a recent experiment on the Norfolk & Western Railway by putting copper safe-ends in a consolidation freight engine equipped with the reinforced flue sheet (see American Engineer, June, 1908, page 207). The engine ran but a short time before the flues began to leak, which condition became continuous, the engine seldom going through a terminal without requiring attention. The heads were finally entirely burned off, and the ends of the flues were reduced to practically a knife-edge. The engine was finally withdrawn from service on this account, the flues having made but 9,189 miles, which is about one-fourth of the mileage we should expect to get with iron or steel.—Alexander Kearney, assistant superintendent motive power, Norfolk & Western Ry., before the Richmond Railroad Club.

TIMBER WASTE IN U. S .- We are now cutting timber from the forests of the United States at the rate of 500 feet board measure a year for every man, woman and child. In Europe they use only 60 board feet. At this rate, in less than thirty years all our remaining virgin timber will be cut. Meantime, the forests which have been cut over are generally in a bad way for want of care; they will produce only inferior second growth. We are clearly over the verge of a timber famine. This is not due to necessity, for the forests are one of the renewable resources. Rightly used, they go on producing crop after crop indefinitely. The countries of Europe know this, and Japan knows it; and their forests are becoming with time not less, but more, productive. We probably still possess sufficient forest land to grow wood enough at home to supply our own needs. If we are not blind, or wilfully wasteful, we may yet preserve our forest independence and, with it, the fourth of our great industries .-Treadwell Cleveland, Jr., U. S. Forest Service.

Honesty.—What may be designated as the first element, or rather, essential, of success, is common honesty. To state the old maxim: "Honesty is the best policy," is but to reiterate a truism, and to repeat parrot-like the principle that has stood the test of ages. There is, however, a broader honesty than that apparent on the surface, that is a requirement. This consists not entirely in the application of the Commandment, "Thou shalt not steal," but seeks also for its guiding principle the "Golden Rule." In other words, a studious and persistent effort to render just and fair treatment to all alike whether he or it be great or small.—

W. J. Harahan, before the New York Railroad Club.


At Altoona, Pa., telephones have been installed in the homes of 517 trainmen of the Pennsylvania Railroad, and all of the trainmen and yardmen of the Middle division are now called to service by telephone, instead of by messenger as formerly. Fifteen callers have been appointed to other positions.

APPLYING FLEXIBLE STAYBOLTS.*

By R. V. ANDERSON.

One of the most important jobs on a locomotive boiler is the proper application of flexible staybolts. Every part of the work has to be carefully performed to be successful. The method used at the Rogers Locomotive Works, which has been very successful, is as follows:

The holes in the sheet are punched 1/32 inch smaller than the diameter, of the root of the thread at the point of the sleeve, and reamed with a taper reamer that has a guide on the point which goes through the firebox sheet. There is a collar fastened on the reamer at the proper place near the head which stops the reamer from going in too far, and allows 3/32 inch for thread, and makes all the holes exactly the same size. The tap has also a guide and a stop on it so the holes are tapped the same. We only use one reamer and one tap in the holes and get a perfect



DEVICE FOR HOLDING ON IN RIVETING FLEXIBLE STAYBOLTS.

thread. The sleeves are screwed in with a stud nut, driven with a ratchet lever. The bolts are run in with an air drill until they are nearly home, then adjusted carefully by hand, taking care to get an equal load on all the bolts without pulling the firebox sheet out of line.

While riveting the bolt we have a simple device for holding on which may be new to some of you. It obviates all danger of spoiling the thread on the sleeve. It consists of a nipple which is screwed on to the sleeve, and has a sliding plunger inside which fits on the head of the bolt. The holding on is done by a common holding on sledge which backs up on the outside end of the plunger. An order of 60 boilers for the Wabash Railroad recently completed had 298 flexible staybolts in each, making a total of 17,880 bolts. The inspector would not permit any calking on the sleeves, but only 10 of them had to be renewed because of leaks. The most important thing needed in putting in flexible saybolts is good judgment. You can have your holes perfect, your reamer perfect, your tap perfect, your bolts and sleeves perfect, yet an injudicious or careless workman will spoil the whole job.

ANALYSIS OF COST OF LOCOMOTIVE REPAIR SHOPS

George A. Damon, of the Arnold Engineering Company, presented the following analysis of the cost of locomotive repair shops in a paper on "Arrangement of Railroad Shops," read before the Canadian Railway Club:

Our records show that locomotive repair shops which are laid out on a basis of the number of pits required equal to 6 per cent. of the number of locomotives served can be built and equipped complete for an expenditure ranging between \$50,000 and \$65,000 per pit. If one pit will serve sixteen and two-thirds engines per year, the cost of repair facilities will fall some place between the limits of from \$3,000 to \$4,000 per locomotive. An investment amounting to the lower limit is absolutely necessary if the engines are to be kept on the road. Just how much

more than the lower limit should be spent in order to secure the minimum cost of locomotive maintenance, including all the items of not only actual repair expenses, labor, and material, but also interest, depreciation, insurance and taxes upon the plant provided, is a question that should have the most careful consideration.

The following analysis of the total cost will serve to indicate the relative importance of the decisions that must be reached in order to give each dollar expended a maximum earning capacity.

Table of Cost Limits for Locomotive Repair Shops on the Basis of Twenty-Five Erecting Pits.

DIVISIONS	——Per	of Cost Pit—	Approx. Proportion of
Tracks, Crane Runways, Transfer or	"Low."	"High."	Tot. Cost
		\$ 3,000	4%
Water and Sewer Systems		1,800	
Piping and Wiring Tunnels and		1,000	2%
		1 000	10
Tunnel Piping		1,000	1%
Marking and Frankings.		*0.000	1 amino
Machine and Erecting Shop	8,000	12,000	17%
Boiler and Tank Shop	3,000	5,000	
Forge Shop		2,400	4%
Storehouse and Offices	1,000	2,500	3%
Locomotive Carpenter Shop		1,000	1%
Power House	1,200	2,400	3%
Oil House and Equipment	400	600	or 1%
Miscellaneous buildings:		12	
Scrap Bins, Material Sheds, Fences	500	1,000	1%
GENERAL EQUIPMENT FOR A			THE PARTY OF THE P
Power House Equipment		8,000	11%
Traveling Cranes	1.500	3,000	4%
Tool Equipment	10,000	15,000	
Heating System	1.200	2,500	3%
Power and Lighting Systems, includ	. 1,200	2,000	370
		4 500	E Of
ing yard, wiring, and lighting.	. 1,000	4,500	
Plumbing and Lockers		1,000	1%
Air, Water, Steam, and Oil Piping		4 000	
in Buildings		1,200	2%
Incidentals, Organization, and En			-
gineering	. 2,000	7,000	8%
			100%

Note.—These figures do not include items for Real Estate and Preparation of the Shop Site, which cost necessarily varies between wide limits.

The Foundry building and equipment are not included in these figures.

The sum total of the "low" and of the "high" figures shown will result in grand totals which will show a wider range than the 33½ per cent. variation indicated by unit figures of \$3,000 to \$4,000 per locomotive, but as it is improbable that any shop would be built using either the lowest or the highest estimate for every one of its parts it will be found that only in exceptional cases will the actual total cost fall outside of the limits first given.

HARDENING OF STEAM Hose.—In the case of steam hose the hardening is caused from the fact that there is too much sulphur in the rubber and vulcanization goes on with the heat from the steam, after you commence to use it. If we could get an exact proportion of sulphur this vulcanization would not go on, but this is a very difficult thing to do. The crude rubber is gathered by natives all the world over, and is taken from trees varying from seven years to ten years old, and if you bought ten tons of rubber, you might have ten different qualities.—A. D. Thornton, general technical superintendent, Canadian Rubber Company, before the Canadian Railway Club.

ROLLER BEARINGS.—There is almost no limitation for the use of anti-friction bearings, but the possibilities can be better appreciated when it is known that such bearings are sold at prices ranging from 2 cents to \$7,500 for a single bearing, and are used to carry loads from a few ounces, running at 30,000 revolutions per minute, to loads of 1,500,000 pounds at 100 revolutions per minute and 250,000 pounds at 500 revolutions per minute.

^{*} A paper presented before the Master Blacksmiths' Association.

SIDE SHEETS OF WIDE FIREBOXES.*

C. A. SELEY.

The author prefaced his paper with the following remarks:

"I suppose I ought to make an apology for offering a paper to this club on a matter of pure speculation. I have no data to offer; I built up a theory on a set of conditions which I believe represent the result that we are getting in the life of the side sheets of the modern locomotive. The matter is not new, as it was discussed in the Master Mechanics' Association in 1905, the subject in part being covered by the topical discussion by Lawford H. Fry, of the Baldwin Locomotive Works. There is one paragraph of his paper which I would like to read, part of which I agree with for reasons other than are assigned. He says 'As the water in contact with the side sheets is turned into steam, it must be allowed to rise to the steam space and must be replaced by other waters. The water spaces should be so designed that this natural circulation is aided and that the currents of steam and water impede each other as little as possible. This is secured if the firebox sheets are vertical or with a slight slope outward as they rise from the mud ring, so that the steam can rise along the firebox sheets and the water descend along the outside sheets without mutual interference."

The life of side sheets in the modern wide-firebox locomotives is a problem that is demanding the active attention of motive power officials because of their decidedly shorter life as compared with side sheets in the older narrow-firebox types. A prominent railway mechanical officer recently stated the matter about as follows: "That the old-style deep firebox with ogee's sides was rather hard on staybolts, but the boxes lasted on an average of from six to nine years. The later wide fireboxes, while easier on staybolts, frequently fail in two or three years." On this showing it was thought that the tendency in firebox design would be towards a modified ogee side with very flowing lines.

*

181

*

The above statement presents an effect and a possible remedy, but does not consider the causes. It is unfortunate if we cannot utilize an increase in the width of the grates to secure the area necessary in large locomotives without having such a decided reduction in the life of the side sheets. It has not been noted that the crown sheets are similarly affected, there has been no radical change in the quality of the steel employed, or of the fuel or service demanded of the locomotive, that would account for the trouble, and we are forced to the conclusion that there must be some element in the design or operation of wide fireboxes which has an unfavorable influence not clearly understood.

By the life of side sheets is meant serviceable condition, freedom from cracks, leakage, and other failures that may require renewal. The life is not particularly affected by the pressure carried, as the staying is generally done with a large factor of safety, but is directly affected by the temperature changes, the expansions and contractions, in service under steam as well as when out of service on sidings or over cinder pits and in washing out, and water changing in the roundhouse.

Steel will stand a certain number of stresses before failure, dependent on the degree or amplitude. We can increase the number of applications of a test specimen by decreasing the amplitude. In a firebox it is difficult to decrease the number of the applications as they are dependent on the service of the engine, the number of times it is fired up and cooled off and these conditions are not materially different for the two types of fireboxes under discussion, and thus it may be that the short life of the side sheets of wide fireboxes can be accounted for by the greater amplitude of the movement or increased expansion and contraction.

At first thought one would say that the ogee box presents a series of curves that will adjust themselves to meet those movements in a way not possible in the straight and more rigid side of the wide box. This is true only in part, as the side is straight

• Read at the December meeting of the Western Railway Club.

longitudinally in both designs, and this is the most important direction. Apparently, therefore, the increased amplitude must be accounted for by a higher internal temperature of the side sheets by reason of less perfect heat transmission to the water in the leg.

In the later designs of boilers we find a general tendency towards the use of wider mudrings and water legs than formerly. This has resulted in giving staybolts longer life, as their increased length gives a smaller amplitude of vibration or motion, but it has also decreased the rate of the flow of the water upward proportionally as the volume of water in the leg is increased. This point will be considered later.

In getting away from the ogee form of box and the narrow water leg, it was thought that the circulation of the water would be improved, as the ogee presents a curve adverse to the direct vertical rise of the water as it is heated and displaced by the cooler water coming from the throat. The results, however, would seem to prove this theory wrong, or at least we have only gained in life of staybolts.

The secret of the matter seems to be that, if the rate of flow and its wiping, scrubbing, impinging action can be directed against the side sheets it has the effect of wiping off the steam bubbles as they form, prevents their combining into a film or curtain of steam against the sheet, which is by no means as good a conductor of heat as is the solid water. This theory will account for increased internal temperature of vertical and inwardly inclined side sheets and can be inferentially proven.

It is well known that crown sheets outlast several sets of side sheets, and while this is due in part to the fact that there are not the same variations of temperature at the same time in different parts of the sheet, it is also true that its surface presents no chance for formation of a film of steam and it has practically solid water in contact with it at all times.

This is also true of the Wooten type of furnace, the parts failing being generally a limited portion at the sides, which approach the vertical. It has also been noted that the door sheets of fire-boxes which have moderately inclined back heads do not last as long as those that are vertical. The incline forces the wiping action of the circulation against the outer sheet.

It has been stated that in the early days of torpedo boat design a locomotive type of boiler was tried because of its great efficiency and amount of steam produced per foot of heating surface in locomotive service. On the boat, however, it was an utter failure. By way of experiment this boiler was put on a vibrating cradle, which greatly increased the steam production. This could only be accounted for by an increased circulation, facilitating the heat transmission. It has been proven by late Government experiments that increased boiler efficiency can be obtained by increasing the rate of flow of the gases, this action tending to wipe off from the heating surface the partially cooled gases, replacing them with new and hotter gases.

Thus the questions of circulation, whether of water or gases, seems to be a very important factor in boiler efficiency, and while some of the examples quoted may be somewhat remote in their application, yet they seem to point to the circulation in the water leg as being a vital factor in the life of side sheets.

There seems to be no question that if there is a strong impinging circulation against the fire sheet, the heat will be more freely transmitted, steam film prevented, solid water maintained against the sheet, and the internal temperature of the sheet kept down and the amplitude of the sheet movement reduced to the minimum. To effect this the side sheets should not be vertical nor sloped inward, but be sloped or curved outward from above the fire line, but it is obvious that this cannot be extreme without getting into grate area difficulty.

It is quite possible, however, that we have gone too tar and are too liberal in that respect, as the reports of successful steaming of some recent engines would seem to indicate, these engines having a much lower proportion of grate area than is at present common. If a reduction of grate area can be made, it will permit the modification of side sheets as proposed.

The question might also be raised as to the width of water leg. Aside from affording sufficient room to hold the accumu-

[†] The form having a reverse curve in section with the convex part above.

lated sediment to a safe height, there seems to be no good reason for a wide leg except from the staybolt point of view. There is no question of a stronger circulation with the narrow leg, and if need be, some form of flexible staybolt could be considered for extreme cases of angular movement.

In the older designs of fireboxes it was often 80 inches from the mudring to the water level above the crown sheet, the water varying in temperature, while in circulation from 150 or 180 degrees at the bottom to the temperature due to the steam pressure at the top. The depth of this column of water in wide firebox designs is very materially decreased, and as the temperature limits are about the same, it is apparent that for an equal width of water space the rate of flow of the circulation as a whole would be decreased about proportionately to the travel. If in addition to this, the width of the water leg be increased, the rate of movement is further decreased.

If rapid circulation and a wiping effect will serve to carry off the steam bubbles, preventing steam film and overheating of fire sheets, this function has been absolutely sacrificed in many wide firebox designs and the short-lived side sheets seem to prove it. The highest duty boilers are those having the most rapid circulation. The water spaces in legs and between tubes of fire engine boilers are very small, but the probabilities are that the rate of steaming and efficiency would be decreased if these spaces were materially increased and the larger volume of water would lower the rate of circulation.

It is quite likely that the rate of movement in the locomotive water leg has much to do with this question. The water next to the fire sheet has an upward tendency. That next to the outside sheet can only rise when heated by conduction through a body of water equal to the entire width of the leg or by the mingling, mixing action set up when the sheets are not vertical. There seems to be a reasonable ground for the belief that there is a very sluggish circulation in a directly vertical water leg of considerable width, contributing to formation of a steam film and overheating of the sheets when fires are forced.

This discussion would not be complete without considering the other end of the temperature scale to which the fire sheets are subjected. As before stated, it is the amplitude of the vibrations or movement of the sheet which are most subject to control. All possible mileage should be made between knocking out of fires. Firing methods can often be improved so that an engine can be returned without knocking the fire. The usual ash pit methods use up much of the life of side sheets and cold water washing and filling, and rapid firing up takes a lot more. It is quite true that the old-time fireboxes had to stand all this, but while considering temperatures and their effects it would be just as well to help on the lower end of the scale if possible.

Improved methods of blowing down and filling up of the boiler at terminals, hot water changing and washout plants are now well demonstrated and these will all help to reduce the amplitude of the temperature scale traversed in locomotive operation as regards the firebox sheets and thus add to their life.

* * * * * * *

After considerable discussion the writer's closing remarks were as follows: "I think I have attained my object in getting a discussion on this rather interesting question. The idea that I had in mind was simply to find some reason why the modern wide fireboxes are lasting one-third of the life of the old-time boxes. In seeking for a theory it occurred to me to consider those elements which contribute to ultimate failure, viz: the vibrations or the expansions and contractions or movements of the sheet in the performance of its duty. I do not know that I am right yet, but at the same time, if there is successful performance of fireboxes about sixty inches wide, and boxes wider than that have not given as good performance, it would indicate that the slope of the sheet due to the narrower width had something to do with it. Now, just how that works out; whether I am correct in supposing that that upward circulation against an outwardly inclined sheet assists in wiping off the steam bubbles and combining them with the current, transmitting the heat, warming up the entire body of water in the water leg, instead of permitting a curtain or film of steam which will contribute to over-heating of the sheet,

it at least seems to be a reasonable theory or explanation with some foundation for it.

"Whether Mr. Fry's theory of downward circulation or mine of facilitating wiping action of the circulation are used, the result is the same as regards the desirability of outward instead of inward inclination of firebox side sheets.

"As regards Mr. Squire's inquiry about the solid water, it would seem to me that there is absolutely no possibility of a steam bubble combining with another and another and another until there is a film on any portion of the crown sheet which is considerably beyond the vertical. If the volume of the water leg is increased by greater width of water leg, I think it is reasonably sure that the rate of the circulation as a whole is decreased, due to that larger volume, and if the rate of circulation is a factor in keeping down the internal temperature of the sheet, the failures are in accord with my theory.

"What I am trying to find out is this,-you will probably all admit that a firebox sheet has a certain life, it will stand so many vibrations, so many expansions, so nany contractions, from the normal and then it will develop that crack that goes off like a pistol shot, or some other way, at any rate there is a failure of the sheet. Now, that being the case, if we can lengthen out the period of time over which that total movement will happen, we get the increased life in our sheet. It seems to me that if the box is designed in such a way that the internal temperature of the sheet is kept down by keeping solid water against it by any means whatsoever, then with all of the fireboxes, even with the despised ogee, we have made a distinct gain. I think this is a matter worth thinking about and possibly of going into our records of firebox failures. Classify the fireboxes of different widths and angles and forms on our roads and go back through our records for years and find out the number of fireboxes and side sheets that have been applied and see what results we obtain. I do not believe that it is due to the quality of firebox steel falling down necessarily, but probably a matter of design.

"As regards Mr. Wickhorst's belief that there is no downward circulation, or at least that there does not seem to be much to support that theory, I agree with that in a great measure. My idea of the circulation is that it is a very rapid, upward, against the inside sheet and less rapid at the outside, so that a number of inclined lines, each of a greater angle, would express the velocity as I understand it. But I can hardly understand why water up at two-thirds of the height of the firebox against the outside sheet should come down. I cannot see why it will not rise, although at a very less rate than that of water that is close to the firebox sheet.

INSPECTION PITS AT ENGINE House.—An adjunct to terminal facilities is now being advocated by those giving the matter close attention, and that is having what is known as an inspection pit placed where engines bound toward the roundhouse will pass over it. This pit should be shallow, simply deep enough to permit men to walk under the engine and enable them to examine all its parts. The object of the pit is that engines will be stopped over it on their arrival and will be thoroughly examined by competent inspectors, and in a busy time this is quite an advantage in helping the movement of engines. Many times an engine reaching this pit will be found on inspection to have but a few nuts loose here and there, or in need of some slight repairs that can be made right on the pit; the engine then passing along through its different operations, goes on the table to be turned and is ready for a return trip. This saves its going to the house at all and is an advantage at a busy terminal in busy times when power is scarce.-R. D. Smith before the New England Railroad

A CAR WAS BLOWN FROM THE TRACK of the Union Pacific Ry. near Lone Tree Creek, Wyo., 30 miles west of Cheyenne, on October 19. It was the caboose of a work train bound for Hermosa Junction and carried about 40 laborers. The wind threw the car from the rails, breaking its coupling, and it dropped 30 feet down the embankment. The car was entirely broken up and six men were killed.